



भारत सरकार
GOVERNMENT OF INDIA
खान मंत्रालय
MINISTRY OF MINES
भारतीय खान ब्यूरो
INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय
OFFICE OF REGIONAL CONTROLLER OF MINES



फैक्स: (080) 23371027 / 23373287
दूरभाष: 080-23371027 / 23375366/67
Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,
गोरगुंटापाल्या येशवंतपुर,
बेंगलुरु -560022

सं/No.: KNT/MYS/Mgst-13/BNG Mine-code: 39KAR14013

दिनांक/Dated: 10/02/2021

To,
Sri N. Rajashekar
No.38, 'Sri Nanjudeshwara Nilaya'
Udayaravi Road, KHB Colony
Kuvempunagar
District-Mysuru
Karnataka-570023

विषय/Subject: **Violation of provisions of MCDR 2017 in respect of your Talooru Magnesite Mine, ML 2484 of Shri. N Rajashekar over an extent of 11.88 ha, in Talooru Village, Mysuru Taluk and District of Karnataka State.**

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during inspection on 27.01.2021 & 28.01.2021 by undersigned and Shri. H.M Shivakumar, AME in presence of Dr. C.P. Prasanna Kumar, QP, Shri Y.Narayan Rao, Agent and other mining officials:

Rules	Nature of Violations observed
11 (1)	<p>Scheme of Mining was approved by IBM vide letter no. 279/770/2003/BNG dated 1/10/2015, for five years period (2015-16 to 2019-20). The deviations observed in mining operation vis-à-vis approved document are given below.</p> <p>i) The total ROM (Magnesite ore) production proposed for the year 2019-20 is 8187 tonnes against which only 5,000 tonnes of ROM (Magnesite ore) production has been done. The deviation in the overall Magnesite ore production is 39 % less than the approved proposal.</p> <p>ii) The total Mineral Reject quantity proposed for the year 2019-20 is 2325 Cum against which only 833 Cum of Mineral Reject is generated.</p> <p>iii) The construction of 485 m retaining wall and 1175 m garland drain has been proposed for the year 2015-16 and 380 m safety bund all along the Lease area in 2019-20. It is observed during inspection that the retaining wall, garland drain and safety bund construction have not been completed as per the proposal.</p>

	iv) Two Silt Settling tank has been proposed in the year 2015-16 & 2016-17. It was observed during inspection that no silt settling tank construction has been carried out as per the proposal.
26(2)	Yearly report on PMCP setting forth the extent of protective and rehabilitative works carried out as per the approved Progressive mine closure plan, has not been submitted for the year 2019-20 as per the provision of this rule.
55	A whole time Mining Engineer has not been appointed as per the provision of this rule.
45(7)	<p>The online Annual return for the year 2019-20 has been submitted by the Lessee; Following discrepancies are noted in the submitted copy as observed during site inspection.</p> <p><u>Part-I:</u>The land use (area in ha) as given in Part-I(12) under 12(v) &(vi)are not reported correctly as per the latest approved document for the period 2020-21 to 2024-25.</p> <p><u>Part-III:</u> i) The Royalty figures have not been reported correctly in Sec 2(a). ii) The DMF and NMET amount has not been reported correctly in Sec (5) (c).</p> <p><u>Part-V:</u> i) The details of Mineral Reserve & Resources as given in Sec 3 are not correct as per the latest approved document for the period 2020-21 to 2024-25. The production quantity for the year 2019-20 to be depleted from the reserves and figures to be reported accordingly. The Resource figures will remain same. ii) The total quantity of ROM ore production & overburden/waste removed during the year 2019-20 has not been reported correctly in Sec 4.2(b) & 4.2(c) respectively. Also, the Quantity disposed of in external dumps 4.2(c) (ii) has also been not reported correctly. iii)The Grade of the mineral reject generated has not been reported correctly in Sec 4.2(B)</p> <p><u>Part-VI:</u> i) The ROM ore production and Closing stock have not been reported correctly in Part-VI (1). ii) The Ex-mine price not reported correctly in Part-VI (2).</p>

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR, 2017.
03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
04. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (Forty Five) days** from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-

(Sandeep Kumar Singh)

Assistant Controller of Mines
Indian Bureau of Mines

Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

Sd/-

(Sandeep Kumar Singh)

Assistant Controller of Mines
Indian Bureau of Mines