



भारत सरकार/ Government of India
खान मंत्रालय / Ministry of Mines
भारतीय खान ब्यूरो / Indian Bureau of Mines
क्षेत्रीय खान नियंत्रक का कार्यालय / Office of the Regional Controller of Mines



रजिस्टर्ड ए0डी0/ उल्लंघनपत्र

File No.: MP/Katni/Lst-07 448-451

Jabalpur, dated: 13/02/2020

सेवा में,

M/s. S.N. Sunderson & Co. Pvt Ltd
Opp.S-1/56, Sector-1, Daddadham,
Post Box-39, Dist-Katni (M.P.)-483501

विषय - म0प्र0 राज्य के Katni जिले में स्थित आपकी Badari Limestone Mine, (क्षेत्रफल- 5.04 हे0) में खनिज संरक्षण एवं विकास नियमावली, 2017 के नियमों का उल्लंघन। (Mine Code-38MPR18013)

महोदय,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mentioned mine during the inspection by Shri Sanjay M. Girhe, Regional Mining Geologist on 16.01.2020 in presence of Shri Ajay Pandey, Geologist as under:-

नियम स.	पाए गए उल्लंघन की विस्तृत प्रकृति
Rule 11 (1)	<p>According to this rule-No holder of a mining lease shall commence or carry out mining operation in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Govt. pursuant to the provisions to clause (b) of Sub Section (2) of Section 5 or approved by the competent authority of the Atomic Minerals Directorate for exploration and Researching respect of minerals specified in Part B of the First Schedule of the Act where the grade of such atomic minerals is equal to or above the threshold value limit declared under schedule-A of the Atomic Mineral Concession Rules 2016</p> <p>The Modified Mining Plan of above mentioned mine was approved vide this office letter No-MP/Katni/Limestone/MPLN-45/2016-17 dated 21/04/2017 incorporating the proposals of working from 2017-18 to 2021-22. During the inspection it was found that following provisions of rule have been violated</p> <p>In chapter-4, Para-b, Overburden/waste of 47958CuM was proposed to be generated during the year and it was proposed to backfill in barrier & east of quarry. But, no such backfilling is carried out as per the proposals & thus there is violation of above mentioned rule.</p>
Rule 26(2)	<p>The holder of mining lease shall submit a yearly report as per the format specified before 1st July of every year setting forth the extent of protective and rehabilitative work carried out as envisaged in the approved mine closure plan, and if there is any deviation, reason thereof</p> <p>But, in your case the aforesaid Report in prescribe Form for the year 2018-19 not submitted to the Regional Controller of Mine, Jabalpur till the date of inspection.</p>
Rule 31(4)	<p>The plans and sections required under these rules shall be maintained up to date within three months in case of category 'A' mines as referred to in clause (a) of sub-rule (2) of rule 55, and within twelve months in case of any other mine</p> <p>As this is "A" category mine and required plans & sections are need to be updated on quarterly basis as required under this rule but the same were are not updated in stipulated time and not maintained at mines site office.</p>
Rule 45(1)	<p>The holder of the mining lease, or any person or company engaged in trading or storage or end use or export of minerals mined in the country, shall cause himself to be registered online with the Indian Bureau of Mines as per application specified in Form-K of the Schedule and the registration number so allotted by the Indian Bureau of Mines shall be used for all purpose of online reporting and correspondence connected therewith</p> <p>But, it is observed that you have not done online MTS registration in prescribed Form so for till the date of inspection & thus violating above provision of this rule.</p>
Rule 45(5) (c)	<p>The holder of a mining lease shall submit online returns in respect of each mine to the Regional Controller of Mine or any other authorized officer of the Indian Bureau of Mines in the following manner-</p> <p>In annual Return for the year 2018-19 in form H-8 submitted to the Regional Controller of Mines found following discrepancies -</p> <p>Part-I under item-12, Under the lease area utilization, area marked under current working as 1.94Ha is not matching with the area furnished in modified mining plan approved on dtd 21.04.2017.</p> <p>Part-V, under item-3, Reserves under category (111) is furnished as 10 Million Tonnes mismatching with details furnished in modified mining plan approved on dtd 21.04.2017.</p>

Part-VI(2)- Ex-mine price for BF grade limestone is furnished as Rs 266/Tonne which is to be incorrect & on lower side compare to the ASP published by IBM for month of Aug. 2019.
Part-VI(5)- During the year total 274945.959MT limestone dispatched to the different buyers but in most of the cases their registration numbers allotted by the IBM are not mentioned which is mandatory and no dispatched is allowed to such unregistered buyers as per the statutory provisions.

- 02 In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR-2017.
03. Non compliance of the rule 11(1) & of MCDR-2017 may lead to suspension of Mining operations under the provisions of rule 11(2) of MCDR-2017. Further, for the non-compliance of Rule 45(5)(c) of MCDR-2017, necessary action shall be initiated as deemed fit under the provision of rule 45(7) of MCDR,2017.
- 04 You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय,

(संदीप सिंह)

उप.खान नियंत्रक
भारतीय खान ब्यूरो,

प्रतिलिपि सूचनार्थ हेतु प्रेषित :

01. The Director of Geology & Mining, Govt .of Madhya Pradesh, Khanij Bhavan, 29-A, Arera Hills, Bhopal (M.P.).
02. The District Collector, Katni (M.P.).

प्रतिलिपि प्रेषित :

The Controller of Mines (CZ), IBM, Nagpur for information.

उप.खान नियंत्रक
भारतीय खान ब्यूरो,