


भारत सरकार/ Government of India खान मंत्रालय / Ministry of Mines

भारतीय खान ब्यूरो / Indian Bureau of Mines





रजिस्टर्ड ए०डी०/ उल्लंघनपत्र

Jabalpur, dated: 04/02/2020

File No.: MP/Satna/Bauxite-01

सेवा मे,

Shri Harilall Rameshwar Prasad Post- Jaitwara, Dist-Satna (M.P.)-485221 Email- rrbansal@bsnl.in

विषय – म०प्र0 राज्य के Satna जिले में स्थित आपकी Naugawan Bauxite Mine, (क्षेत्रफल- 13.44 है0) में खनिज संरक्षण एव विकास नियमावली, 2017 के नियमों का उल्लंघन। (Mine Code-32MPR35037)

महोदय.

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mentioned mine during the inspection by Shri Sanjay M. Girhe, Regional Mining Geologist on 15.01.2020 in presence of Shri Ashish Bansal, Partner of Firm, Kesh Bansal, Partner as under-:

inder-:	
नियम स.	पाए गए उल्लंघन की विस्तृत प्रकृति
Rule 13(1)	In opencast working, the benches formed shall be so arranged that the benches in ore or mineral and overburden are separate so as to avoid mixing of waste with the ore or mineral But, it observed that in new pit opened near to mine site office towards eastern side of lease area the overburden benches not form separately and mixing of overburden with ore is
	occurred.
Rule 26(2)	The holder of mining lease shall submit a yearly report as per the format specified before 1st July of every year setting forth the extent of protective and rehabilitative work carried out as envisaged in the approved mine closure plan, and if there is any deviation, reason thereof But, in your case the aforesaid Report in prescribe Form not submitted to the Regional Controller of Mine, Jabalpur till the date of inspection. The plans and sections required under these rules shall be maintained up to date within the plans and sections required under these rules shall be maintained up to date within
Rule 31(4)	The plans and sections required under these rules state to inclause (a) of sub-rule (2) of rule three months in case of category 'A' mines as referred to in clause (a) of sub-rule (2) of rule 55, and within twelve months in case of any other mine As this is "A" category mine and required plans & sections are need to be updated on quarterly basis as required under this rule but the same were are not updated in stipulated time and not maintained at mines site office.

- In this connection it is brought to your notice that the above violations constitute an offence 02 punishable under Rule 62 of MCDR-2017.
- You are advised to rectify the above violations immediately and intimate the position to this 04 office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय

उप.खान नियंत्रक भारतीय खान ब्यूरो,

प्रतिलिपि सूचनार्थ हेतु प्रेषित :

The Director of Geology & Mining, Govt .of Madhya Pradesh, Khanij Bhavan, 29-A, Arera 01. Hills, Bhopal (M.P.).

The District Collector, Katni (M.P.). 02.

प्रतिलिपि प्रेषित:

The Controller of Mines (CZ), IBM, Nagpur for information.