



भारत सरकार

खान मंत्रालय

भारतीय खान ब्यूरो, क्षेत्रीय खान नियंत्रक कार्यालय, रायपुर
दुसरी मंजील, जीएसआई फील्ड प्रशिक्षण केन्द्र, महालेखाकार आफिस कोम्प्लेक्स,
पोस्ट - विधान सभा, रायपुर (छ.ग)-492005, फोन- 0771—2282530 /2285590 /95
ईमेल- ro.raipur@ibm.gov.in / ro.raipur.ibm@gmail.com



संख्या: नारायनपुर / लौह / खयो-1194 / 2018-रायपुर

दिनांक - 27.02.2019

प्रेषित : सर्वश्री जायसवाल नीको इंडस्ट्रीज लिमिटेड,
माइन्स डिवीजन, इंडस्ट्रीयल ग्रोथ सेंटर,
सिलतारा, रायपुर,
छत्तीसगढ़ - 493111

विषय: खनिज (परमाणु और हाइड्रोकार्बन ऊर्जा खनिजों से भिन्न) रियायत नियम 2016 के नियम 17(2) एवं खनिज संरक्षण एवं विकास नियमावली, 2017 के नियम 23 के अंतर्गत प्रस्तुत निकट ग्राम - छोटेडोंगर, तहसील - नारायनपुर, जिला - नारायनपुर (छग) में स्थित छोटेडोंगर लौह अयस्क खान, क्षेत्रफल - 192.25 है की खनन योजना का पुनर्विलोकन सह उत्तरोत्तर खान बंद करने की योजना की प्रस्तुति।

महोदय,

आप द्वारा प्रस्तुत उपरोक्त क्षेत्र की खनन योजना का पुनर्विलोकन सह उत्तरोत्तर खान बंद करने की योजना की जांच व खान निरीक्षण के उपरांत इसमें कमियां/त्रुटियों पाई गई हैं। संलग्नक में दर्शाई गयी कमियों/त्रुटियों को सुधारते हुए खनन योजना का पुनर्विलोकन सह उत्तरोत्तर खान बंद करने की योजना की (3) तीन स्वच्छ बाउण्ड प्रतियां एवं 2 सॉफ्ट कॉपी (CD) इस पत्र के जारी होने की तिथि से पंद्रह (15) दिनों की अवधि में इस कार्यालय में प्रस्तुत करें तथा यह भी सुनिश्चित करें कि तीन स्वच्छ प्रतियों के प्रत्येक पृष्ठ पर अर्हित व्यक्ति द्वारा हस्ताक्षर कर दिये गये हैं। तथा बिन्दुवार कमियां सुधार का विवरण भी प्रस्तुत करें।

आपको यह भी सलाह दी जाती है कि आप खनन योजना का पुनर्विलोकन सह उत्तरोत्तर खान बंद करने की योजना की तीन स्वच्छ बाउण्ड प्रतियां पूर्ण सावधानी से तैयार करें अन्यथा पुनः कमियां/त्रुटियां पाए जाने की स्थिति में यह आपको संशोधनार्थ न लौटाते हुए इस पर अंतिम कार्रवाई कर दी जायेगी।

आप कृपया खनन योजना का पुनर्विलोकन सह उत्तरोत्तर खान बंद करने की योजना के साथ प्रस्तुत की जाने वाली वित्तीय आश्वासन एम सी डी आर 2017 के अनुसार पाँच वर्ष की अवधि का (Financial Assurance) क्षेत्रीय खान नियंत्रक, भारतीय खान ब्यूरो, रायपुर के पक्ष में प्रस्तुत करें। वित्तीय आश्वासन के अभाव में खनन योजना का पुनर्विलोकन सह उत्तरोत्तर खान बंद करने की योजना अपूर्ण मानते हुए अंतिम कार्रवाई कर दी जाएगी।

भवदीय,

संलग्न: यथोपरि

(बी एल. गुर्जर)
क्षेत्रीय खान नियंत्रक
भारतीय खान ब्यूरो

प्रतिलिपि:

1. खान नियंत्रक (मध्य), भारतीय खान ब्यूरो, नागपुर। (ई मेल द्वारा)
2. श्री एस के पॉल, सर्वश्री जायसवाल नीको इंडस्ट्रीज लिमिटेड, माइन्स डिवीजन, इंडस्ट्रीयल ग्रोथ सेंटर, सिलतारा, रायपुर, छत्तीसगढ़ - 493111

क्षेत्रीय खान नियंत्रक
भारतीय खान ब्यूरो

Annexure

Scrutiny comments on Modified Mining plan & with Progressive Mine closure plan of Chotedongar Iron ore Mine, Lease over an extent of 192.25 hector in Village: Chotedongar, Tehsil:Narayanpur, District: Narayanpur, Chhattisgarh of M/S Jayaswal Neco Industries Limited.

1. In the cover page of the document the proposal period is mentioned from 2017-18 to 2019-20 but the period 2017-18 is already lapsed therefore proposal period may be corrected and accordingly correction to be done in all relative places.
2. **Reason for modification in approved document:** In the given Para it should be clearly mentioned that modification is done due to change is area of approach road and area of infrastructure which was not mentioned in earlier lease deed. Earlier as per lease deed only one approach road is exist and now as per new proposal two approach roads and also place for infrastructure incorporated.
3. The information furnished at a glance should not contain the information regarding conceptual stage of mining proposal therefore it should be deleted.
4. Review of Mining Plan: In the given Para the last approved document review also to be incorporated. The correction to be done.
5. **Mining:** In the given chapter proposal is given for 2017-18 but the period is already lapsed therefore the same should be reflect in review Para. The production and development plate of 2017-18 also not required to enclose and plate should be furnished financial yearwise and not third year, fourth year ,etc.. The correction to be done accordingly.
6. Mining: since it is modification of already approved mining plan, therefore earlier production planning along with proposed changes needs to be furnished as per table given

Year	Proposal of mineral production As per earlier approved mining plan dated 18/1/2018.	Modified production proposal as proposed in submitted modification in tonnes	Reasons of same
2015-16	None	Period already passed	
2016-17	None	Period already passed	
2017-18	0.050 million tones	Period already passed	
2018-19	0.7 million tones	Period already passed	
2019-20	1.4 Million tones	1.4 million tones	

Changes in text and plates of document accordingly needs to be made.

7. **Conceptual Mining Plan:** A proper conceptual plan based on the long term design parameters of the mine covering all the mining and allied activities has not been furnished. All the activities should be furnished with extent of area and quantity involved in the form of 5 yearly blocks up to the lease period. In the submitted document it is mentioned that 2.5 million tons of Iron ore will be produce from 2020-21 which is practically not possible, till date single ton of iron ore is not dispatched from mine therefore till date there is no infrastructure to crater such a huge quantity nor road connectivity. Only for sake of getting EC for large capacity in one go is not justify for given such ambitious proposal and it is not acceptable. The lease was executed almost 14 years back and production till date is zero and it

- proposed that from next year production will be 2.5 million tons. The same should be justify with the view of scientific and systematic mining. The plate to be revised accordingly.
8. The modification is submitted due to change in lease area and approach road and incorporation of infrastructure area but in lease attached the area for approach road and infrastructure area is not as mining lease area. If the area given for approach road and infrastructure is in ML area than the area has to explored first than only it can be decided that can be used for infrastructure or not and if exploration already done than the exploration detail should be enclosed.
 9. In lease deed ML area is granted in granted bearing Topo-sheet No./Cadastral survey No.-65-E/7,Compartment No.R.F. 255 to 265 but as per new area it is not mentioned that Compartment No. changed or not.
 10. During development of approach road the quantity of excavation should be furnished and if mineral produce that also should be mentioned.
 11. The information on protective measures for reclamation and rehabilitation work yearwise may be provided incorporating proposal for check dam, retaining wall, drainage, etc. and same should be incorporated in respective plates.
 12. **Use of Minerals:** In the given Para it is mentioned that 6 million tons of Iron ore is required lessee's steel plant. The same should be review and accordingly correction to be done.
 13. **Disaster Management plan:** A proper Disaster Management Plan based on the risk assessment and clearly indicating the chain of activities along with the name and designation of key persons with infrastructure (**hospital**, fire station, police station, etc.) should be furnished. The contact no. of the responsible person to be given.
 14. **Development plan: Development Plan & Section:** The working plan should be proposed with proper advancement and top and bottom RL. The section also to be corrected accordingly. The benches should be proposed with bench RL and regular in manner. The topsoil, OB, mineral benches should be marked with different colour code to identify. The haul road not shown from working face to top soil, waste dump, screen reject and mineral stack. The top soil dump, waste dump and mineral stack should be shown in the plate and should be proposed yearwise with RL. The production proposal is given in last approved document 0.05 million ton in 2017-18, 0.7 million tons in 2018-19 and 1.4 million in 2019-20 but the period 2017-18 already lapse and 2018-19 is almost end and production yet to be started therefore production proposal should be reviewed and accordingly proposal should be given as EC is only having for 5000 tons. The plate should be revised accordingly.
 15. All the plates should be index properly as the features shown in the plan with the same colour code for clarity and signed with date.