



भारत सरकार
GOVERNMENT OF INDIA
खान मंत्रालय
MINISTRY OF MINES
भारतीय खान ब्यूरो
INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय



OFFICE OF REGIONAL CONTROLLER OF MINES

दूरभाष: (080) 39505368 / 29720499
Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,
गोरगुंटापाल्या येशवंतपुर
बेंगलुरु -56002

सं/No.: **KNT/GLB/LST/50/BNG-Vol-II**

Mine-code: 38KAR10016

दिनांक/Dated: 10/03/2022

To,
Shri Devesh Kumar Mishra,
Agent Mines & Joint President (Works),
Kallur Limestone Mine
M/s. Chettinad Cement Corporation Private Limited
Kallur (Village), Garagapalli (Post)
Chincholi Taluk,
Kalaburagi-585 305, Karnataka

विषय/Subject: **Violation of provisions of MCDR 2017 read with MCDR(Amendment),2021 in respect of your Kallur Limestone Mine, ML 2648 over an extent of 422.94 ha, in Kallur Village, Chincholi Taluk, Kalaburagi District of Karnataka State.**

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 read with Mineral Conservation and Development (Amendment) Rules, 2021 were found violated in your above mine during inspection on 25.02.2022 by the undersigned in presence of Sri V. Balasubramani, Mine Manager, Sri V. Rami Reddy, Mining Engineer and other mine officials:

Rules	Nature of Violations observed
11 (1)	<p>Review and updation of Mining Plan was approved by IBM vide letter no. 279/1044/2009/BNG dated 20/11/2018, for five years period (2019-20 to 2023-24) and Modification to the approved Review and updation of Mining Plan was approved by IBM vide letter no. 279/1004/2009/BNG dated 04/02/2021, for the period 2021-22 to 2023-24. The deviations observed in mining operation vis-à-vis approved document are given below.</p> <p>i)The total ROM production proposed for the year 2020-21 is 3,999,750 tonnes against which 2,398,243 tonnes of ROM production has been done. The deviation in the overall ROM production is 40 % less than the approved proposal.</p> <p>ii)It was observed during inspection that the Retaining Wall and Garland drain along toe of the waste Dump-2 at co-ordinates N-1923290, E- 780400 to N-1923400 E- 760200 are not maintained.</p>

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR (Amendment), 2021.
03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
04. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (Forty-Five) days** from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-
(Sandeep Kumar Singh)
Assistant Controller of Mines
Indian Bureau of Mines

Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

Sd/-
(Sandeep Kumar Singh)
Assistant Controller of Mines
Indian Bureau of Mines