



भारत सरकार
Government of India
खान मंत्रालय
Ministry of Mines
भारतीय खान ब्यूरो
Indian Bureau of Mines

पंजीकृत पावती
उल्लंघन पत्र
माखुपूरा औद्योगिक क्षेत्र,
Makhupura Industrial Area
अजमेर.-305 002 (राजस्थान)
Ajmer- 305 002 (Rajasthan)
फैक्स नं 0145.2695202 फोन नं 2695165
Email-ro.ajmer@ibm.gov.in

Mine Code: 34RAJ27002

संख्या : RAJ/UDP/LEAD ZINC-02/Vol-II

दिनांक : 03.08.2021

प्रेषित : एजेंट,

सिन्देसर खुर्द लेड जिंक माइन,
मैसर्स हिंदुस्तान जिंक लिमिटेड,
पोस्ट-दरीबा, तहसील-रेलमगरा,
जिला-राजसमन्द (राजस्थान)

Email- Vinod.Jangir@vedanta.co.in

विषय : Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your **Sindesar Khurd Lead Zinc Mine** (Lease area 199.8425Hect.) in Rajsamand District of Rajasthan State.

महोदय,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during the inspection made on 08.07.2021 & 09.07.2021 by the undersigned in presence of Sh. Vinod Jangir, Unit Head & Mines Agent:

Rule No.	Nature of violation observed in detail																			
11(1)	<p>The mining operations are carried out in violation of following provisions of approved Modified Mining Plan (Approved on 09.07.2020) for the year 2020-21: -</p> <p>(i)</p> <table border="1"><thead><tr><th>Year</th><th>Proposed Exploration Drilling(U/G)</th><th>Actual Drilling (U/G)</th></tr><tr><td></td><td>No. of Bore Holes</td><td>Meterage</td><td>No. of Bore Holes</td><td>Meterage</td></tr></thead><tbody><tr><td>2020-21</td><td>800</td><td>85000</td><td>414</td><td>58048</td></tr></tbody></table> <p>It shows that shortfall in underground exploration drilling.</p> <p>(ii)</p> <table border="1"><thead><tr><th>Year</th><th>Proposed UG Development(m)</th><th>Actual UG Development(m)</th></tr></thead><tbody><tr><td>2020-21</td><td>31889</td><td>22012</td></tr></tbody></table> <p>It shows that shortfall in UG development.</p> <p>(iii) During the year 2020-21, total 200m parapet wall & 200m garland drain proposed around the dump periphery but no such parapet wall as well as garland drain made.</p> <p>(iv) During the Stopping inspection ventilation at -90mRL level & -210mRL level was poor.</p>	Year	Proposed Exploration Drilling(U/G)	Actual Drilling (U/G)		No. of Bore Holes	Meterage	No. of Bore Holes	Meterage	2020-21	800	85000	414	58048	Year	Proposed UG Development(m)	Actual UG Development(m)	2020-21	31889	22012
Year	Proposed Exploration Drilling(U/G)	Actual Drilling (U/G)																		
	No. of Bore Holes	Meterage	No. of Bore Holes	Meterage																
2020-21	800	85000	414	58048																
Year	Proposed UG Development(m)	Actual UG Development(m)																		
2020-21	31889	22012																		
Rule 26 (2)	<p>A yearly PMCP report for the year 2020-21 submitted vide your lettered 11.06.2021. The proposals as well as actual backfilling area shown in the PMCP report are not matching with approved modified mining plan with PMCP (Approved on 09.07.2020).</p>																			
Rule 45(7)	<p>In annual return 2020-21 following discrepancies were observed:</p> <ol style="list-style-type: none">1) In part II & III overhead expenditures shown Rs. 11858453056 so per ton cost should be Rs 2448.95 under head overhead, whereas in Part VII you have reported Rs. 943 per ton under head overhead.2) In Part VII Cost of production, Royalty amount has been shown as '0'. The details of DMF & NMET not furnished.3) In part VII Cost of production, direct cost per tonne of ore is not matching with expenditure detail furnished in Part II & Part III.4) Content of Silver, cadmium and other associates mineral in the ore & concentrate have not been furnished.																			

02. इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली, 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है एवं उपरोक्त नियमों का उल्लंघन की अनुपालना नहीं होने पर खनिज संरक्षण एवं विकास नियमावली, 2017 के अंतर्गत :


(क) आपकी खदान की सारी संकियाएं बंद की जा सकती है।

(ख) आपके विरुद्ध अभियोग दायर किया जा सकता है।

(ग) खनन पट्टे को निरस्त करने की सिफारिश राज्य सरकार से की जा सकती है।

03. अतः आपको यह निर्देशित किया जाता है कि आप आप उपरोक्त उल्लंघनों का अतिशीघ्र सुधार करें एवं इसके सुधार की स्थिति की सूचना इस पत्र के जारी होने की दिनांक से 45 (पैंतालीस) दिनों के भीतर इस कार्यालय को प्रेषित करें।

भवदीय




(डी. आर. गुर्जर)

वरिष्ठ सहायक खान नियंत्रक
भारतीय खान ब्यूरो

प्रतिलिपि सूचनार्थ प्रेषित :-

- 1 खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर (ई मेल द्वारा)।
- 2 निदेशक, खान एवं भूविज्ञान विभाग, राजस्थान सरकार, उदयपुर।
- 3 खनि अभियंता, खान एवं भूविज्ञान विभाग, राजस्थान सरकार, राजसमन्द।
- 4 रक्षित पत्रावली।


वरिष्ठ सहायक खान नियंत्रक
भारतीय खान ब्यूरो