



भारत सरकार Government of India

खान मंत्रालय Ministry of Mines

भारतीय खान ब्यूरो Indian Bureau of Mines

क्षेत्रीय खान नियंत्रक का कार्यालय Office of the Regional Controller of Mines

100, ओल्डनेहरू कालोनी, देहरादून (उत्तराखंड) 248001 /100 Old Nehru Colony, Dehradun (U.K.)248001

TEL- 0135-2676350 / 2671896, E-mail – ro.dehradun@ibm.gov.in



फाईल संख्या File No: HP/SRM/LST-07

Mine Code: 38HP10018

दिनांक, 19, March 2021

सेवा में To : Nominated Owner,
M/s Cement Coprporation of Inida
Rajban Cement Factory,
Po-Rajban, Tehsil- Paonta Sahib,
District- Sirmour, Himachal Pradesh - 173028

Email: minemanagercci@gmail.com

विषय Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Manal Limestone Mine, Mining Lease over an area of 172.30 ha located near Village-Manal, Tehsil- Paonta Sahib, District-Sirmour in Himachal Pradesh-Reg

महोदय Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 activities during 2019-20 up to 31.03.2020 were found violated in your above mine during the inspection made by the undersigned on 13.03.2021 in the presence of Shri P.K Sinha, Mine manager and Shri Kumbha Ram, Mining Engineer.

RULE NO.	NATURE OF VIOLATION OBSERVED
11(1)	Mining Operation were not carried out in accordance with the approved Review and Updation of Mining Plan vide letter no. 614(2)/MS-A-182/09-DDN dated 11-07-2018 to the following extent: 1. As per proposal on page -29 during the year 2019-20, it was proposed to carry out 06 bore holes with total 431.02 meterage but during the inspection it was observed no exploration was carried out during the year 2019-20. 2. As per PMCP proposal on page -65 during the year 2019-20, it was proposed to construct garland drain along top periphery of the existing pits of 240m and catch drains along both sides of haul roads of 200m but during the inspection it was observed no such construction was carried out during the year 2019-20.
33	The holder of a mining lease shall, on or before the 30 th day of June every year submit to the authorized officer a digital copy along with a print copy of the surface geological plans and sections maintained under Rule 32. However, the lessee has not submitted the copies of the plans and sections as per Rule 32 for the year 2019-20
45(7)	The holder of mining lease has submitted incomplete and/or inconsistent or false information in annual return: 1. Reported cost of production is given Rs. 284 per Tonnes which appears to be very high.

2. In this connection, it is brought to your kind notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.
3. Mining operations can be suspended as per rule 11(2) in case of non compliance of rules 11(1) and any other relevant rules of MCDR 2017 as these rules ensures systematic scientific and responsible mining.
4. Advise the State Government to order suspension of all mining operations in the mines as per provision of Rule 45(7), in case if it is found that the holder of a mining lease has submitted incomplete or wrong or false information in statutory returns or fails to submit such return within the date specified under Rule 45.
5. You are advised to rectify the above violations immediately and intimate the compliance position to this office within 45 days from date of issue of this letter.

भवदीय Yours faithfully,

(दामोदर प्रसाद शर्मा / D P Sharma)

सहायक खान नियंत्रक / Assistant Controller of Mines

प्रतिलिपि सूचनार्थ प्रेषित :-

- 1- खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर। (zo.udaipur@ibm.gov.in)
- 2- निदेशक उद्योग निदेशालय, हि0 प्र0 सरकार, उद्योग भवन, शिमला (हि0 प्र0). (geologicalwing@gmail.com)
- 3- गार्ड फाइल

सहायक खान नियंत्रक / Assistant Controller of Mines