



भारत सरकार Government of India

खान मंत्रालय Ministry of Mines

भारतीय खान ब्यूरो Indian Bureau of Mines

क्षेत्रीय खान नियंत्रक का कार्यालय Office of the Regional Controller of Mines

100, ओल्डनेहरू कालोनी, देहरादून (उत्तराखण्ड) 248001 / 100 Old Nehru Colony, Dehradun (U.K.) 248001

TEL- 0135-2676350 / 2671896, E-mail – ro.dehradun@ibm.gov.in



फाईल संख्या File No: HP/SRM/LST-35 Mine Code: 38HP10030

दिनांक 20 March 2021

सेवा में To : Mr. Vinender Kumar Walia,  
Village and Post-Dadahu,  
Tehsil- Renukaji,  
District- Sirmour, Himachal Pradesh -  
173025

Email: waliaheadoffice.nahan@yahoo.com,  
supriyank11@gmail.com

विषय Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Bhootmari Limestone Mine, Mining lease over an area of 32.57 ha located near Village-Bhootmari, Tehsil-Renukaji, District-Sirmour in Himachal Pradesh-Reg

महोदय Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection made by the undersigned on 14.03.2021 in the presence of Shri D.K Sinha, Mine Manager.

| <u>RULE NO.</u> | <u>NATURE OF VIOLATION OBSERVED</u>  |
|-----------------|--|
| 11(1)           | Mining Operation were not carried out in accordance with the modified mining plan approved vide letter No. 614(2)/MP-B-283/08-DDN, dated 15-11-2019 to the following extent:<br>1. As per proposal during the year 2019-20, it was proposed to carry out mining operation from 1445 to 1420 mRL by formation of benches 10 mtr height. During the inspection it was observed that benches have not been developed from 1445 mRL downward so far and height of existing benches also observed more than proposal.<br>2. As per proposal on page -22, during the year 2020-21, it was found that proposed to carry out 08 bore holes with total 417 metrage but during the inspection it was no such boreholes were carried out during year 2020-21.<br>3. As per PMCP proposals on page-60, during 2019-20 290 mtr fencing was proposed around plantation but during inspection it was no such fencing was carried out during year 2019-20. |
| 45(7)           | The holder of a mining lease has submitted incomplete or wrong information as follows:<br>Annual Return year 2019-20.<br>Part- III Consumption of Materials -Quantity of diesel consumption is very high which is not correct in r/o of production quantity.<br>Part-VII Cost of Production-Reported production cost of Limestone is Rs.340/Tonnes which is very high.<br>Monthly Return:<br>Part-II, details of consignee including registration no. shall be furnished in the returns.   |

2. In this connection, it is brought to your kind notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.
3. Mining operations can be suspended as per rule 11(2) in case of non compliance of rules 11(1) and any other relevant rules of MCDR 2017 as these rules ensures systematic scientific and responsible mining.
4. Advise the State Government to order suspension of all mining operations in the mines as per provision of Rule 45(7), in case if it is found that the holder of a mining lease has submitted incomplete or wrong or false information in statutory returns or fails to submit such return within the date specified under Rule 45.

5. You are advised to rectify the above violations immediately and intimate the compliance position to this office within 45 days from date of issue of this letter.

भवदीय Yours faithfully,

OIC

*[Signature]*  
20.03.2021

(दामोदर प्रसाद शर्मा / D P Sharma)

सहायक खान नियंत्रक / Assistant Controller of Mines

प्रतिलिपि सूचनार्थ प्रेषित :-

- 1- खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर। (zo.udaipur@ibm.gov.in)
- 2- निदेशक उद्योग निदेशालय, हि0 प्र0 सरकार, उद्योग भवन, शिमला (हि0 प्र0). (geologicalwing@gmail.com)
- 3- गार्ड फाइल

OIC

*[Signature]*  
20.03.2021

सहायक खान नियंत्रक / Assistant Controller of Mines

पत्र प्राप्त किया  
दि. 24/3/21 *[Signature]*