



भारत सरकार Government of India  
खान मंत्रालय Ministry of Mines  
भारतीय खान ब्यूरो Indian Bureau of Mines



क्षेत्रीय खान नियंत्रक का कार्यालय Office of the Regional Controller of Mines  
100, ओल्डनेहरू कालोनी, देहरादून (उत्तराखण्ड) 248001 /100 Old Nehru Colony, Dehradun (U.K.)248001  
TEL- 0135-2676350 / 2671896, E-mail – [ro.dehradun@ibm.gov.in](mailto:ro.dehradun@ibm.gov.in)

फाईल संख्या File No: HP/SRM/LST-18

Mine Code: 38HPR10011

दिनांक 20-03-2021

सेवा में To : M/s Mam Chand Goyal & Sons  
99/3-3 , Ganga Vihar,  
Haridwar Road, Dehradun

E-mail: [goyalsunil63@gmail.com](mailto:goyalsunil63@gmail.com)

विषय Sub: Show Cause Notice in respect of violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Banour Limestone Mine, Mining Lease over an area of 4.958 ha located near Village: Banour Tehsil: Paonta Sahib, District-Sirmour, H.P State.

महोदय Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 (MCDR, 2017) were found violated in your above mine during the MCDR inspection made by the undersigned on 02.11.2020 in the presence of Shri R.C Malik, Mine Manger which was communicated on 01-02-2021.


| RULE NO. | NATURE OF VIOLATION OBSERVED   |
|----------|--|
| 11(1)    | Mining operation were not carried out in accordance with the approved Review & Updation of mining plan with PMCP vide letter no 614(2)/MPB-285/08- DDN dated 25.01.2019 to the following extent:<br>(i) Chapter -2 page no 20 the height of benches in limestone was proposed 6 meter but during the inspection benches height was found more than 6 meter which is not maintained as per proposals.<br>(ii) Chapter-8 page no-46 as per proposals during year 2019-20, it was proposed to erect wire fencing 40 mtr but erection of wire fencing was not carried out as per proposal. |
| 45(7)    | The holder of a mining lease has submitted incomplete or wrong information as follows:<br>Annual Return for the Year 2019-20:<br>1. Part-VII Cost of Production –Reported production cost of Limestone is 500/Tonnes which is very high.<br>2. Reported Ex Mine Price is high for year 2019-20.<br>3. Lease No. details are not correct.<br>Monthly Return:<br>1. Part-II, details of consignee including registration number shall be furnished in the returns.   |
| 47       | The holder of a mining lease shall send intimation in Form I of the Schedule to the authorised officer, within fifteen days after the commencement the sinking of borehole to a depth exceeding ten meters from the surface but intimation not sent to authorised officer.   |
| 48       | The holder of a mining lease shall keep a record in Form-J of all boreholes and shall retain such records and preserve the samples of the strata passed through for a period of not less than twelve months after the completion of the work or abandonment thereof. But during inspection Form-J of all boreholes was not found.  |

- On perusal of your reply of letter No.MCG/DBLSM/HP/2021-367 dated 09-03-2021 received by this office dated 17-03-2021, it is found that complainece of rules 11(1), partly of 45(7) i.e. annual returns, 47 & 48 have been made whereas complainece for violation of Rule 45(7) i.e. monthly returns part is not found complied. Thus violation of rule 45(7) of MCDR, 2017 pertaining to monthly returns still persists.
- In this connection, it is brought to your kind notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.
- Advise the State Government to order suspension of all mining operations in the mines as per provision of Rule 45(7), in case if it is found that the holder of a mining lease, has submitted incomplete or wrong or false information in statutory returns or fails to submit such return within the date specified under Rule 45.
- You are advised to rectify the above violations immediately and intimate the complainece position to this office within 30 days from date of issue of this letter.
- You are therefore directed to show cause within a period of thirty (30) days from the date of issue of this letter, as to why you should not be prosecuted and / or why the mining operation should not be suspended under relevant statutory provisions and/or why not any other appropriate action can be initiated in accordance with rules and/or any competent orders/directives.



7. Please note that no further notice will be given to you in this regard.

भवदीय Yours faithfully,

  
20-03-2021

(दामोदर प्रसाद शर्मा /D P Sharma)  
सहायक खान नियंत्रक /Assistant Controller of Mines  
भारतीय खान ब्यूरो / Indian Bureau of Mines

प्रतिलिपि सूचनार्थ प्रेषित :-

- 1- खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर। (zo.udaipur@ibm.gov.in)
- 2- निदेशक उद्योग निदेशालय, हि0 प्र0 सरकार, उद्योग भवन, शिमला (हि0 प्र0). (geologicalwing@gmail.com)
- 3- गार्ड फाइल

सहायक खान नियंत्रक /Assistant Controller of Mines