

भारत सरकार GOVERNMENT OF INDIA खान मंत्रालय MINISTRY OF MINES भारतीय खान ब्यूरो INDIAN BUREAU OF MINES क्षेत्रीय खान नियंत्रक कार्यालय



OFFICE OF REGIONAL CONTROLLER OF MINES

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमक्र रोड,

गोरगुंटापाल्या येशवंतप्र

बेंगल्र -560022

दूरभाष: (080) 39505368 / 29720499

Email ID: ro. bangalore@ibm.gov.in

सं/No.: KNT/DVN/Mn-2/BNG Mine-code: 40KAR27004 दिनांक/Dated: 06/04/2022

To,

To: Sri B.Anoop Kumar, Managing Partner,

M/s Sri Yerrithatha Mining Company

#53, BCM Compound, Infantry Road, Cantonment,

BALLARI -583 104, Karnataka State.

sriymco@gmail.com

विषय/Subject: Violation of provisions of MCDR 2017 in respect of your Kadathi Mn ore Mine, ML 1783 over an extent of 12.56 ha in Kadathihalli Village, Harpanahalli Taluk, Davangere District of Karnataka State.

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during inspection on 14.03.2022 by the undersigned in the presence of Shri A.P. Moses, Mines Manager, Shri S.Mohan Kumar, Geologist, Shri Shiva Raj, Mining Engineer

Rules	Nature of Violations observed
11 (1)	Modification to the approved Mining plan was approved by IBM vide letter no. 279/932/2006/BNG dated 31/03/2016, for the period 2016-17 to 2020-21. The deviations observed in mining operation vis-à-vis approved document are given below: i)It was observed during the inspection that during the year 2020-21, the construction of 75mx 1.5m x 2.0m of retaining wall and 75mx 1.0m x 1.5m of Garland drain has been proposed. The same has not been carried out.

- 02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR, 2017.
- 03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
- 04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty-Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-(K.Srinivas) Junior Mining Geologist

Copy for kind information to:

- 1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
- 2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

Sd/-

(K.Srinivas) Junior Mining Geologist Indian Bureau of Mines