### INDIAN BUREAU OF MINES MINERALS DEVELOPMENT AND REGULATION DIVISION

# Mining Plan Modification REPORT

# Jabalpur regional office

	Mine	file No : MP/STN/OCH-7	5		Mine	code :	44MPR35082
	(i)	Name of the Inspecting Officer and ID No.	:	SQ05 ) DEEPAK SHARMA			
	(ii)	Designation	:	Senior Mining Geologist			
	(iii)	Accompaning mine Official with Designation	:	Shri R C Bansal			
	(iv)	Date of Inspection	:	16-MAR-22			
	(v)	Prev.inspection date	:				
		PAF	۲ <b>۳</b> –	I : GENERAL INFORMATION			
1.	(a)	Mine Name	:	MUNGWARI (9.166 HA)			
	(b)	Registration NO.	:				
	(c) (d) (e) (f) (g) (h)	Category Type of Working Postal address State District Village Taluka Post office Pin Code FAX No. E-mail Phone Police Station First opening date Weekly day of rest	: : : : : : : : : : : : : : : : : : : :	MUNGWARI RAGHURAJNAGAR SUKWAH 485221 N. A. N. A.			
2.		ess for espondance	:	SHRI R.C.BANSAL P.O. JAITWARA, DIST. SATNA (M.P.) 485221			
3.	(a) (b) (c) (d)	Lease Number Lease area Period of lease Date of Expiry	:	MPR0857 9.16 20 16-JUL-02			
4.	Mine	ral worked	:	LATERITE Asso	ciated ciated ciated	l	

5.	Name and Address of the		
	Lessee :	RAMCHANDRA BANSAL	
		P.O. JAITWARA SATNA	
		MADHYA PRADESH	
		Phone:09425812197/07671-274270	
		FAX :N. A.	
	Owner :	RAMCHANDRA BANSAL	
		AR & P.O. JAITWARA,	
		DIST.SATNA M.P SATNA MADHYA	
		PRADESH	
		Phone: 09425812197	
		FAX : 07672-274272,23	
6.	Date of approval of Mir	ing : Mining Scheme rule 12 MCDR1988	07-APR-97
	Plan/Scheme of Mining	Renewal under rule 22 MCR1960	11-JUN-03
		Mining Scheme rule 12 MCDR1988	05-NOV-08
		FMCP under 23C(1)	11-DEC-08
		Mining Scheme rule 12 MCDR1988	
		MP review under 17(1) MCR 2016	10-AUG-18

Exploration :

Sl.No.	Item	Proposals	Actual work	Remarks
la	Backlog of previous year	NO BACKLOG OF PREVIOUS YEAR	NO BACKLOG OF PREVIOUS YEAR AS THE MINE IS NOT IN OPERTAIONAL SINCE 2017	
1b	Exploration over lease area for geological axis 1 or 2	IS EXPLORED	ML AREA IS EXPLORED UPTO G1 LEVEL	)
1c	Exploration Agencies and Expenditure in lakh rupees during the year	NOT MENTIONED	NOT APPLICABLE	
ld	Balance area to be explored to bring Geological axis in 1 or 2	ML AREA EXPLORED UPTO G1 LEVEL	ML AREA NEEDS TO EXPLORE UPTO G1 LEVEL, FRESH EXPLORATION PROPOSAL ASKED	
1e	Balance reserve as on 01/04/20	111-133157 211-36183	111-94521 211-50331 RESERVES REESTIMATED AS PER MEMC RULE 2015	NO DEPLETION AS THE MINE IS NOT IN OPERATION FOR WANT OF EC NO PRODUCTION REPORTED IN THE AR
lf	General remarks of inspecting officers on geology, exploration etc			ML BELONGS TO VINDHYAN SUPER GROUP OF ROCKS IN THE SATNA REGION, HOST ROCK IS SATNA-REWA SANDSTONE

Sl.No.	Item	Propasals	Actual work	Remarks

Location of IN THE LAST NOT APPLICABLE , THE 2a development PLAN PERIOD MINE IS NOT IN w.r.t.lease area YEAR 2021-22 OPERTAIONAL SINCE 2013-14 FOR WANT OF EC IT WAS PROPOSED TO WORK IN THE NORTHERN SIDE OF THE ML AREA ADVANCING TOWARDS EASTERN DIRECTION 2b Separate benches IT WAS NOT APPLICABLE in topsoil, PROPOSED TO overburden and MAINTAINED minerals (Rule SEPARATE BENCHES 15) 2c Stripping ratio 1:0.29 NIL or ore to OB ratio NIL 2d Quantity of NOT APPLICABLE topsoil generation in m3 Quantity of 3733 NOT APPLICABLE 2e overburden generation in m3 General remarks MINE WAS NOT IN 2f OPERATIONALS SINCE of inspecting officers on 2013-14. FOR THE WANT OF EC. development of pit w.r.t. type of deposit etc

#### Exploitation:

Sl.No.	Item	Propasals	Actual work	Remarks
3a	Number of pit proposed for production	SINGLE OLD PIT	NOT APPLICABLE	
3b	Quantity of ROM mineral production proposed	5520	NIL	

3с	Recovery of sailable/usable mineral from ROM production		NIL
3d	Quantity of mineral reject generation	NOT PROPOSED	NOT APPLICABLE
3e	Grade of mineral rejects generation and threshold value declared.	NOT PROPOSED	NIL
3f	Quantity of sub grade mineral generation.	NOT PROPOSED	NIL
Зg	Grade of sub grade mineral generation	NOT PROPOSED	NIL
3h	Manual / Mechanised method adopted for segregating from ROM	MECHANICAL METHOD WERE PROPOSED	NIL
3i	Any analysis or beneficiation study proposed and carried out for sub grade mineral and rejects.	NOT PROPOSED	NIL
3j	Provision of drilling and blasting in mineral benches	NOT PROPOSED DUE TO SOFT STRATA	NIL
3k	Provision of mining machineries in mineral benches	HEMM USE WAS PROPOSED	NIL
31	of benches in overburden and mineral suitable for method of		NIL

3m	Total area covered under excavation/pits	3.15 HECT	2.05 HECT	
3n	Ore to OB ratio for the pit/mine during the year.	1:0.29	NIL	
30	Total area put in use under different heads at the end of year	4.26 HECT	3.06 HECT	
3р	Production of ROM mineral during the last five year period as applicable	2020-21=9384	2019-20=0 2020-21=0	
3q	General remarks of inspecting officers on method of mining etc.			MINE IS CLOSED SINCE 2013-14, DUE TO WANT OF EC AS ON DATE EC NOT OBTAINED

Solid Waste Management - Dumping:

Sl.No.	Item	Propasals	Actual work	Remarks
4a	Separate dumping of topsoil, OB and mineral rejects (Rule 32,33)	PROPSOED	NOT APPLICABLE	
4b		DUMPS WERE PROPOSED IN THE EASTERN SIDE OF THE ML AREA	NIL	
4 c	Number of dumps within lease area and outside of lease area		TWO TO THREE OLD SMALL DUMPS WERE PRESENT IN THE ML AREA	
4d	Location of dumps w.r.t. ultimate pit limit (Rule 16)	WITHIN THE UPL	WITHIN THE UPL	
4e	Number of active and alive dumps.	NONE	NIL	
4f	Number of dead dumps.	TWO TO THREE	TWO TO THREE	

4g	Number of dumps established.	NOT	PROPOSED	NIL
4h	Whether Retaining wall or garland drain all along dumps are there.	NOT	PROPOSED	NIL
4i	Length of Retaining wall or garland drain all along dumps	NOT	PROPOSED	NIL
4j	Number of settling ponds	NOT	PROPOSED	NIL
4 k	Specific comments of inspecting officer on waste dump management			

MINE WAS CLOSED SINCE 2013-14 FOR WANT OF EC

# Solid Waste Management - Backfilling:

Sl.No.	Item	Propasals	Actual work	Remarks
5a	Status of part or full extraction of mineral from mined out area before starting backfilling.		NIL	
5b	Area under backfilling of mined out area	NOT PROPOSED	FULL EXTRCATION OF MINERAL IS NOT COMPLETED YET	
5c	Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)	PROPOSED IN THE PLANTATION	NIL	
5d	Total area fully reclaimed and rehabilitated	NOT PROPOSED	NIL	

NO AREA IS MATURE ENOUGH FOR BACKFILING AND RECLAMATION AS MINERAL IN NOT EXTRCATED YET UPTO THE UPD

#### Progressive Mine Clousre Plan:

General remarks of inspecting

backfilling and

reclamation etc.

officers on

5e

Sl.No.	Item	Propasals	Actual work	Remarks
ба	Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).	PROPOSED	NOT SUBMITTED MINE WAS NOT IN OPERATIONAL SINCE 2013-14	
6b	Area available for rehabilitation (ha) .	NOT PROPOSED	NIL	
6c	afforestation done (ha).	NOT PROPOSED	NIL	
6d	No. of saplings planted during the year	NOT PROPOSED	NIL	
6e	Cumulative no .of plants	NOT PROPOSED	NIL	
6f	Any other method of rehabilitation	NOT PROPOSED	NIL	

#### Mineral Conservation:

Sl.No.	Item	Propasals	Actual work	Remarks
7a	ROM Mineral dispatch or grade-wise sorting within lease area	GRADE WISE SORTING WAS PROPOSED MANUAL AND MECHANICAL BOTH	NIL	
7b	Method of grade- wise mineral sorting i.e. manual or mechanical.	MANUAL AND MECHANICAL BOTH	NIL	

7c	Different grade of mineral sorted out at mines.	NOT	PROPOSED	NIL
7d	Any beneficiation process at mines	NOT	PROPOSED	NIL
7e	General remarks of inspecting officer on Mineral conservation and beneficiation issues			

MINE WAS NOT IN OPERATIONAL SINCE 2013-14, FOR WANT OF EC AS ON DATE EC NOT OBTAINED

#### Environment:

Sl.No.	Item	Propasals	Actual work	Remarks	
8a	Separate removal and utilization of topsoil (Rule 32)	PROPOSED	NIL		
d8	Concurrent use or storage of topsoil	PROPOSED	NIL		
8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	PROPOSED	NIL		
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	PROPOSED	NIL		

8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	PROPOSED	NIL	
8f	Baseline information on existence of plantation and additional plantation done (Rule 41)	PROPOSED	NIL	
8g	Survival rate	NOT PROPOSED	NIL	
8h	Water sprinkling on roads to control airborne dust	PROPOSED	NIL	
8i	General remarks of inspecting officer on aesthetic beauty in and around mines area			MINE WAS NOT IN OPERATIONAL SINCE 2013-14

# Compliance of Rule 45:

Sl.No.	Item	Propasals	Actual work	Remarks
9a	Status of submission of Monthly and Annual returns		AR SUBMITTED UPTO 2020- 21 AND MR SUBMITTED UPTO FEB 22	
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager		MINE IS NOT IN OPERTAION AND LESSEE HIMSELF IS MINING ENGINEER GEOLOGIST IS NOT APPOINTED	
9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.		DETAILS NOT FURNISHED IN THE AR AS THE MINE NOT IN OPERATIONAL	

9d Scrutiny of Annual return on afforestation

9f Scrutiny of Annual return on ROM stock and/or graded ore

9g Scrutiny of Annual return on sale value, Ex. Mine price and production cost

9h Scrutiny of Annual return on fixed assets

9k Scrutiny of Annual return on mining machineries DETAILS NOT FURNISHED IN THE AR AS THE MINE NOT IN OPERATIONAL DETAILS NOT FURNISHED IN THE AR AS THE MINE NOT IN OPERATIONAL

DETAILS NOT FURNISHED IN THE AR AS THE MINE NOT IN OPERATIONAL

DETAILS NOT FURNISHED IN THE AR AS THE MINE NOT IN OPERATIONAL DETAILS NOT FURNISHED IN THE AR AS THE MINE NOT IN OPERATIONAL

Details of violations observed during current inspection and compliance position of violation pointed out				
Viola	tion observed		Sho	ow couse position
Rule NO.	Issued on	Compliance on	Rule NO	. Issued on Compliance on

Date :

#### (DEEPAK SHARMA)

Indian Bureau of Mines