Date: 29.03.2019



भारत सरकार GOVERNMENT OF INDIA खान मंत्रालय MINISTRY OF MINES भारतीय खान ब्यूरो INDIAN BUREAU OF MINES क्षेत्रीय खान नियंत्रक के कार्यालय OFFICE OF THE REGIONAL CONTROLLER OF MINES



BY REGD POST A/D

Phone: 0674-2352463 Tele Fax: 0674-2352490 E-mail: ro.bhubaneshwar@ibm.gov.in

Plot No.149, Pokhariput BHUBANESWAR-751020

No. ORI/BXT/KPT/MCDR-3/BBS

To

The Managing Director, M/s Odisha Mining Corporation Ltd, OMC House, Bhubaneswar-751001

Sub: Violation of provisions of MCDR, 2017 in respect of your Kodingamali Bauxite Mine over an area of 428.075 ha in Koraput & Rayagada district of Odisha State.

Sir,

The following provisions of Mineral Conservation and Development Rule, 2017 (MCDR, 2017) were found violated in respect of the above said mine during inspection on 12.03.2019 by under signed.

Rule	Proposed as per approved modification	Violation
No.	of Mining Plan	V TOTALLOTT
11(1)	In the year 2018-19, it was proposed to drill 24 Nos. of Bore Holes as per the modification of Mining Plan approved on 20.12.2017.	During inspection, it is observed that no Bore Holes has been drilled against the proposal of 24 Nos. of Bore Holes.
12(1)	The prospecting and mining operations shall be carried out in such a manner so as to ensure systematic development of mineral deposits, conservation of minerals and protection of the environment.	 (1) During inspection, it is observed that the waste dump terrace height is around 15m against proposal of 10m maximum. (2) During inspection it is observed that the retaining wall has not been maintained properly around the waste dump to check wash off.
45(7)	If it is found that the holder of a mining lease or the person or company engaged in trading or storage or end-use or export of minerals, as the case may be, has submitted incomplete or wrong or false information in daily or monthly or annual returns or fails to submit a return within the date specified.	(1) On examination of monthly return for the year 2018-19 i.e. Feb'2019 it is observed that in Part-II, S.I. No. 4, sale value of mineral furnished without including payments towards Royalty, DMF & NMET.

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR, 2017.

Besides, inability to comply with the provisions of Rule 11(1) is liable for suspension of mining operations according to the provisions of Rule 11(2) of MCDR, 2017.

03. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty five) days from issue of this letter.

Yours faithfully,

(हरकेश मीना) क्षेत्रीय खान नियंत्रक

Copy forwarded for kind information to:

- (1) The Director of Mines, Directorate of Mines, Government of Odisha, Heads of Department Building, Bhubaneswar-751 001
- (2) The Controller of Mines (EZ), Indian Bureau of Mines, CP-13, Sector V Salt Lake City, Kolkata- 700 091.

(हरकेश मीना) क्षेत्रीय खान नियंत्रक