

VIOLATION LETTER

संख्या : एचपी/एसआरएम/ एलएसटी-29

Mine Code: 38HPR10001

रजिस्टर्ड ए0 डी0
100-ओल्ड नेहरू कालोनी,
देहरादून, (उत्तराखण्ड),
दिनांक : 23.01.2017

सेवा में :
मै0 फ्रैन्ड्स मिनरल्स
पार्टनर- श्री चन्द्र मोहन शर्मा
वार्ड नं0-3, आदर्श कालोनी,
पॉवटा साहिब,
जिला-सिरमौर (हि0प्र0)।

विषय : Violation of provisions of Mineral Conservation & Development Rules, 1988 in respect Of your **Bandla** Limestone Mine in Sirmour District of Himachal Pradesh State

The following provisions of the Mineral Conservation and Development Rules, 1988 were found violated in your above mine during the inspection made on 20.01.2017 by the undersigned in presence of Shri K. Mishra, Mine Manager

Rule No. Nature of violation observed in detail

13(1) The mining operations are carried out in violation of following provisions of approved Review & Updation of Mining Plan (Approved on 29-07-2016): -

- 1) Mine development work is not commensurate with the proposal made in the approved Review & Updation Mining Plan.
- 2) No effective preventative measures have been taken to prevent roll down the waste material into natural drainage.

23(E)(2): A yearly report to be submitted before 1st July of every year setting forth the extent of protective and rehabilitation works carried out as envisaged in the approved mine closure plan has not been submitted to this office for the year 2015-16.

45(5) (a) Monthly returns for month of December 2016 has not been submitted to this office.

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 58 of MCDR, 1988.
03. The mining operation can be suspended under rule 13(2) of MCDR 1988 if compliance of rule 13(1) of MCDR 1988 is not found-satisfactory.
04. You are advised to rectify the above violations immediately and intimate the position to this office on letter pad signed by the owner within 45 (forty-five) days from the date of issue of this letter.

पत्र प्रेषित किया
दि 0 23/1/17
Rajesh

भवदीय,

साधु राम शर्मा
23/01/2017

(डी0आर0 गुर्जर)
सहायक खान नियंत्रक
भारतीय खान ब्यूरो

o/c

प्रतिलिपि सूचनार्थ-

1. खान नियंत्रक (उ0), भारतीय खान ब्यूरो, उदयपुर।
2. निदेशक, उद्योग विभाग, उद्योग भवन, हि0प्र0सरकार, शिमला।

साधु राम शर्मा
23/01/2017

सहायक खान नियंत्रक
भारतीय खान ब्यूरो

o/c