

GOVERNMENT OF INDIA
MINISTRY OF MINES
INDIAN BUREAU OF MINES
OFFICE OF THE REGIONAL CONTROLLER OF MINES
No. JHK/LTH/BX-251/RRO.

318/B, Road No.3
Ashok Nagar, Ranchi – 834 002
Date: 14.09.2016

To

(1) ShriK.N.Bhandari, Nominated Owner (2) Shri B.K. Jha, Joint President & Agent
M/s HINDALCO Industries Ltd. M/s HINDALCO Industries Ltd.
Court Road, Lohardaga Court Road, Lohardaga
Jharkhand-835 302 Jharkhand-835 302

Sub: Violation of provisions of MCDR 1988 in respect of your Chiro-Kukud Bauxite Mine in Latehardistrict, Jharkhand State, over an extent of 166.68ha– reg.

Sir,

The following provisions of Mineral Conservation and Development Rules, 1988 were found violated in your above mine during the inspection on 22.08.2016 by the undersigned, accompanied by ShriR.R.P.Ambasta, Mine Manager.

Rule	Nature of Violation observed
23E(2)	The yearly report on protective rehabilitation measures for the year 2015-16 has not been submitted to the Regional Controller of Mines, IBM, Ranchi so far, which ought to have been submitted before 1 st July of the following year for the preceding financial year as required under the rule.
29	The updated plans and sections for the year 2015-16, as required under rule 28 has not been submitted to the Controller General IBM Nagpur, Controller Mines (CZ) IBM Nagpur and the Regional controller of Mines, IBM Ranchi, which has to be submitted on or before 30 th June 2016.
42(1)(c)(i)	Since, the mine falls under category –A (Other Than Fully Mechanised), a full time Mining Engineer holding degree in mining engineering has not been employed to carry out mining operations as required under the rule

02. In this connection, it is brought to your notice that the above violation constitutes an offence punishable under Rule 58 of MCDR, 1988.

03. You are, therefore, advised to rectify the above violations immediately and intimate the position to this office within 45 (forty five) days from the date of issue of this letter.

Yours faithfully,

Sd/-
(G.C.SETHI)
Deputy Controller of Mines

N.O.O.:

Copy for kind information to: -

1. The Controller of Mines (CZ), IBM, Indira Bhawan, Civil Lines, Nagpur.
2. The Director of Mines, Govt. of Jharkhand, Nepal House Area, Doranda, Ranchi-834 001.

Sd/-
(G.C.SETHI)
Deputy Controller of Mines