



भारत सरकार  
खान मंत्रालय  
भारतीय खान ब्यूरो  
क्षेत्रीय खान नियंत्रक का कार्यालय  
पोस्ट-फाटोडा, मडगाँव, दक्षिण गोआ 403602

GOVERNMENT OF INDIA  
MINISTRY OF MINES  
INDIAN BUREAU OF MINES  
OFFICE OF REGIONAL CONTROLLER OF MINES  
P.O. Fatorda, Madgao, South Goa – 403602

संख्या: महा/कोल्हा/बाक्साइड-9/गोवा

खानकोड 07MSH13008

दिनांक : 02-03-2016

सेवामें

श्री सुरेन्द्र टी. कोडाचवाड, खान मालिक,  
भरतेश कन्सट्रक्शन कम्पनी,  
34/35 कारपोरेशन काम्पलेक्स,  
गोवा-वेस, हिन्दवाडी, बेलगाम-590011

विषय: महाराष्ट्र राज्य के कोल्हापुर जिले के शाहूवाडी तालुका में स्थित आपकी गिरगाँव बाक्साइड खान 140.20 हेक्टेयर में खनिज संरक्षण एवं विकास नियमावली, 1988 के नियमों का उल्लंघन।

महोदय,

अद्योहस्ताक्षरी द्वारा दिनांक 04.02.2016 को श्री अमृत साबले, खान प्रबन्धक और श्री गुरु किरण, खनि अभियन्ता की उपस्थिति में उपरोक्त खान का निरीक्षण किया गया था और खनिज संरक्षण एवं विकास नियमावली, 1988 के निम्नलिखित नियमों का उल्लंघन पाया गया है।

नियम	उल्लंघन के प्रकार का विस्तृत ब्योरा
13(1)	<p>The mining operations in the lease area are not carried out as per scheme of mining approved vide letter No. MSH/MECH/-90(MAH)Goa/2014-15 dated 20.04.2015 and following deviations are observed during inspection.</p> <p>a) It was proposed in Para 2.0B.II for 50,000t recovery of cement grade (+30 Al<sub>2</sub>O<sub>3</sub> to -35% Al<sub>2</sub>O<sub>3</sub>) sub-grade bauxite production by dump rehandling during the year 2015-16 from Dump-1, 2 &amp; 3 with 35% total recovery and remaining 65% waste was planned for backfilling as reclamation &amp; rehabilitation of mined out area of pit. It was observed during inspection of mine that these three dumps are found intact and not re-handled for recovery of cement grade bauxite and backfilling in the mined out area. The grade of 34.45% Al<sub>2</sub>O<sub>3</sub>, 32.98% Al<sub>2</sub>O<sub>3</sub> and 30.57% Al<sub>2</sub>O<sub>3</sub> bauxite was estimated from Dump-1, 2 &amp; 3 respectively.</p> <p>b) It was proposed in Para 4.0c) for backfilling of 49,200m<sup>3</sup> of waste from dump rehandling to reclaim 12.0ha plateau area inbetween E380250-E380400 and N1863100-N1863270. It was observed during inspection of mine that three dumps are found intact and reclamation is not started over the planned area.</p>
45(5)(b)	<p>It is observed on scrutiny of office records that online Annual returns of the mine for the year 2014-15 have been submitted in Form-H-3 with following short comings.</p> <p>a) Part V-4.2(B): The 25,000t ROM production is indicated here and quantity of OB/waste removed is kept blank. However, ROM production was 285500t during the year as per Part-VI. Further, 25,000t waste is reported under backfilled during the year.</p> <p>b) Use of mobile crushing &amp; screening plant is not reported in the return; although three units were in operations as per last inspection dated 12.12.2014. Updated surface plan and sections are not submitted by post so far and wrongly indicated as not applicable in A.R.</p> <p>c) Mineral reject is a part of ROM material, but you have shown opening &amp; closing stock of different grade of mineral at par with ROM ore without including mineral reject of 25000t under cement grade. Generation of 25,000t mineral reject of 28% Al<sub>2</sub>O<sub>3</sub> grade is indicated in Part-V-4.2(B), but grade of mineral reject should be more than threshold limit i.e 30% Al<sub>2</sub>O<sub>3</sub>. It is not clear that whether mineral reject and waste are treated at par in A.R. due to equal quantity of 25,000t.</p> <p>d) Appointment of Shri Guru Kiran as Mining Engineer is neither reported in the A.R. of 2014-15 nor separate intimation is sent in Form-I.</p>



भारत सरकार  
खान मंत्रालय  
भारतीय खान ब्यूरो  
क्षेत्रीय खान नियंत्रक का कार्यालय  
पोस्ट-फाटोडा, मडगाँव, दक्षिण गोआ 403602

GOVERNMENT OF INDIA  
MINISTRY OF MINES  
INDIAN BUREAU OF MINES  
OFFICE OF REGIONAL CONTROLLER OF MINES  
P.O. Fatorda, Madgao, South Goa – 403602

02. इस सम्बन्ध में आपका ध्यान आकर्षित किया जाता है किया जाता है कि उपरोक्त नियम का उल्लंघन खनिज संरक्षण एवं विकास नियमावली, 1988 के नियम 58 के अन्तर्गत दंडनीय अपराध हैं।
03. उपरोक्त नियम की अनुपालना नहीं होने पर खनिज संरक्षण एवं विकास नियमावली, 1988 के नियम 13(2) के अन्तर्गत खान में सभी खनन संक्रियाएँ बन्द की जा सकती हैं।
04. अतः आपको सलाह दी जाती है कि आप उपरोक्त उल्लंघन का अतिशीघ्र सुधार करें एवं इसके सुधार की स्थिती की जानकारी इस पत्र के जारी होने की दिनांक से 45 (पैंतालीस) दिनों के भीतर इस कार्यालय को सूचित करें।

भवदीय

(गिरीश कुमार जांगिड)  
उप खान नियंत्रक

- प्रतिलिपी सूचनार्थ : 1. खान नियंत्रक (द. आ.) भारतीय खान ब्यूरो, बैंगलूरु  
2. उप निर्देशक, भूविज्ञान एवं खान विभाग, नागलापार्क, कोल्हापुर- 416003

(गिरीश कुमार जांगिड)  
उप खान नियंत्रक