Registered/Speed Post Violation letter



GOVERNMENT OF INDIA MINISTRY OF MINES INDIAN BUREAU OF MINES OFFICE OF REGIONAL CONTROLLER OF MINES



29, Industrial Suburb, II Stage, Tumkur Road, Gorguntapalya, Yeshwantpur, Bangalore- 560 022.

Date: 01.02.2018

FAX: 080-23371027/

23373287

Tel: 080-23371027 /

23375366 / 67

Email ID:

ro.bangalore@ibm.gov.in rcombng@rediffmail.com

No.KNT/BLR/FE/413/BNG

To,

Shri.Allum Prashanth, Mine Owner, Gadagi Palace, Car Street, Ballari. Karnataka- 583101

Sub: Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your Sanjeevnarayana Kote Iron Ore Mine (ML-2289) of Shri.Allum Prashanth over an area of 42.42 Ha located in Sanjeevarayanakote Village, Sandur Taluk, Ballari District of Karnataka State.

Sir,

The following provisions of the Mineral Conservation & Development Rules 2017 were found violated in your above mine during the inspection carried out by the undersigned in presence of Shri. Allum Prashant, Mine Owner and Shri. A P Sing, Mines Manager on 11.01.2018.

Rule	Nature of violations observed
11(1)	Scheme of Mining with PMCP was approved vide letter no.279/584/97/BNG dated 18.04.2016 for a period of 2016-17 to 2020-2021. The deviation observed in mining operation vis-a-vis approved document are given below As per the approved document, the benches of 6 Mts height and width more than the height was proposed in the working benches. It was observed that the adequate width of the benches was not maintained.

Responsibility of holder of a mining lease - The holder of mining lease shall submit to the competent authority a yearly report as per the format specified by the Indian Bureau of Mines, before 1st day of July every year setting forth the extent of protective and rehabilitative works carried out as envisaged in the approved mine closure plan, and if there is any deviation, reasons thereof

Yearly report on PMCP has not been sent to this office in the standard format.

- 02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017. Further, the violation of Rule 11(1) may also attract provisions of Rule 11(2) of MCDR, 2017 regarding suspension of mining operations till the compliance of violations.
- 03. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

Yours faithfully,

Sd/-(Arun Kumar) Deputy Controller of Mines

Copy forwarded to:

- 1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
- 2. The Director, Department of Mining & Geology, No. 49, Khanijabhavan, R.C. Road, Bangalore-560 001

Sd/-(Arun Kumar) Deputy Controller of Mines