

भारत सरकार
खान मंत्रालय
भारतीय खान ब्यूरो
क्षेत्रीय खान नियंत्रक का कार्यालय
कर्मयोगी भवन, सैक्टर-10ए, चतुर्थ तल, ब्लॉक-2,
गांधीनगर, गुजरात-382 010



Government of India
Ministry of Mines
Indian Bureau of Mines
Office of the Regional Controller of Mines
Karmyogi Bhawan, 4th Floor, Block-2, Sector 10-A,
Gandhinagar (Gujarat)-382010

ईमेल: gandhinagar.ibm@gmail.com

Mine code-38GUJ21016

Date- 09/4/2019

मिसिल संख्या :Guj/Juna/Lst-55 (vol-I)

प्रेषित :- Shri UdaySingh M Jethwa,
R/o 1, Gatral Bhawan, Satyam Park,
Rajiv Nagar, Porbandar, Dist-Porbandar, Gujarat

विषय:- गुजरात राज्य के पोरबंदर जिले में रानावाव गाँव/तालुका में आपकी रानावाव चूना पत्थर खान, सर्वे नंबर 78/5पी, क्षेत्रफल 12.14 हेक्टर में खनिज संरक्षण एवं विकास नियमावली, 2017 के नियमों का उल्लंघन हेतु।

महोदय,

उपरोक्त खान का स्टार रेटिंग /एमसीडीआर निरीक्षण अधोहस्ताक्षर द्वारा दिनांक 19/3/2019 को खान मालिक के प्रीतिनिधि श्री देवाभाई भूतिया की उपस्थिति में किया गया था तथा खनिज संरक्षण एवं विकास नियमावली 2017 के निम्नलिखित उपबन्धों का उल्लंघन हुआ है।

नियम	उल्लंघन के प्रकार का विस्तृत ब्यूरो
Rule 11(1)	<p>The mining operations were not being carried out as proposed in approved Review of mining Plan vide 684(4)(1)/MP-37(86/17)/2017-GNR Dated 24.1.2018.</p> <p>(1) Excavation-In was proposed for excavation/ mine workings in Pit No.2 & Pit No.1 for the year 2017-18 (Jan to March) & 2018-19 in southern part of lease area only as earmarked in plate No 6 & 6A but actual excavation/ mine workings has been carried out in lower benches/levels of south pits (Pit No.1&2) & North East side of lease area/pit where no proposal was there for the years. Further no minimum bench width maintained & formed high walls of more than 3m height which was not proposed. More so HEMM used in mine/pit are not as proposed in approved mining plan.</p>
Rule 45(1)	<p>IBM Registration number IBM/8434/2012 issued to lessee as association of individuals but as per lease deed document, lessee is individual capacity, which is incorrect & needs correction/updation as individual only.</p>
Rule 45(7)	<p>In your case, while scrutiny of annual return 2017-18 & monthly return of Feb, 2019 following discrepancies are observed.</p> <ol style="list-style-type: none">(1) Part-I, Sr No.1 (f) fax number/ phone number & Sr.No.2 Post office and taluka is not given. Sr.No 6& 7 Name of agent & manager is left blank.(2) Part-I, Sr No.12, area exploited is given as 1.125 Ha whereas actual area is about 2ha or more appears to be exploited with in lease area. Area occupied by plant/building, roads & green belt/afforestation etc are not shown. It needs correction.(3) Part-II, Sr No.3 (i) A-C, ROM production reported for the year but opencast face worker & loader shown zero, which is incorrect. It needs correction.(4) Part-III, value of fixed assets & overheads costs are shown zero which is incorrect. Electricity & Tyres & spares and stores are shown zero which is in correct.(5) Part-IV-Total quantity of Overburden reported is left blank. It needs correction.(6) Part-V, Sec-5/6/8/9-HEMM capacity used in mine & proposed in approved mining plan are not same. It needs correction.

	(7) Part-VI, Sr.No.2,4- Computation of Ex-mine price/PMV/Cost of Production is not taken correctly & no Sale invoice copies submitted & reported to this office. It needs correction. (8) Part-VII- Sr No. (5) Entire ROM is reported for sale as chemical grade but copy of sale invoice is not provided. Registration of Hi Bond Cement is shown as zero which is incorrect. Cost of production & their details break up is not provided during inspection. Production proposal for financially year 2017-18 is shown as zero, which is not correct.
Rule 47 & Rule 48	<i>Notice of shaft sinking & boreholes in Form-I & records of shafts and borehole in Form-J-The lessee has been carried out the 06 exploratory core boreholes in the year 2018-19 but no such intimation in form-I & details in form-J submitted to this office along with supporting field photograph & analysis reports etc.</i>
Rule26(2)	<i>A yearly report before 1st July of every year setting forth the extent of protective and rehabilitation work carried out as envisaged in the approved progressive mine closure plan has not been submitted to this office.</i>
Rule 33	The owner, agent, mining engineer or manager of mine shall submit the digital copy along with a print copy of the Surface Geological plan & section on or before the 30th June of every year. In your case, you have not submitted the aforesaid updated plan & section maintained under rule 32 of MCDR, 2017to this office till date.
Rule55(1)(3)	<i>A full time Mining Engineer and Geologist have not been employed for the purpose of carrying out mining operations in accordance with these rules.</i>

02. इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली, 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है तथा इन नियमों के उल्लंघन की अनुपालना नहीं होने पर खनिज संरक्षण एवं विकास नियमावली 2017के नियम 11 (2)/ 45(7) के अंतर्गत खदान की सारी संक्रियाएं बंद की जा सकती है, और / या आपके विरुद्ध अभियोग दायर किया जा सकता है, और / या राज्य सरकार से खदान की सारी संक्रियाएं बंद करने और / या आपके विरुद्ध अभियोग दायर करने की सिफारिश की जा सकती है।
03. अतः आपको यह निर्देशित किया जाता है कि आप इस पत्र के जारी होने की तिथि से **30 दिन** के भीतर उपरोक्त नियमोंके उल्लंघन की अनुपालना इस कार्यालय में दर्ज करावें।

भवदीय

(जी. राम)

वरिष्ठ सहायक खान नियंत्रक,
भारतीय खान ब्यूरो, गांधीनगर

पहले 1 प्रति पर नहीं है।

01. खान नियंत्रक(उ.आ.), भारतीय खान ब्यूरो, उदयपुर को सूचनार्थ प्रेषित।
02. आयुक्त, भूविज्ञान एवं खनन, निदेशालय, गुजरात को सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित। *Further ROM stacked seem to be more than reported in present monthly statutory returns. Entire ROM is reported as chemical grade but proposal ROM are cement & chemical grade.*
03. उप महानिदेशक (सांख्यिकी), खान एवं खनिज प्रभाग, भारतीय खान ब्यूरो, नागपुर, को आवश्यक कार्यवाही हेतु प्रेषित हैं, ताकि ऑनलाइन विवरणी में विसंगति दूर करवा सके (by referred back)। यह पत्र क्षेत्रीय खान नियंत्रक, भारतीय खान ब्यूरो, गांधीनगर के अनुमोदन के बाद ही जारी किया जा रहा है।

(जी. राम)

वरिष्ठ सहायक खान नियंत्रक,
भारतीय खान ब्यूरो, गांधीनगर