

भारत सरकार
खान मंत्रालय
भारतीय खान ब्यूरो
क्षेत्रीय खान नियंत्रक का कार्यालय
कर्मयोगी भवन, सैक्टर-10 ए, चतुर्थ तल, ब्लॉक-2,
गांधीनगर, गुजरात-382 010



Government of India
Ministry of Mines
Indian Bureau of Mines
Office of the Regional Controller of Mines
Karmyogi Bhawan, 4th Floor, Block-2, Sector 10-A,
Gandhinagar (Gujarat)-382010

ईमेल: gandhinagar.ibm@gmail.com

Mine Code-38GUJ08103

Date-09/4/2019

मिसिल संख्या : GUJ/POR/LST-31

प्रेषित : M/s Tata Chemicals Ltd.

Ranavav Quarries, P.O. & Taluka-Ranavav,
District-Porbandar-Gujarat
PIN-360575

विषय:- गुजरात राज्य के पोरबंदर जिले, रानावाव तालुका, अनियाली गाँव में स्थित आपकी अनियाली चुना पत्थर खदान, सर्वे नंबर 207 P, क्षेत्रफल 12.27 हेक्टर में खनिज संरक्षण एवं विकास नियमावली, 2017 के नियमों का उल्लंघन होने बाबत। महोदय,

उपरोक्त खदान का स्टार रेटिंग /एमसीडीआर निरीक्षण अधोहस्ताक्षर द्वारा दिनांक 18/3/19 को खान मैनेजर मयंक श्रीवास्तव की उपस्थिति में किया गया था तथा खनिज संरक्षण एवं विकास नियमावली 2017 के निम्नलिखित उपबन्धों का उल्लंघन हुआ है।

नियम	उल्लंघन के प्रकार का विस्तृत ब्यूरो
Rule 11(1)	<p>The mining operations were not being carried out as proposed in approved of mining Plan vide 684(23)(373)/2005-खानिखस(उ)/Udai Dated 14.9.2016.</p> <p><i>Exploration-It was proposed to drill 02 number of exploratory borehole, 10m depth each to ascertain the mineral continuity & grade at the bottom of the existing pits as earmarked in plate no.4A for the year 2016-17, but no such exploratory boreholes drilled and reported to this office.</i></p>
Rule 45(7)	<p><i>In your case, while scrutiny of annual return 2017-18 & monthly return of Feb, 2019 following discrepancies are observed.</i></p> <ol style="list-style-type: none"> (1) Part-I, Sr No.1 (f) Pin code & fax number & Sr.No.2 Post office and taluka is not given. (2) Part-I, Sr No.12, area exploited is given as 3.11 Ha whereas actual area is about 4ha appears to be exploited with in lease area. It needs correction. (3) Part-II, Sr No.3 (i) A-C, ROM production reported 12150T but opencast face worker & loader shown zero, which is incorrect. It needs correction. (4) Part-III, value of fixed assets & overheads costs are shown zero which is incorrect. Whereas Overhead cost in part-VII mentioned as 4.78Rs/T. It is contradictory & needs correction. (5) Part-IV-Overburden removed is reported in star rating templates whereas zero is annual return. It needs correction. (6) Part-V, Sec-5/6/8/9-HEMM capacity used in mine & proposed in approved mining plan are not same. It needs correction. (7) Part-VI, Sr.No.2,4- Computation of Ex-mine price/PMV/Cost of Production is not taken correctly since captive plant is situated about 130Km away from lease, whereas details of deductions used for computation of Ex mine price is shown zero in respective column. It needs correction. (8) Part-VII- Sr No. (5) Nature of dispatch is reported domestic transfer only whereas it is mentioned as captive consumption. It needs correction. Further registration number 437 reported in buyer's column whereas there is no buyers. It needs correction. Production proposal for financially year 2017-18 is shown as zero, which is not correct.

Rule 26(2)	<i>A yearly report before 1st July of every year setting forth the extent of protective and rehabilitation work carried out as envisaged in the approved progressive mine closure plan for 2017-18 has not been submitted to this office.</i>
Rule 33	The owner, agent, mining engineer or manager of mine shall submit the digital copy along with a print copy of the Surface Geological plan & section on or before the 30th June of every year. In your case, you have not submitted the aforesaid updated plan & section for the year 2017-18 maintained under rule 32 of MCDR, 2017 to this office till date.
Rule 55(1)(3)	<i>A full time Mining Engineer and Geologist have not been employed for the purpose of carrying out mining operations in accordance with these rules.</i>

02. इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली, 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है तथा इन नियमों के उल्लंघन की अनुपालना नहीं होने पर खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 45(7)(1) के अंतर्गत राज्य सरकार से खदान की सक्रियाएं बंद करने और / या आपके विरुद्ध अभियोग दायर करने की सिफारिश की जा सकती है।
03. अतः आपको यह निर्देशित किया जाता है कि आप इस पत्र के जारी होने की तिथि से **45 दिन** के भीतर उपरोक्त नियमों के उल्लंघन की अनुपालना इस कार्यालय में दर्ज करावें।

भवदीय

(जी. राम)

वरिष्ठ सहायक खान नियंत्रक,
भारतीय खान ब्यूरो, गांधीनगर

पहले 1 प्रति पर नहीं है।

01. खान नियंत्रक(उ.आ.), भारतीय खान ब्यूरो, उदयपुर को सूचनार्थ प्रेषित।
02. आयुक्त, भूविज्ञान एवं खनन, निदेशालय, गुजरात को सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित। *The excavation/ mine workings has been carried out with in 7.5m of statutory barrier/common boundary of adjoining leases where no proposal was there, therefore necessary action may be initiated under provision of rules.*
03. उप महानिदेशक (सांखिकी), खान एवं खनिज' प्रभाग, भारतीय खान ब्यूरो, नागपुर को आवश्यक कार्यवाही हेतु प्रेषित हैं, ताकि ऑनलाइन विवरणी मे विसंगति दूर करवा सके (by referred back)। यह पत्र क्षेत्रीय खान नियंत्रक, भारतीय खान ब्यूरो, गांधीनगर के अनुमोदन के बाद ही जारी किया जा रहा है।

(जी. राम)

वरिष्ठ सहायक खान नियंत्रक,
भारतीय खान ब्यूरो, गांधीनगर