

भारत सरकार
खान मंत्रालय
भारतीय खान ब्यूरो
क्षेत्रीय खान नियंत्रक का कार्यालय
कर्मयोगी भवन, सैक्टर-10 ए, चतुर्थ तल, ब्लॉक-2,
गांधीनगर, गुजरात-382 010



Government of India
Ministry of Mines
Indian Bureau of Mines
Office of the Regional Controller of Mines
Karmyogi Bhawan, 4th Floor, Block-2, Sector 10-A,
Gandhinagar (Gujarat)-382010

ईमेल:gandhinagar.ibm@gmail.com

Mine Code- 07GUJ07019

Date-15/3/2019

मिसिल संख्या : GUJ/JMN/BXT-074

प्रेषित : Owner/Agent/Manager/Mining Engineer,
M/s Orient Abrasives Ltd.,
Jamnagar Dwarka Highway,
Dist. - Devbhumi Dwarka, Gujarat- 361 305.

विषय:- गुजरात राज्य के देव भूमि द्वारका जिले, कल्यांपुर तालुका, में स्थित आपकी कोठारिया बाक्साइट खदान, सर्वे नंबर 330/पी, क्षेत्रफल 62.32 Ha हेक्टर में खनिज संरक्षण एवं विकास नियमावली, 2017 के नियमों का उल्लंघन होने बाबत ।

महोदय,

उपरोक्त खदान का निरीक्षण अधोहस्ताक्षर द्वारा दिनांक 16/2/2019 AN को श्री गुनानन्द राय एवं श्री संतोष कलुसकर, की उपस्थिति में किया गया था तथा खनिज संरक्षण एवं विकास नियमावली 2017 के निम्नलिखित उपबन्धों का उल्लंघन हुआ है ।

नियम	उल्लंघन के प्रकार का विस्तृत ब्यूरो
Rule 45(5)(b) & 45(5)(c)	<p>The holder of a mining lease shall submit online returns in respect of each mine to the Regional Controller or any other authorised official of the Indian Bureau of Mines in the following manner. In your case, while scrutiny of annual return 2017-18 & monthly return of Jan, 2019 following discrepancies are observed.</p> <ol style="list-style-type: none"> (1) Part-I, Sr No.12 land used details is not seems to be correct as per approved scheme of mining. Reconcile & furnished correctly. (2) Part-IIA, Capital structure, i.e. value to fixed assets, land, building, plant & machinery, etc. are not mentioned proportionally of other leases. It needs correction. (3) Part-III, Sr. No.1, electricity consumed in mine lease area shown as NIL, which is incorrect. Details of Tyres & Grease, Drill rods and other spares cost shown NIL, which is incorrect. Details of Royalty shown zero whereas ROM production & dispatch area reported in financial year. It needs correction. (4) Depreciation of fixed assets & Overhead cost is not given correctly, reconcile & furnished with respect to weighted average of instant lease instead of similar cost in other leases. (5) Part-V, Sr No.1, Type of Ore-Chemical specification of mineral rejects should be above threshold value & below cut off, It needs correction.. Sr No.4.2 (B),-Total quantity of OB/Waste removal & Mineral rejects shown as NIL which is incorrect. (6) Part-V-Sec-5/6/8/9-HEMM capacity used in mine & proposed in approved mining plan are not same. It needs correction. (7) Part-VI, Sr.No.2- Computation of Ex-mine price is not given correctly based upon invoice etc. Transportation cost from mine pit head to jetty should be mentioned separately in respective column. It needs correction. (8) Part-VI, Sr No-4, It was reported that domestic sale of bauxite mineral of 404.86T was domestic transfer instead of domestic sale. Therefore it needs correction. (9) Part-VII- Sr No. (v) Overhead cost mentioned 61.68Rs/T & Cost of royalty/ tonne mentioned as 120Rs/T which seems to be not correct. cost of production needs to reconcile & furnished

	proportionately. Production proposal for financially year 2017-18 is shown as zero, which is not correct.
Rule 28(1)	<i>The holder of a mining lease shall send to the authorized officer, as the case may be, and the State Government a notice in Form-E, when the mining & mineral processing operation in the mine or part thereof are dis-continued for a period exceeding ninety days so as to reach them within one hundred and twenty days from the date of such temporary discontinuance. In your case, such discontinuance notice is not submitted to IBM Gandhinagar office so far.</i>
Rule 31(4)	<i>The plans and sections required under these rules shall be maintained up to date within three months in case of category 'A' mines and within twelve months in case of any other mine.</i> But, In your case, it is observed that plans and section required under the prescribed rules were not updated as per the above specified provisions & submitted to this office till date.
Rule 26(2)	<i>A yearly report before 1st July of every year setting forth the extent of protective and rehabilitation work carried out as envisaged in the approved progressive mine closure plan has not been submitted to this office.</i>

02. इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली, 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है तथा इन नियमों के उल्लंघन की अनुपालना नहीं होने पर खनिज संरक्षण एवं विकास नियमावली 2017के नियम 45(7)(1) के अंतर्गत राज्य सरकार से खदान की संक्रियाएं बंद करने और / या आपके विरुद्ध अभियोग दायर करने की सिफारिश की जा सकती है ।
- 03.अतः आपको यह निर्देशित किया जाता है कि आप इस पत्र के जारी होने की तिथि से **45 दिन** के भीतर उपरोक्त नियमों के उल्लंघन की अनुपालना इस कार्यालय में दर्ज करावें ।

भवदीय

(जी. राम)

वरिष्ठ सहायक खान नियंत्रक,
भारतीय खान ब्यूरो, गांधीनगर

पहले 1 प्रति पर नहीं है।

01. खान नियंत्रक(उ.आ.), भारतीय खान ब्यूरो, उदयपुर को सूचनार्थ प्रेषित ।
02. आयुक्त, भूविज्ञान एवं खनन ,निदेशालय , गुजरात को सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित ।
03. उप महानिदेशक (सांख्यिकी), खान एवं खनिज' प्रभाग, भारतीय खान ब्यूरो, नागपुर को सूचनार्थ प्रेषित, यह पत्र क्षेत्रीय खान नियंत्रक, भारतीय खान ब्यूरो, गांधीनगर के अनुमोदन के बाद ही जारी किया जा रहा है।

(जी. राम)

वरिष्ठ सहायक खान नियंत्रक,
भारतीय खान ब्यूरो, गांधीनगर