

भारत सरकार
खान मंत्रालय
भारतीय खान ब्यूरो
क्षेत्रीय खान नियंत्रक का कार्यालय
कर्मयोगी भवन, सेक्टर-10A, चतुर्थ माला,
ब्लॉक-2, सी विंग, गांधीनगर
ई-मेल: gandhinagar.ibm@gmail.com



GOVERNMENT OF INDIA
MINISTRY OF MINES
INDIAN BUREAU OF MINES
Office of Regional Controller of Mines
Karmayogi Bhavan, 4th Floor, Block-2, Sector-10A,
Gandhinagar-382010, Gujarat

मिसिल सं. GUJ/PORB/LST-29

दिनांक: 05.03.19

प्रेषित : **M/s. Tata Chemicals Limited**
Ranavav Quarries
P.O.-Ranavav, Taluka-Ranavav,
Dist-Porbandar, Gujarat-360550.
Email: cdwivedi@tatachemicals.com

विषय : गुजरात राज्य के Porbandar जिले के Ranavav तालुका में स्थित आपकी Aniyari Limestone Mine, सर्वे नं-[207/1P] क्षेत्रफल-21.04 में खनिज संरक्षण व विकास नियमावली 2017 के प्रावधानों का उल्लंघन [(*Mine Code-38GUJ21097*)]

महोदय ,

अधोहस्ताक्षरी द्वारा दिनांक 29/01/2019 को आपकी उपरोक्त खान के निरीक्षण के दौरान खनिज संरक्षण एवं विकास नियमवाली 2017 के प्रावधानों का उल्लंघन पाया गया।

नियम स.	पाए गए उल्लंघन की विस्तृत प्रकृति
Rule 14	<p><i>All the non-saleable or un-usable minerals above the threshold value of mineral, as may be notified by Indian Bureau of Mines from time to time, or otherwise shall be stacked separately on ground earmarked for the purpose.</i></p> <p>But, In your case, it is observed that non-saleable or un-usable mineral i.e. undersize cement grade limestone was stacked in unsystematic manner & near to the working pit in the lease area.</p>
Rule 35(2)	<p><i>Every holder of a mining lease shall monitor his mining & allied activities as per the notified template of star ratings in the format prescribed in this behalf by Indian Bureau of Mines from time to time, and shall submit online its self-assessment report before the first day of July every year for the previous financial year, along with the soft copy of high resolution satellite images from CARTOSAT-2 satellite LISS-IV sensor on the scale of cadastral map, as on the 31st day of March for that financial year, covering the mining lease and an area of two kilometers from the lease boundary, to the Regional Controller of Mines.</i></p> <p>But, in your case, you have submitted the online Star Rating Templates for the year 2017-18 but soft copy of high resolution satellite images from CARTOSAT-2 satellite LISS-IV sensor not submitted to the Regional Controller of Mines, Gandhinagar.</p>
Rule 54(a)	<p><i>The holder of the mining lease or a holder of prospecting license or prospecting cum mining lease shall maintain details of contribution made to District Mineral Foundation and National Mineral Exploration Trust</i></p> <p>But, in your case, it is observed during inspection that you have not maintained relevant documents as required under prescribed rules.</p>

Rule 55(1)(c)(i)	A full time Geologist has not been appointed for the purpose of carrying out the mining operations in accordance with these rules.
---------------------	--

02. इस संदर्भ में आपका ध्यान आकर्षित किया जाता है की उपरोक्त नियमों का उल्लंघन खनिज संरक्षण व विकास नियमावली, 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है।
03. अतः आपको सलाह दी जाती है कि आप उपरोक्त उल्लंघनों का तत्काल सुधार कर इसकी सूचना इस पत्र के जारी होने की तिथि से 45 (पैंतालीस) दिनों के अंदर इस कार्यालय को भेजे

भवदीय,

(संजय गिरहे)
वरिष्ठ खनन भूविज्ञानी
भारतीय खान ब्यूरो

प्रतिलिपि सूचनार्थ हेतु प्रेषित:-

1. खान नियंत्रक (उ.) भारतीय खान ब्यूरो, उदयपुर को सूचनार्थ हेतु।
2. आयुक्त, भूविज्ञान व खनन विभाग, ब्लॉक-1, 7वां माला, उद्योग भवन, गांधीनगर (गुज.),
3. रक्षित पत्रावली।

वरिष्ठ खनन भूविज्ञानी
भारतीय खान ब्यूरो