



भारत सरकार  
Government of India  
खान मंत्रालय  
Ministry of Mines  
भारतीय खान ब्यूरो  
Indian Bureau of Mines

Mine Code: 38RAJ21009

पंजीकृत पावती  
उल्लंघन पत्र  
माखुपूरा औद्योगिक क्षेत्र,  
Makhapura Industrial Area  
अजमेर.-305 002 (राजस्थान)  
Ajmer- 305 002 (Rajasthan)  
फैक्स नं 0145.2695202 फोन नं 2695165

संख्या : RAJ/PAL-45/LST-3

दिनांक : 26.03.2018

प्रेषित : खान एजेंट, रास-1 चूना पत्थर खान,  
मेसर्स अम्बुजा सीमेंट लिमिटेड,  
पोस्ट-राबडियावास, तहसील-जैतारण, जिला-पाली (राजस्थान) 306 709

विषय : Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your **RAS I Limestone Mine** (Lease area 183.53 Hect.) situated in Pali District of Rajasthan State.

महोदय,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during the inspection made on 11.02.2018 by the undersigned in presence of Shri C.S.Dhadheech, Mine Manager

| Rule No.   | Nature of violation observed in detail                                                                                                                                                                                                                                                                                                                     |
|------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Rule 11(1) | The mining operations are carried out in violation of following provisions of approved Modified Mining Plan (Approved on 03.11.2016) in Chapter 4.0: -<br>1) It was proposed a retaining wall along the toe of the waste dump would be constructed to arrest the washed fines and rolling boulders; but no such wall constructed at the toe of waste dump. |
| Rule 47    | Notice of sinking of bore holes in Form-I submitted but the location plan indicating the precise location of bore holes has not been submitted.                                                                                                                                                                                                            |

- In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR, 2017 and in case of non compliance of the above rules following action may be initiated under MCDR, 2017:  
(a) Mining operations may be suspended under rule 11(2) of MCDR, 2017.  
(b) Prosecution may be launched against you.
- You are advised to rectify the above violations immediately and intimate the compliance to this office on letter pad signed by the owner within 45 (forty-five) days from the date of issue of this letter.

भवदीय

( डी. आर. गुर्जर )  
सहायक खान नियंत्रक  
भारतीय खान ब्यूरो

प्रतिलिपि सूचनार्थ प्रेषित :-

- खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर (ई मेल द्वारा)
- निदेशक, खान एवं भूविज्ञान विभाग, राजस्थान सरकार, उदयपुर।
- रक्षित पत्रावली।

सहायक खान नियंत्रक  
भारतीय खान ब्यूरो