

**REPORT ON CHECK UP INSPECTION OF UMSOO-MOOTANG BLOCK-V MINE OF
M/s ADHUNIK CEMENT LTD. SITUATED IN VILLAGE THANGSKAI, TEHSIL NARPUH,
DISTRICT JAINTIA HILLS, STATE MEGHALAYA**

File No: IBM/GHY/MEG/JNH/Lst-14

Mine code/ Lease code: 38MEG03015

Name & Designation of the Inspecting Officer: PK Bhattacharjee, RCOM

Date of inspection: 9.9.2018

1. General Information about the Mine:

- (i). Mine Name: Umsoo Mootang Block-V
- (ii). Owner: M/s Adhunik Cement Ltd.
- (iii). Nominated owner: S/Shri. R.A.Krishna Kumar
- (iv). Mining Engineer: Shishupal Singh
- (v). Geologist: Neelabh Saxena
- (vi). Agent: Sanjay Kumar
- (vii). Mines Manager: Shishupal Singh
- (viii). Lease Area: 128.52 Ha.
- (ix). Location: Village-Thangskai, Tehsil-Narpuh, Distt. – Jaintia Hills, Meghalaya
- (x). Lease Period: 50 years
- (xi). Date of Expiry: 20.12.2066
- (xii). Date of Approval of Mining Plan: 29.4.2010 (from IBM Nagpur)
- (xiii). Date of Approval of Modification/Review of Mining Plan/Mining Scheme/FMCP etc.
29.8.2017 (from IBM Guwahati)
- (xiv). Period of Mining Plan/Mining scheme/FMCP: Upto 31.3.2021

2. Status of compliance of MCDR'2017 during the last 3 years:

SN	Date of Inspection	Name of Inspecting Officer	Violation of MCDR, 1988/2017 Observed & pointed out	Rectification of violation	Remarks
1	30.1.2018	PK Bhattacharjee	NIL	NA	The State Govt. was apprised that the lessee has signed a MDPA wherein the minimum production quantities differ from the modified mining plan. Corrective action taken by the State Govt.

3. Observations/ remarks on the earlier inspection carried out by sub-ordinate officer(s) with specific thrust on systematic and scientific mining, mineral conservation and environmental protection and other sensitive/important aspects pertaining to the mine area or surroundings (CRZ/ Western Ghats/ Wildlife Sanctuaries etc.):

- 1) Name of inspecting officer: Undersigned
- 2) Date and Type of inspection: 30.1.2018, Check up inspection
- 3) Observations/Remarks w.r.t. the inspection carried out by the sub-ordinate officer(s) and shortfalls in the inspection report, if any, thereof: NIL

4. Communication / Direction(s) issued to the concerned RCOM/ IO based on the check-up inspection for further necessary action accordingly: Corrective action taken by the State on the advice issued from this office on the basis of the above inspection. However, violations under MCDR 2017 were observed and accordingly the same were also issued vide letter dtd. 10.9.2018.

Place: Guwahati

Date: 11.9.18

Signature