



**GOVERNMENT OF INDIA
MINISTRY OF MINES
INDIAN BUREAU OF MINES
OFFICE OF THE REGIONAL CONTROLLER OF MINES**



Tel No.080 23371027
Fax No.080 23373287
Email ID: ro.bangalore@ibm.gov.in,

29, Industrial Suburb, II Stage
Tumkur Road, Goruguntapalya
Yeshwantpur, Bangalore-560022

No. KNT/BLR/FE/403/BNG/VolDated: 18/07/2018

To,

Shri Faisal Shareef, Director In Charge.
M/s Nadeem Mineral
“Alfa Manon”, No.27, 1st Floor
Greenglen layout, Off, Outer Ring Road,
Bellandur, Bangalore, Karnataka -560 103

Subject: Violation of provisions of MCDR 2017 in respect of Donimalai Iron Ore Mine (M.L. No. 2526) of M/s Nadeem Minerals, over an extent of 52.82ha, in TaranagarVillage, SandurTaluk, Bellari district, Karnataka State...Reg.

Sir,

The following provisions of Mineral Conservation and Development Rules 2017 were found violated in your above mine during the inspection on 20/6/2018 by undersigned in the presence of Mines Manager S/ShriBharathidasan & Geologist. K.L. Shekhar

Rule 11(1)	<p>It was proposed in Review & Updation of Mining Plan approved vide letter No. 279/591/97/BNG/573 dated 24/10/2017 for the period 2017-18 to 2020-21.. The deviations observed in mining operations vis-a-vis approved document are given below:</p> <p>(i). The proposed development & production as per the year 2018-19, given in plan & sections of plate No. 6B, that as per the field observation made on the day of inspection reveals that the workings are being carried out without forming the systematic benches drawn in the sections, plate 6B, otherwise, it will lead to unsystematic workings in the future.</p> <p>(ii). The waste dumps shown in between sections 13-13' & 14-14' reveals that the waste dump location is now used for stacking BHJ/ BHQ, and extended towards 15-15', which needs to be protected within the given retaining wall & raised through terracing method, instead of spreading laterally.</p> <p>(iii). For waste dump, referred in the approved document with notation as inactive waste dumps, in the same manner, for BHJ/BHQ also, a separate stack need to be created with appropriate notations.</p>
Rule 45(7)	<p>Annual return, for the year 2016-17 & 2017-18, In Part-I, Sl.no. 12(i), wherein 3.95 ha area has been marked for already exploited & abandoned by open cast is not appropriate & correct. If it is so, why this is not updated in the surface plan. If this land is used in reclamation & rehabilitation land also, this need to be reconciled and corrected appropriately.</p>

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservation and Development Rules, 2017.

03. You are, therefore, advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

Yours faithfully,
Sd/-

(C. Parameshwaran)
Dy. Controller of Mines
Indian Bureau of Mines

Copy:(i). The COM (SZ), IBM, Bangalore,for kind information.
(ii). The Director, DMG, Karnataka state, for kind information.

Sd/-
(C. Parameshwaran)
Dy. Controller of Mines