

भारत सरकार Government of India खान मंत्रालय Ministry of Mines

भारतीय खान ब्यूरो Indian Bureau of Mines क्षेत्रीय खान नियंत्रक का कार्यालय Office of the Regional Controller of Mines



100, ओल्डनेहरू कालोनी, देहरादून (उल्तराखंड) 248001 /100 Old Nehru Colony, Dehradun (U.K.)248001

TEL- 0135-2676350 / 2671896, E-mail - ro.dehradun@ibm.gov.in

फाईल संख्या File No: HP/SRM/LST-45 Mine Code: 38HPR10038

दिनाक, 18 February 2020

सेवा में

E- mail: mcshimanchal@gmail.com

To:

श्री चूही राम शर्मा, ग्राम व पोस्ट – कमरऊ, तहसील – पावंटासाहिब, जिला – सिरमौर (हि0प्र0)

विषय Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Bhimgoda Limestone Mine over an area of 3.05 ha located near Village-Kamroo, Tehsil-Karmoo in Sirmour district of HP State.

महोदय Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection made by the undersigned on 23.01.2020 in the presence of Shri Shom Prakash Tomar Mine Manager.

RULE NO.	NATURE OF VIOLATION OBSERVED
11(1)	Mining operation were not carried out in accordance with the approved modified mining plan vide letter no 614(2)/MS-B-65/98-DDN dated 04.06.2018 to the following extent: (i) As per proposal during the year 2018-19, it was proposed to carry out 03 DTH bore holes total metrage 113 mtr, but during the inspection it was observed no such DTH drilling carried out during the year 2018-19. (ii) As per proposal during the year 2018-19, it was proposed to carry out mining operation from 1929 to 1905 mRL by formation of 4 benches 6 mtr height .During the inspection height of benches has been observed about 10 mtrs whereas as per approved modified mining plan it should be six meter
26(2)	The holder of mining lease shall submit to the competent authority a yearly report as per the format specified by the Indian Bureau of Mines, before1 st day of July every year setting forth the extent of protective and rehabilitative works carried out as envisaged in the approved mine closure plan, and if there is any deviation, reasons thereof: On perusal of office records it is observed that yearly report for the year 2018-19 has not been submitted to the competent authority by the holder of the lease in the prescribed in this office till date.
33	The holder of a mining lease shall, on or before the 30 th day of June every year submit to the authorized officer a digital copy along with a print copy of the surface geological plans and sections maintained under rule 32. However, the lessee has not submitted the copies of the plans and sections as per rules.
45(5)(c)	Annual returns for the years ending 31 st March 2018 and 31 st March 2017 have not been submitted by the lessee to the Regional controller/authorized officer of Indian Bureau of Mines

- 2. In this connection, it is brought to your kind notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.
- 3. Mining operations can be suspended as per rule 11(2) in case of non compliance and it constitutes non compliance of Rule 11(1) of MCDR, 2017.
- 4. The mining operation may be advised to the State Govt. for suspension of all the mining operations in this mine as per provision of Rule 45(7), in case of non compliance of Rule 45(5)(c).
- 5. You are advised to rectify the above violations immediately and intimate the compliance position to this office within 45 days from the date of issue of this letter.

भवदीय Yours faithfully,

olc

(दामोदर प्रसाद शर्मा / D P Sharma)

सहायक खान नियंत्रक / Assistant Controller of Mines

प्रतिलिपि सूचनार्थ प्रेषित :-

1- खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर। (zo.udaipur@ibm.gov.in)

2- निदेशक उद्योग निदेशालय, हि0 प्र0 सरकार, उद्योग भवन, शिमला (हि0 प्र0). (geologicalwing@gmail.com)

3- गार्ड फाइल

0/0 .

सहायक खान नियंत्रक / Assistant Controller of Mines भारतीय खान ब्यूरो / Indian Bureau of Mines

C:\Users\ibm\Desktop\Violation Bhimgoda Mine -Chui Ram.docx