



भारत सरकार Government of India

खान मंत्रालय Ministry of Mines

भारतीय खान ब्यूरो Indian Bureau of Mines

क्षेत्रीय खान नियंत्रक का कार्यालय Office of the Regional Controller of Mines

100, ओल्डनेहरू कालोनी, देहरादून (उत्तराखण्ड) 248001 /100 Old Nehru Colony, Dehradun (U.K.)248001

TEL- 0135-2676350 / 2671896, E-mail – ro.dehradun@ibm.gov.in

फाईल संख्या File No: HP/SRM/LST-27 Mine Code: 38HPR100029 दिनांक, 31 March 2020 WFH
 सेवा में मैं. सोहनसिंह मीतसिंह एण्ड संस, E-mail: sohansinghmeetsingh@gmail.com
 To : ग्राम व पो- 0 कमरऊ,
 तह - 0 पावंटा साहिब,
 जिला - सिरमौर (0प्र0हि)

विषय Violation of provisions of Mineral Conservation & Development Rules, 2017 in
 Sub: respect of your Bhimgoda Limestone Mine over an area of 3.32 ha located near
 Village-Kamroo, Tehsil-Paonta Sahib in Sirmour district of HP State.

महोदय
 Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection made by the undersigned on 23.01.2020 in the presence of Shri Som Prakash Tomar, Mine Manager.

| <u>RULE NO.</u> | <u>NATURE OF VIOLATION OBSERVED</u> |
|-----------------|--|
| 11(1) | Mining operation were not carried out in accordance with the approved modified mining plan vide letter no 614(2)/MP-B-288/08- DDN dated 22.02.2019 to the following extent: As per proposal during the year 2019-20, it was proposed to carry out mining operation from 2045 to 1985 mRL by formation of benches 6 mtr height. During the inspection height of benches has been observed up to 10 mtrs whereas as per approved modified mining plan it should be six meter. |
| 29 | “ Mine was found in operation, whereas Intimation of re-opening of mine through Form-C has not been submitted to the authorised officer in the prescribed form on resumption/ restart of mining operation after temporary discontinuance, so as to reach this office within 15 days from the date of such reopening”. |
| 55 | Every holder of mining lease shall employ a geologist in the mine. But geologist has not been appointed in the mine. |

2. In this connection, it is brought to your kind notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.
3. The Mining Operation can be suspended under rule 11(2) of MCDR 2017 in case of non compliance of rule 11(1) of MCDR 2017.
4. You are advised to rectify the above violations immediately and intimate the compliance position to this office within 45 days from the date of issue of this letter.

भवदीय Yours faithfully,

(दामोदर प्रसाद शर्मा / D P Sharma)

सहायक खान नियंत्रक / Assistant Controller of Mines

प्रतिलिपि सूचनार्थ प्रेषित :-

- 1- खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुरा (zo.udaipur@ibm.gov.in)
- 2- निदेशक उद्योग निदेशालय, हि0 प्र0 सरकार, उद्योग भवन, शिमला (हि0 प्र0). (geologicalwing@gmail.com)
- 3- गार्ड फाइल

सहायक खान नियंत्रक / Assistant Controller of Mines
भारतीय खान ब्यूरो / Indian Bureau of Mines