



भारत सरकार Government of India

खान मंत्रालय Ministry of Mines

भारतीय खान ब्यूरो Indian Bureau of Mines

क्षेत्रीय खान नियंत्रक का कार्यालय Office of the Regional Controller of Mines

100, ओल्डनेहरू कालोनी, देहरादून (उत्तराखण्ड) 248001 /100 Old Nehru Colony, Dehradun (U.K.)248001

TEL- 0135-2676350 / 2671896, E-mail – ro.dehradun@ibm.gov.in



फाईल संख्या File No: HP/SOLAN/LST- 03-DDN CV-WFH Mine Code: 38HPR11002 दिनांक, 30 March 2020
सेवा में To: Mines Manager, E-mail: satish.audichya@ambujacement.com
Kashlog Limestone Mine,
M/s Ambuja Cements Ltd,
Village: Kashlog, Tehsil: Arki,
Dist.: Solan, HP-171102

विषय Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Kashlog Limestone Mine over an area of 469 ha located near Village: Kashlog, Tehsil: Arki, District-Solan, H.P State.

महोदय Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the check-up inspection made by the undersigned on 18.02.2020 in the presence of Shri Lokesh Shrimali GM Mines and Sh MP Singh Geologist.

RULE NO.

NATURE OF VIOLATION OBSERVED

- 11(1) Mining operations are not carried out in accordance with the approved mining plan vide 614(2) MP-A-216/05- DDN Dated 21-11-2016 to the following extent:
Benches are found merged at following local grid co-ordinates E 500 to E-700 and N 200 to N 300 @ mRL 1420 to 1460 where bench height was more than 10 m.
- 45(7) The holder of a mining lease has submitted in correct information in annual return for the year 2018-19 as follows;
- 1) Depth of Mine, 240 m, given at Part V Para 4.2 in Opencast Para 4.2(A)(iii) is in-correct.
 - 2) Ex Mine Price is not correct. Ex Mine price is indicated other than cost of production, whereas the mine is captive mine.
- 54, 54(a) and 54 (c) The Holder of Mining lease Shall Maintain the Royalty assessment Register. Whereas the same was not found maintained and details of contribution made to District Mineral Foundation and National Mineral Exploration Trust. Further the details of expenditure incurred towards mine closure activities was also not found maintained
2. In this connection, it is brought to your kind notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.
3. Mining operations can be suspended as per rule 11(2) in case of non compliance and it constitutes non compliance of Rule 11(1) of MCDR, 2017.
4. The mining operation may be advice to the State Govt. for suspension of all the mining operations in this mine as per provision of Rule 45(7), in case of non compliance of Rule 45(7).
5. You are advised to rectify the above violations immediately and intimate the compliance position to this office within 45 days from the date of issue of this letter.

भवदीय Yours faithfully,

(पुष्पेन्द्र गौड़ / Pushpender Gaur)

क्षेत्रीय खान नियंत्रक / Regional Controller of Mines

प्रतिलिपि सूचनार्थ प्रेषित :-

- 1- खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर। (zo.udaipur@ibm.gov.in)
- 2- निदेशक उद्योग निदेशालय, हि0 प्र0 सरकार, उद्योग भवन, शिमला (हि0 प्र0). (geologicalwing@gmail.com)
- 3- गार्ड फाइल

क्षेत्रीय खान नियंत्रक / Regional Controller of Mines