

भारत सरकार Government of India खान मंत्रालय Ministry of Mines

भारतीय खान ब्यूरो Indian Bureau of Mines

भारताय खान ब्यूरा Indian Bureau of Mines

क्षेत्रीय खान नियंत्रक का कार्यालय Office of the Regional Controller of Mines 100, ओल्डनेहरू कालोनी, देहरादून (उत्तराखंड) 248001 /100 Old Nehru Colony, Dehradun (U.K.)248001

TEL- 0135-2676350 / 2671896, E-mail - ro.dehradun@ibm.gov.in

फाईल संख्या File No: HP/SRM/LST-04

Mine Code 38HPR10004

दिनाक, Habitary 2020

e-mail:rajendra.tewari@gmail.com

सेवा में To: M/s Jai singh Thakur & Sons,

119/10-Devi Nagar, Paonta Sahib,

Dist: Sirmour, HP

विषय Sub:

Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Baldhwa Limestone Mine over an area of 12.38 ha located near village-Baldhwa, Post-Kamroo,

Tehsil-Kamroo in Sirmour district of Himachal Pradesh State.

महोदय Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection made by Shri Pushpender Gaur, Regional Controller of Mines on 10.01.2020 in the presence of Shri R.P Tewari, Mine Agent:

RULE NO.	NATURE OF VIOLATION OBSERVED
11(1)	Mining operations are not carried out in accordance with the approved modified mining plan vide letter 614(2)/MS-B-237/06-DDN, dated 18.08.2016 to the following extent: As per proposal during the year 2018-19, it was proposed to carry out Mining operations by formation benches of 6 meters in height. During the inspection it was observed that benches have found merged between along lease line EF. The height of such benches has also been observed more than 10 meters. Whereas it should be six meters as per approved modified Mine plan.
26(2)	The holder of mining lease shall submit to the competent authority a yearly report as per the format specified by the Indian Bureau of Mines, before1 st day of July every year setting forth the extent of protective and rehabilitative works carried out as envisaged in the approved mine closure plan, and if there is any deviation, reasons thereof: On perusal of office records it is observed that yearly report for the year 2018-19 has not been submitted
	to the competent authority by the holder of the lease in the prescribed in this office till date.
	The holder of a mining lease has submitted incomplete or wrong information in annual return.
45(7)	 Ex Mine Price is not correct and abnormally high. Blasting cost and fuel consumption is not found correct.

- In this connection, it is brought to your kind notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.
- 3. The Mining Operations can be suspended as per provision of Rule 11(1), in case of non-compliance of Rule 11(1).

4. The mining operation may be advice to the State Govt. for suspension of all the mining operation in this mine as per provision of Rule 45(7), in case of non compliance of Rule 45(7).

You are therefore advised to rectify the above violations immediately and intimate the compliance position to this office within 45 days from the date of issue of this letter.

भवदीय Yours faithfully,

(पुष्पेन्द्र गौड़) Pushpender Gaur)

क्षेत्रीय खान नियंत्रक / Regional Controller of Mines

प्रतिलिपि सूचनार्थ प्रेषित :-

- 1- खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर। (zo.udaipur@ibm.gov.in)
- 2- निदेशक उद्योग निदेशालय, हि0 प्र0 सरकार, उद्योग भवन, शिमला (हि0 प्र0). (geologicalwing@gmail.com)
- 3- गार्ड फाइल

क्षेत्रीय खान नियंत्रक / Regional Controller of Mines भारतीय खान ब्यूरो / Indian Bureau of Mines