

		SHOW CAUSE NOTICE E-MAIL / REGD A.D.
	भारत सरकार Government of India खान मंत्रालय Ministry of Mines भारतीय खान ब्यूरो Indian Bureau of Mines क्षेत्रीय खान नियंत्रक का कार्यालय Office of the Regional Controller of Mines 100, ओल्ड नेहरू कालोनी, देहरादून (उत्तराखण्ड) 248001 /100 Old Nehru Colony, Dehradun (U.K.)248001 TEL- 0135-2676350 / 2671896, E-mail – ro.dehradun@ibm.gov.in	
फाईल संख्या File No: HP/Mandi/Salt-3 CV-WFH	Mine Code: 51HPR08003	दिनांक, 07 April 2020

सेवा में To : Mines Manager
Hindustan Salt Ltd
Drang Bhatog-175001
District-Mandi (HP)

E-mail: drang.mandi@indiansalt.com

विषय Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Drang Rock Salt Mine over an area of 8.12 ha located near Village Drang, Tehsil- Sadar, District-Mandi of H.P State.

महोदय Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection made by the undersigned on 15.11.2019 in the presence of Shri Dileswar Kar, Mine Manager & communicated to you vide our letter of even number dated on 20-12-2019.

<u>RULE NO.</u>	<u>NATURE OF VIOLATION OBSERVED</u>
11(1)	1. Mining operation were not carried out in accordance with the mining plan approved, vide letter no 614(2)/MP-A-265/15 DDN dated 17.12.2015 to the extent that Geo technical study is to be carried out before commencement of the mining operations whereas mining operations found in operation without geo technical studies .Refer page no 33(Mining Plan). 2. Proposed exploration for precise delineation of the mineralization has not been carried out as proposed at page no 22. 3. Incline D-2 is not developed as per proposal in mining plan.
45(7)	The holder of a mining lease has submitted incomplete or wrong information in annual return 1. Ex Mine Price is not correct, as per sale value of rock salt Ex Mine Price is Rs.9406/- but it is indicated Rs.9500/-, which is wrong.
55	Every holder of mining lease shall employ a geologist in the mine. But geologist has not been appointed in the mine.

2. However, on perusal of your letter No. MND/MINE/IBM-V/2017-2018/1024 dated 05.02.2020, the compliance of rule 45(7) of MCDR, 2017 has been considered. Whereas the reply is not found satisfactory for compliance of rules 11(1), 55 of MCDR, 2017 thus the compliance of violated rules 11(1), 55 was not considered and thus the violation of rules 11(1), 55 of MCDR, 2017 still persists.
3. In this connection, it is brought to your kind notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.
4. Mining operations can be suspended as per rule 11(2) in case of non compliance of rule 11(1) of MCDR, 2017.

5. You are therefore directed to show cause within a period of thirty (30) days from the date of issue of this letter, as to why you should not be prosecuted and / or why mining operation can be suspended under statutory provisions.
6. Please note that no further notice will be given to you in this regard.

भवदीय Yours faithfully,

D P

07.04.2020

(दामोदर प्रसाद शर्मा / D P Sharma)

सहायक खान नियंत्रक / Assistant Controller of Mines

प्रतिलिपि सूचनार्थ प्रेषित :-

- 1- खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुरा (zo.udaipur@ibm.gov.in)
- 2- निदेशक उद्योग निदेशालय, हि0 प्र0 सरकार, उद्योग भवन, शिमला (हि0 प्र0). (geologicalwing@gmail.com)
- 3- गार्ड फाइल

सहायक खान नियंत्रक / Assistant Controller of Mines

भारतीय खान ब्यूरो / Indian Bureau of Mines