

**INDIAN BUREAU OF MINES  
MINERALS DEVELOPMENT AND REGULATION DIVISION**

**MCDR INSPECTION REPORT**

**Nagpur regional office**

**Mine file No :** MAH/BHD/MN-120/NGP

**Mine code :** 40MSH05003

- (i) Name of the Inspecting : **204** ) **SNEHANKIT H. CHATTE**  
Officer and ID No.
- (ii) Designation : Assistant Mining Engineer
- (iii) Accompanying mine : Sh. Nilesh Sawalkar, Manager & shri. M.S. Waghmare, Q  
Official with  
Designation
- (iv) Date of Inspection : 07-Dec-21
- (v) Prev.inspection date : 03-May-12

**PART-I : GENERAL INFORMATION**

1. (a) **Mine Name** : **HIWARA**
- (b) **Registration NO.** :
- (c) Category : B Manual
- (d) Type of Working : Opencast
- (e) Postal address  
State : MAHARASHTRA  
District : BHANDARA  
Village : HIWARA  
Taluka : MOHADI  
Post office : KANDRI (JAM)  
Pin Code :  
FAX No. :  
E-mail :  
Phone :
- (f) Police Station :
- (g) First opening date : 22-Jul-68
- (h) Weekly day of rest : THU
2. Address for : SHRI P. R. LANJEWAR, C/O: LATE R. B. LANJEWAR,  
correspondance VIVEKANAND NAGAR, TAH: TUMSAR- 441912,  
DISST. BHANDARA (M. S.)
3. (a) Lease Number : MSH0120
- (b) Lease area : 12.33
- (c) Period of lease : 20
- (d) Date of Expiry : 18-Nov-91
4. Mineral worked : MANGANESE ORE Main

## 5. Name and Address of the

Lessee : M/S: RAM B. LANJEWAR  
6/3 MIG COLONY, WANJARI  
NAGAR, NAGPUR. NAGPUR  
MAHARASHTRA  
Phone:  
FAX :

Owner : SHRI DUSHYANT LANJEWAR  
NAGPUR MAHARASHTRA  
Phone:  
FAX :

6. Date of approval of Mining	:	Mining Scheme rule 12 MCDR1988	18-Feb-09
Plan/Scheme of Mining	:	Mining Scheme rule 12 MCDR1988	18-Dec-12
	:	MP modif under MCR 1960	01-Apr-15
	:	MP review under 17(1) MCR 2016	01-Apr-20

## PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

## Exploration :

Sl.No.	Item	Proposals	Actual work	Remarks
1a	Backlog of previous year	The Mining Plan was approved on 22.07.2020 for the proposal period year 2020-21 to 2021-22 (up to 18.11.2021) No proposal of bore hole drilling were given year 2020-21, however in the year 2021-22 proposal of 05 nos. of borehole having 141 meter was proposed.	Nil, The Mine was water logged.	The Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, Mine mine was found water logged & the dumps were found stabilized naturally.
1b	Exploration over lease area for geological axis 1 or 2	The area was explored under G2 which is 1.4068 hect. no proposal was given in the year 2020-21	Nil	The Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, Mine mine was found water logged & the dumps were found stabilized naturally.
1c	Exploration Agencies and Expenditure in lakh rupees during the year	Not applicable	Nil	The Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, Mine mine was found water logged & the dumps were found stabilized naturally.

1d	Balance area to be explored to bring Geological axis in 1 or 2	no proposal was given in the year 2020-21 however, 1.3882 hect. area was proposed to be explored. in next year	Nil	The Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, Mine mine was found water logged & the dumps were found stabilized naturally.
1e	Balance reserve as on 01/04/20	as per last approved document under 122 reaserves are furnished as 36646 T	Since no working was carried out from year 2013 given figure seems correct	The Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, Mine mine was found water logged & the dumps were found stabilized naturally.

1f	General remarks of inspecting officers on geology, exploration etc	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged and plants and bushes were found grown on mine site/ dumps.lease was lapsed by State Government of Maharashtra on 31.03.2021 as per section 8A(6) of MMDR Act, 2015, the lessee revived & recieved extended the lease period up to 08.11.2022 by bringing order from Hon'ble High court Bombay, Nagpur Bench. concent to operate yet to be received.
----	--	---

## Development :

Sl.No.	Item	Propasals	Actual work	Remarks
2a	Location of development w.r.t.lease area	Grid Reference E-344862 to E- 345177 & N-2367584 to N-2367694	No development work was carried out by the lessee as the mine was non-working since May 2013, but the pit was found in the said grid which was water logged.	The Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, During inspection Mine mine was found water logged & the dumps were found stabilized naturally.

2b	Separate benches in topsoil, overburden and minerals (Rule 15)	height of Benches in Ore & OB having dimension of H=6m X W= 6m were proposed.	Nil as No development work was carried out by the lessee as the mine was non-working since May 2013, but the pit was found which was water logged.	The Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, During inspection Mine mine was found water logged & the dumps were found stabilized naturally.
2c	Stripping ratio or ore to OB ratio	year 2020-21 = ratio was proposed 1:1.8	Nil as No development work was carried out by the lessee as the mine was non-working since May 2013, but the pit was found which was water logged.	The Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, During inspection Mine mine was found water logged & the dumps were found stabilized naturally.
2d	Quantity of topsoil generation in m3	year 2020-21= 372 m3	Nil as No development work was carried out by the lessee as the mine was non-working since May 2013, but the pit was found which was water logged.	The Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, During inspection Mine mine was found water logged & the dumps were found stabilized naturally.
2e	Quantity of overburden generation in m3	year 2020-21= 24152m3	Nil as No development work was carried out by the lessee as the mine was non-working since May 2013, but the pit was found which was water logged.	The Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, During inspection Mine mine was found water logged & the dumps were found stabilized naturally.

2f	General remarks of inspecting officers on development of pit w.r.t. type of deposit etc	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged and plants and bushes were found grown on mine site/ dumps.lease was lapsed by State Government of Maharashtra on 31.03.2021 as per section 8A(6) of MMDR Act, 2015, the lessee revived & recieved extended the lease period up to 08.11.2022 by bringing order from Hon'ble High court Bombay, Nagpur Bench. consent to operate yet to be received.
----	---	---

#### Exploitation:

Sl.No.	Item	Propasals	Actual work	Remarks
3a	Number of pit proposed for production	02 nos	02 nos of pits are existing in the mine but found water logged as it has been non-working since may 2013	The Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, During inspection Mine mine was found water logged & the dumps were found stabilized naturally.

3b	Quantity of ROM mineral production proposed	year 2020-21= 16177 T	Nil as mine has been non-working since may 2013	The Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, During inspection Mine mine was found water logged & the dumps were found stabilized naturally.
3c	Recovery of sailable/usable mineral from ROM production	year 2020-21= 90% i.e 14559.3 T	Nil as mine has been non-working since may 2013	The Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, During inspection Mine mine was found water logged & the dumps were found stabilized naturally.
3d	Quantity of mineral reject generation	Year 2020-21= 10% of ROM i.e. 1617.7 T	Nil as mine has been non-working since may 2013	The Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, During inspection Mine mine was found water logged & the dumps were found stabilized naturally.



3e	Grade of mineral below 10% Mn rejects generation and threshold value declared.		Nil	The Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, During inspection Mine mine was found water logged & the dumps were found stabilized naturally.
3f	Quantity of sub grade mineral generation.	NO PROPOSAL	NIL	
3g	Grade of sub grade mineral generation	NO PROPOSAL	NIL	
3h	Manual / Mechanised method adopted for segregating from ROM	Manual	Nil, as mine was non-working since May, 2013	The Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, During inspection Mine mine was found water logged & the dumps were found stabilized naturally.
3i	Any analysis or beneficiation study proposed and carried out for sub grade mineral and rejects.	not proposed	nil	The Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, During inspection Mine mine was found water logged & the dumps were found stabilized naturally.

3j	Provision of drilling and blasting in mineral benches	yes given. Drilling by Jack hammer & Wagon Drill Machine	nil,	The Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, During inspection Mine mine was found water logged & the dumps were found stabilized naturally.
3k	Provision of mining machineries in mineral benches	drilling by Jack hammer/ wagon drill=01, tipper truck (16T)=3, Loders=01, Water Pump(10HP)=01	NIL	The Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, During inspection Mine mine was found water logged & the dumps were found stabilized naturally.
3l	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	YES	AS PER PROPOSAL	The Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, During inspection Mine mine was found water logged & the dumps were found stabilized naturally.

3m	Total area covered under excavation/pits	1.4068 HECT	as proposed	The Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, During inspection Mine mine was found water logged & the dumps were found stabilized naturally.
3n	Ore to OB ratio for the pit/mine during the year.	year 2020-21= Ratio 1:1.8	NIL	The Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, During inspection Mine mine was found water logged & the dumps were found stabilized naturally.
3o	Total area put in use under different heads at the end of year	AREA UNDER PIT= 1.4068 HECT WASTE DUMP= 0.4194 HECT ROADS= 0.1755 HECT	AS PROPOSED	The Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, During inspection Mine mine was found water logged & the dumps were found stabilized naturally.

3p	Production of ROM mineral during the last five year period as applicable	The Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, During inspection Mine mine was found water logged & the dumps were found stabilized naturally.	NIL	
3q	General remarks of inspecting officers on method of mining etc.			No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged. Further the lease was lapsed by State Government of Maharashtra on 31.03.2021 as per section 8A(6) of MMDR Act, 2015, the lessee revived & recieved extended the lease period up to 08.11.2022 by bringing order from Hon'ble High court Bombay, Nagpur Bench. consent to operate yet to be received and notice of re-opening not received in this office.

---

Solid Waste Management - Dumping:

---

Sl.No.	Item	Propasals	Actual work	Remarks
4a	Separate dumping of topsoil, OB and mineral rejects (Rule 32,33)	YES PROPOSED	ONE STABALIZED DUMP WAS FOUND DURING INSPECTION	The Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, During inspection Mine mine was found water logged & the dumps were found stabilized naturally.
4b	Location of topsoil, OB and mineral reject dumps	proposals:- top soil= near BP 17, OB Dump= Near BP 14 & Mineral Rejects= between BP 3 & BP4	Nil,	During inspection only on dump was seen which was stabalized as the Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, During inspection Mine mine was found water logged & the dumps were found stabilized naturally.
4c	Number of dumps within lease area and outside of lease area	no. of dumps= 01 (Within Lease area)	as proposed	During inspection only on dump was seen which was stabalized as the Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, During inspection Mine mine was found water logged & the dumps were found stabilized naturally.

4d	Location of dumps w.r.t. ultimate pit limit (Rule 16)	Near BP 14 (E345060-E3450150 TO N2367650 TO N2367720)	AS proposed	During inspection only on dump was seen which was stabilized as the Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, During inspection Mine mine was found water logged & the dumps were found stabilized naturally.
4e	Number of active and alive dumps.	no. of active dump =01	no active dump found in the lease however 01 dump was found during inspection which was stabilized due to non working since may 2013.	During inspection only on dump was seen which was stabilized as the Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, During inspection Mine mine was found water logged & the dumps were found stabilized naturally.
4f	Number of dead dumps.	Nil	01 dump was found during inspection which was stabilized due to non working since may 2013.	During inspection only on dump was seen which was stabilized as the Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, During inspection Mine mine was found water logged & the dumps were found stabilized naturally.

4g	Number of dumps established.	01	01	During inspection only on dump was seen which was stabalized as the Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, During inspection Mine mine was found water logged & the dumps were found stabilized naturally.
4h	Whether Retaining wall or garland drain all along dumps are there.	during year 2020-21, construction of retaining wall was proposed to 350 mtr & no proposal of garland drain was given	Nil as mine was non working since May 2013	During inspection only on dump was seen which was stabalized as the Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, During inspection Mine mine was found water logged & the dumps were found stabilized naturally.

4i	Length of Retaining wall or garland drain all along dumps	length of garland drain=not proposed in year 2020-21	Nil	During inspection only on dump was seen which was stabalized as the Mine was not working since year May 2013, garland drain was also found grown with plants/ bushes and no working was carried out by the lessee in the mine, During inspection Mine mine was found water logged & the dumps were found stabilized naturally.
4j	Number of settling ponds	Not proposed	nil	



4k	Specific comments of inspecting officer on waste dump management	During inspection Mine mine was found water logged & the dumps were found stabilized naturally.	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged. Further the lease was lapsed by State Government of Maharashtra on 31.03.2021 as per section 8A(6) of MMDR Act, 2015, the lessee revived & recieved extended the lease period up to 08.11.2022 by bringing order from Hon'ble High court Bombay, Nagpur Bench. concent to operate yet to be received and notice of re-opening not received in this office.
----	--	---	--

---

Solid Waste Management - Backfilling:

Sl.No.	Item	Propasals	Actual work	Remarks
--------	------	-----------	-------------	---------

---

5a	Status of part or full extraction of mineral from mined out area before starting backfilling.	excavation was NIL proposed in the existing pit during year 2020-21 having area 1.4068 hect	No excavation work was carried out in the lease as the Mine was not working since year May 2013 and no working was carried out by the lessee in the mine, During inspection Mine mine was found water logged & the dumps were found stabilized naturally.
5b	Area under backfilling of mined out area	Not proposed nil	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged & the dumps were found stabilized naturally.
5c	Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)	Not proposed nil	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged & the dumps were found stabilized naturally.

5d	Total area fully reclaimed and rehabilitated	NIL	NIL	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged & the dumps were found stabilized naturally.
5e	General remarks of inspecting officers on backfilling and reclamation etc.			No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged. Further the lease was lapsed by State Government of Maharashtra on 31.03.2021 as per section 8A(6) of MMDR Act, 2015, the lessee revived & recieved extended the lease period up to 08.11.2022 by bringing order from Hon'ble High court Bombay, Nagpur Bench. consent to operate yet to be received and notice of re-opening not received in this office.

---

Progressive Mine Clousre Plan:

---

Sl.No.	Item	Propasals	Actual work	Remarks
--------	------	-----------	-------------	---------

---

6a	Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).	NIL	NIL	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged & the dumps were found stabilized naturally.
6b	Area available for rehabilitation (ha) .	NIL	NIL	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged & the dumps were found stabilized naturally.
6c	afforestation done (ha) .	NOT PROPOSED	NIL	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged & the dumps were found stabilized naturally.
6d	No. of saplings planted during the year	NOT PROPOSED	NIL	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged & the dumps were found stabilized naturally.

6e	Cumulative no .of plants	INFORMATION NOT AVAILABLE	the Mine was not working since year May 2013 During inspection Mine mine it was found that vegetation / bushes ets were found grown at mine site / on dumps. therefore no information can be given	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged & the dumps were found stabilized naturally.
6f	Any other method not proposed of rehabilitation	not proposed	nil	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged & the dumps were found stabilized naturally.
6g	Cost incurred on watch and care during the year	not proposed	nil	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged & the dumps were found stabilized naturally.
6h	Compliance on reclamation and rehabilitation by backfilling (i) Voids available for backfilling ( Lx B x D	not proposed	nil	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged & the dumps were found stabilized naturally.

6i	Compliance on reclamation and rehabilitation by backfilling (ii) Voids filled by waste / tailings	not proposed	nil	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged & the dumps were found stabilized naturally.
6j	Compliance on reclamation and rehabilitation by backfilling (iii) Afforestation on on backfilled area	not proposed	nil	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged & the dumps were found stabilized naturally.
6k	Compliance on reclamation and rehabilitation by backfilling (iv) Rehabilitation by making water reservoir	not proposed	nil	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged & the dumps were found stabilized naturally.
6l	Compliance on reclamation and rehabilitation by backfilling (v) any other specific means.	nil	nil	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged & the dumps were found stabilized naturally.

6m	Compliance of rehabilitation of waste land within lease (i) afforestation	not proposed	nil	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged & the dumps were found stabilized naturally.
6n	Compliance of rehabilitation of waste land within lease (ii) Area rehabilitation (ha)	no proposals	nil	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged & the dumps were found stabilized naturally.
6o	Compliance of rehabilitation of waste land within lease (iii) Method of rehabilitation	not proposed	NIL	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged & the dumps were found stabilized naturally.
6p	Compliance of environmental monitoring (core zone and buffer zone)	PROVISIONS WERE GIVEN IN APPROVED MINING PLAN	NIL	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged & the dumps were found stabilized naturally.

6q	General remarks of inspecting officers on PMCP compliance and progressive closure operations etc.	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged & the dumps were found stabilized naturally.	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged. Further the lease was lapsed by State Government of Maharashtra on 31.03.2021 as per section 8A(6) of MMDR Act, 2015, the lessee revived & recieved extended the lease period up to 08.11.2022 by bringing order from Hon'ble High court Bombay, Nagpur Bench. concent to operate yet to be received and notice of re-opening not received in this office.
----	---	---	--

---

Mineral Conservation:

Sl.No.	Item	Propasals	Actual work	Remarks
7a	ROM Mineral dispatch or grade-wise sorting within lease area	MANUAL	NIL	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged.

---



7b	Method of grade-wise mineral sorting i.e. manual or mechanical.	manual	nil	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged.
7c	Different grade of mineral sorted out at mines.	grade= Av. grade of Mn 44.33% (Manganese ore)	Nil	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged.
7d	Any beneficiation process at mines .	nil	nil	nil

7e	General remarks of inspecting officer on Mineral conservation and beneficiation issues	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged. Further the lease was lapsed by State Government of Maharashtra on 31.03.2021 as per section 8A(6) of MMDR Act, 2015, the lessee revived & recieved extended the lease period up to 08.11.2022 by bringing order from Hon'ble High court Bombay, Nagpur Bench. concent to operate yet to be received and notice of re-opening not received in this office.
----	--	--

Environment:

Sl.No.	Item	Propasals	Actual work	Remarks
8a	Separate removal and utilization of topsoil (Rule 32)	during the year 2020-21 proposal was 372m3 of top soil removal & its utilization for storage	nil	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged.

8b	Concurrent use or storage of topsoil	storage is proposed	nil	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged.
8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	yes proposed	nil	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged.
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	no proposals	nil	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged.
8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	not proposed	nil	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged.
8f	Baseline information on existence of plantation and additional plantation done (Rule 41)	no proposals were given for plantation	nil	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged.

8g	Survival rate not proposed not applicable	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged.
8h	Water sprinkling yes proposed nil on roads to control airborne dust	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged.
8i	General remarks of inspecting officer on aesthetic beauty in and around mines area	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged and plants and bushes were found grown on mine site/ dumps.lease was lapsed by State Government of Maharashtra on 31.03.2021 as per section 8A(6) of MMDR Act, 2015, the lessee revived & recieved extended the lease period up to 08.11.2022 by bringing order from Hon'ble High court Bombay, Nagpur Bench. concent to operate yet to be received.

Sl.No.	Item	Propasals	Actual work	Remarks
9a	Status of submission of Monthly and Annual returns	NOT SUBMITTED	NOT SUBMITTED	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged. Further the lease was lapsed by State Government of Maharashtra on 31.03.2021 as per section 8A(6) of MMDR Act, 2015, the lessee revived & recieved extended the lease period up to 08.11.2022 by bringing order from Hon'ble High court Bombay, Nagpur Bench. concent to operate yet to be received and notice of re-opening not received in this office.

9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	Monthly/ Annual returns has not been filed by the lessee	Monthly/ Annual returns has not been filed. lessee got extension of lease period till 08.11.2022 by Court order after lapsing of lease by State Govt. Maharashtra. in absence of consent to operate & mine was non-working since May 2013, Mining Engineer & Geologist has not been / yet to be appointed by the lessee	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged. Further the lease was lapsed by State Government of Maharashtra on 31.03.2021 as per section 8A(6) of MMDR Act, 2015, the lessee revived & recieved extended the lease period up to 08.11.2022 by bringing order from Hon'ble High court Bombay, Nagpur Bench. concent to operate yet to be received and notice of re-opening not received in this office.
----	---	--	---	--

9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	Monthly/ Annual returns has not been filed by the lessee since May 2013	area under pit/ excavation = 1.4068 hect area under dump= 0.4194 hect roads= 0.1755 hect	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged. Further the lease was lapsed by State Government of Maharashtra on 31.03.2021 as per section 8A(6) of MMDR Act, 2015, the lessee revived & recieved extended the lease period up to 08.11.2022 by bringing order from Hon'ble High court Bombay, Nagpur Bench. concent to operate yet to be received and notice of re-opening not received in this office.
----	---	---	--	--

9d	Scrutiny of Annual return on afforestation	Monthly/ Annual returns has not been filed by the lessee since May 2013	Nil, mine was non-working since may 2013 hence no afforestation / plantation work carried out.	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged. Further the lease was lapsed by State Government of Maharashtra on 31.03.2021 as per section 8A(6) of MMDR Act, 2015, the lessee revived & recieved extended the lease period up to 08.11.2022 by bringing order from Hon'ble High court Bombay, Nagpur Bench. concent to operate yet to be received and notice of re-opening not received in this office.
----	--	---	--	--



9e	Scrutiny of Annual return on mineral reject generation (Grade and quantity)	Monthly/ Annual returns has not been filed by the lessee since May 2013	Nil, mine was non-working since may 2013 hence no afforestation / plantation work carried out.	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged. Further the lease was lapsed by State Government of Maharashtra on 31.03.2021 as per section 8A(6) of MMDR Act, 2015, the lessee revived & recieved extended the lease period up to 08.11.2022 by bringing order from Hon'ble High court Bombay, Nagpur Bench. concent to operate yet to be received and notice of re-opening not received in this office.
----	---	---	--	--

9f	Scrutiny of Annual return on ROM stock and/or graded ore	Monthly/ Annual returns has not been filed by the lessee since May 2013	Nil, mine was non-working since may 2013	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged. Further the lease was lapsed by State Government of Maharashtra on 31.03.2021 as per section 8A(6) of MMDR Act, 2015, the lessee revived & recieved extended the lease period up to 08.11.2022 by bringing order from Hon'ble High court Bombay, Nagpur Bench. concent to operate yet to be received and notice of re-opening not received in this office.
----	--	---	--	--

9g	Scrutiny of Annual return on sale value, Ex. Mine price and production cost	Monthly/ Annual returns has not been filed by the lessee since May 2013	Nil, mine was non-working since may 2013	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged. Further the lease was lapsed by State Government of Maharashtra on 31.03.2021 as per section 8A(6) of MMDR Act, 2015, the lessee revived & recieved extended the lease period up to 08.11.2022 by bringing order from Hon'ble High court Bombay, Nagpur Bench. concent to operate yet to be received and notice of re-opening not received in this office.
----	---	---	--	--

9h	Scrutiny of Annual return on fixed assets	Monthly/ Annual returns has not been filed by the lessee since May 2013	NIL	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged. Further the lease was lapsed by State Government of Maharashtra on 31.03.2021 as per section 8A(6) of MMDR Act, 2015, the lessee revived & recieved extended the lease period up to 08.11.2022 by bringing order from Hon'ble High court Bombay, Nagpur Bench. concent to operate yet to be received and notice of re-opening not received in this office.
----	---	---	-----	--

9k	Scrutiny of Annual return on mining machineries	Monthly/ Annual returns has not been filed by the lessee since May 2013	NIL	No excavation work was carried out in the lease as the Mine was not working since year May 2013 During inspection Mine mine was found water logged. Further the lease was lapsed by State Government of Maharashtra on 31.03.2021 as per section 8A(6) of MMDR Act, 2015, the lessee revived & recieved extended the lease period up to 08.11.2022 by bringing order from Hon'ble High court Bombay, Nagpur Bench. concent to operate yet to be received and notice of re-opening not received in this office.
----	---	---	-----	--

---

**Details of violations observed during current inspection and compliance position of violation pointed out**

Violation observed		Show cause position	
Rule NO.	Issued on Compliance on	Rule NO.	Issued on Compliance on

**Date :**

**(SNEHANKIT H. CHATTE)**

Indian Bureau of Mines