

भारत सरकार /GOVERNMENT OF INDIA खान मंत्रालय/ MINISTRY OF MINES

भारतीय खान ब्यूरो /INDIAN BUREAU OF MINES क्षेत्रीय खान नियंत्रक कार्यालय/ OFFICE OF THE REGIONAL

CONTROLLER OF MINES

फैक्स: (080) 23371027 / 23373287

29, इंडस्ट्रियल सबर्ब II स्टेज,, त्मक्र रोड,

दूरभाष: 080-23371027 / 23375366/67

गोरगुंटापाल्या येशवंतपुर,

 ${\bf Email~ID:~ro.~bangalore@ibm.gov.in.}$

बेंगल्र -560022

सं. KNT/CTD/Mn/113/BNG

दिनांक:28.10.2019

सेवा में

Shri. Bharat K Parikh, Nominated Owner,M/s Bharat Parikh Co. No.703/179,'Sri.Shankarkrupa',4th Main, 5th Block, Anjaneya Layout, Dist: Dayanagere

Dist: Davanagere, Karnataka-577004

विषय/Sub: Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your Hulikatte Manganese Ore Mines (ML-2571) over an area of 32.23 Ha located in Hulikatte village, Sandur taluka, Bellary district of Karnataka State.

महोदय/Sir,

The following provisions of the Mineral Conservation & Development Rules 2017 were found violated in your above mine during the inspection carried out by the undersigned in presence of, Sri.Sharnabasappa -Mining Engineer & Sri.Rajesh Satish Kore -Geologist on 03.10.2019

Rule	Nature of violations observed
11(1)	Modified RMP including PMCP was approved vide letter no.279/131/89/BNG dated 01.08.2017 for a period of 2017-18 to 2019-2020. The deviation observed in mining operation vis-a-vis approved document are given below: Terracing was proposed in the active overburden dump for stabilization, which was not carried out
11(4)	Review & updation of Mining Plan has not been submitted to the competent authority for review at least one hundred and eighty days before the expiry of five years period for which it was approved on the last occasion.
35 (2)	Self assessed report (online) on Star Rating Template along with the soft copy of high resolution satellite images covering the mining lease and an area of two kilometres from the lease boundary has not been submitted.
26(2)	Yearly report on PMCP setting forth the extent of protective and rehabilitative works carried out as per the approved Progressive Mine Closure Plan has not been submitted till date.

- 02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017. Further, the violation of Rule 11(1) may also attract provisions of Rule 11(2) of MCDR, 2017 regarding suspension of mining operations till the compliance of violations.
- 03. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

(अरुण कुमार) उप खान नियंत्रक भारतीय खान ब्यूरो

प्रतिलिपि सूचनार्थ'/Copy for kind information to:

- 1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
- 2. The Director, Department of Mining & Geology, No.49, Khanijabhavan, R.C. Road, Bangalore-560 001

उप खान नियंत्रक भारतीय खान ब्यूरो