



भारत सरकार/**Government of India**  
खान मंत्रालय/**Ministry of Mines**  
भारतीय खान ब्यूरो/**Indian Bureau of Mines**  
हैदराबाद क्षेत्रीय कार्यालय/**Hyderabad Regional Office**



Phone No. : (040)-27539992/2753993

Fax No.(TF): (040)-27539991

E-Mail : ro.hyderabad@ibm.gov.in

F.No. AP/VZNR/MN-24/HYD

603, 6<sup>th</sup> Floor,

CGO Towers, Kavadiguda,  
Secunderabad – 500 080.

Dated: 13/3/2020

To

The Agent(Mines),

Devada Mangaese Mine,

M/s R B S S D & F N Das,

P.O.Shreeram Nagar-535101,

Vizianagaram District,

Andhra Pradesh State.

Sub: Violation of Provisions of MCDR, 2017 in respect of your Devada Manganese ore Mine of M/s RBSSD & FN Das over an extent of 41.054 ha in Devada Village,Vizianagaram district,Andhra Pradesh State - reg

Sir,

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated in your above mine during the inspection on 04.03.2020 by the undersigned accompanied by Sri A.Viswanath Naidu,Mines Manager.

Rule no.	Nature of violation
11(1)	<p>No holder of a mining lease shall <del>commence or</del> carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines <del>or prepared and certified in accordance with the system established by the State Government</del> pursuant to the proviso to clause (b) of sub-section (2) of section 5.</p> <p><b>Mining operations are not being carried out in accordance with the proposals given in the Review of Mining Plan approved vide letter no. AP/VZNR/MP/MN-18/HYD dated 04.01.2016 to the extent indicated below:</b></p> <p><b>“It was proposed to develop benches with 3 meters bench height and 3 meters width.However, during the inspection it was observed that mining is not being carried out with proper benching methods.Several levels of workings are merged into forming high walls which is against the proposal and Systematic &amp; Scientific Mining.”.</b></p>

02 In this connection, it is brought to your notice that the above violations constitute an offence punishable under rule 62 of MCDR, 2017. Inability to comply the provision of Rule 11(1) and 45(7)(a) is liable for suspension of mining operations under rule 11(2) and 45(7)(a) of MCDR, 2017.

03 You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

Yours faithfully,

Shailendra Kumar  
(Regional Controller of Mines)

मूल प्रति पर नही/Not on the Originalप्रतिलिपि निम्न को सादर सूचनार्थ अग्रेषित ।

- (1) खान नियंत्रक(द), भारतीय खान ब्यूरो, बंगलूर को प्रतिलिपि सूचनार्थ अग्रेषित ।
- (2) The Director of Mines and Geology, Government of Andhra Pradesh, Sri Anjaneya Towers, Door No.7-104, B-Block, 5<sup>th</sup> and 6<sup>th</sup> Floors, BTPS Road, PO Ibrahimpatnam-521 456, Vijayawada, Krishna district.
- (3) The Assistant Director of Mines and Geology, Vizianagaram.

Shailendra Kumar  
(Regional Controller of Mines)