

By Email/Post

Government of India Ministry of Mines Indian Bureau of Mines Office of the Regional Controller of Mines, Jabalpur

File No.: MP/Satna/Lst/358 4730 - 4732

Dated: 10/05/2021

Bandhi Ghorwai Limestone Mine RCCPL Private Limited Village -Bharauli, Post - Itahara Tehsil - Maihar, District - Satna Madhya Pradesh – 485773

Sub.: Violation of provisions of Mineral Conservation and Development Rules, 2017, in respect of your Bandhi Ghorwai Limestone Mine, mine code-38MPR35325 over an area of 129.802 Ha, in District Satna of Madhya Pradesh

Sir.

Following provisions of MCDR 2017 were found violated in your above mine during the inspection by the Undersigned on 06.03.2021 in the presence of Shri Deepak Gupta (Mines Manager) and Mines officials.

Rule No	Nature of violation observed in detail
11(1)	No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government.
	 (a) It was proposed to remove 3530 cubic meter of topsoil in the year 2019-20 but only 80 cubic meter of topsoil is achieved. (b) It was proposed to achieve 52950 cubic meter of OB in the year 2019-20 but only 801.68 cubic meter of OB achieved. (c) It was proposed to produce 500.000 metric tonnes of limestone in the year 2019-20 but only 39944.19 metric tonnes of limestone production achieved. Hence the mine development and production were lagging and not as per the proposals of the approved document consistently for last 04 years.
26(2)	The holder of mining lease shall submit to the competent authority a yearly report as per the format specified by the Indian Bureau of Mines, before 1stday of July every year setting forth the extent of protective and rehabilitative works carried out as envisaged in the approved mine closure plan, and if there is any deviation, reasons thereof: During scrutiny of the office records, it has been observed that the yearly report in respect of rule 26(2) of MCDR 2017 has not been submitted for the year 2019-20.
45(7)	Following deficiency was observed in the Annual Returns submitted for the year 2019-20. Part-I (Item No-12 (ii) & 12(iv)): Area covered under current (O/C) workings and area used for waste disposal is furnished incorrectly. Annual return may be suitably revised with corrected figures.

- 1. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservations and Development Rules, 2017.
- 2. The mining operations can be suspended under the rule 11(2) of MCDR-2017, if compliance of rule 11(1) of MCDR-2017 is not found satisfactory.
- 3. You are advised to rectify the violations of abovementioned rules immediately and intimate the position to this office within 45 (Forty-Five) days from the date of issue of this letter.

0/c

Yours faithfully

(Robert Simon C)
Asst. Controller of Mines.
Jabalpur Region, IBM

Copy to:

1) The Controller of Mines (CZ), Nagpur, IBM

2) The Director, Directorate of Geology & Mining, Khanij Bhavan, Arera Hills, Bhopal (MP).

(Robert Simon'C) Asst. Controller of Mines.

Jabalpur Region, IBM