



भारत सरकार/ Government of India खान मंत्रालय / Ministry of Mines भारतीय खान ब्यूरो / Indian Bureau of Mines क्षेत्रीय खान नियंत्रक का कार्यालय / Office of the Regional Controller of Mines



File No: MP/Satna/lst.185

Scheme No.-11, Kamla Nehru Nagar Jabalpur, Dated: 26/04/2021

To,

Shree Vivek Krishan Agnihotri (Nominated Owner) Executive Director-Cement, Prism Cement Limited, Rahejas 2nd Floor, Main Avenue, V.P. Road, Santacruz(W), Mumbai (Maharashtra)-400054

M/S Prism Cement Limited, 'Rajdeep', Rewa Road, Satna, District-Satna (M.P.) - 485 001

Subject: Violation of provisions of provisions of Mineral Conservation & Development Rules, 2017

in respect of your Baghai Limestone Mine of Prism Cement (772.067 Hect.) in Satna district of

Dear Sir.

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mentioned mine during MCDR inspection on 13/02/2021 by the undersigned in presence of Mr.Amit Biswas, Geologist and Mines Manager Mr. Shashi Shekhar Ray.

Rule.						
	Nature of violations observed.					
Rule	1. Mining operations under mining lease.—(1) No holder of a mining lease shall commence or carry out mining plan approved.					
11(1),	operations in accordance mining lease.—(1) No holder of a mining lease shall communicate the state of the sta					
MCDR 2017	operations in any area except in accordance with the mining plan approved, modified or reviewed by the India Bureau of Mines or prepared and certified in accordance with the system established by the State Governme pursuant to the proviso to clause (b) of sub-section (2) of section 5 or approved by the competent authority of the Schedule to the Act where the grade of such atomic minerals is equal to or above the threshold value limit declared under Schedule-A of the Atomic Minerals Concession Rules, 2016. (2) If the mining operations are not carried out in accordance with the approved or certified mining plan or any information contained in the mining plan is found to be incorrect, misleading or non-compliant with applicable and permit continuance of only such operations as are required to restore the conditions in the mine as envisaged under the approved or certified mining plan or modified mining plan, for the purpose of restoration to the extensional possible:					
	possible:	or certified mining plan or mod	lified minin	I to restore the cong plan, for the pur	ditions in the mine as envisaged pose of restoration to the exten	
	possible: During inspection for	or certified mining plan or mod	lified minin	g plan, for the pur	ditions in the mine as envisaged pose of restoration to the exten	
	possible: During inspection for	or certified mining plan or mod the year 2019-20, it is observe the development are very less t	ified minin	g plan, for the pur	ditions in the mine as envisaged pose of restoration to the exten	
	possible: During inspection for 1.The production an	or certified mining plan or mod the year 2019-20 ,it is observe	ified minin	g plan, for the pur	officient in the mine as envisaged pose of restoration to the exten	
	possible: During inspection for	or certified mining plan or mod the year 2019-20 ,it is observe d development are very less t Limestone	ified minin	g plan, for the pur ed. Top Soil	OB (Unit)	
	possible: During inspection for 1.The production an	or certified mining plan or mod the year 2019-20, it is observe the development are very less t	ified minin	g plan, for the pur	officient in the mine as envisaged pose of restoration to the exten	
	possible: During inspection for 1.The production an	the year 2019-20 ,it is observed development are very less to Limestone 3000000T	ified minin	ed. Top Soil	OB (Unit)	
	During inspection for 1. The production an PLANNED ACHIEVED	the year 2019-20, it is observed development are very less to Limestone 3000000T	ified minin	ed. Top Soil 155155M ³	OB (Unit) 747750	
	During inspection for 1. The production an PLANNED ACHIEVED	the year 2019-20 ,it is observed development are very less to Limestone 3000000T	ified minin	ed. Top Soil 155155M ³	OB (Unit) 747750	

	1600N,2800E-3300E & 600N-180N,3200E-3400E)
	3.Backfilling over 2.64-hectare area in NP-1(New pit 1 has not been done.)
	4.Exploration of 37 nos. of bore holes planned as per last plan not done.
Rule 26(2) MCDR 2017	(2) The holder of mining lease shall submit to the competent authority a yearly report as per the format specified by the Indian Bureau of Mines, before 1st day of July every year setting forth the extent of protective and rehabilitative works carried out as envisaged in the approved mine closure plan, and if there is any deviation, reasons thereof:
	1.PMCP report is not given
02.In t	his connection it is brought to your notice that the allege to the second the second the second the second to the second the second to the second that the second the seco

02.In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR-2017.

03 . You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

गपदाय

उप खान नियंत्रक

भारतीय खान ब्यूरो

पता : योजनाकमांक 11, कमलानेहरू नगर, जबलपुर 482002 (भ०प०) / फोन2416780 / 2416589 / 2416231 फैक्स0761- 2416780 Address : Scheme No 11, Kamla Nehru Nagar, Jabalpur 482002 (М.Р) Phone 2416780 / 2416589 241631 Fax : (0761) 2416780 E Mail : <u>ro.jabalpur@ibm.gov.in</u>