



**GOVERNMENT OF INDIA
MINISTRY OF MINES
INDIAN BUREAU OF MINES
OFFICE OF REGIONAL CONTROLLER OF MINES**

**VIOLATION LETTER
SPEED-POST**



FAX : 080- 23371027 / 23373287
Tel : 080-23371027 / 23375366 / 67
Email ID: ro.bangalore@ibm.gov.in
rcombng@rediffmail.com

29, Industrial Suburb, II Stage,
Tumkur Road, Gorguntapalya,
Yeshwantpur,
Bangalore- 560 022.

File no: KNT/GLB/LST-53/BNG

Dated: 27 /11/2018

To,
M/s Kalburgi Cement Pvt. Ltd.
(Formerly Vicat Sagar Cement Pvt. Ltd.)
Chatrasala Village,
Karchikhed post
Chincholi Taluka,
Kalburgi-485320

Subject: Violation of provisions of MCDR 2017 in respect of Kalburgi Cement Kherchikhed Limestone Mine (ML No.2676), M/s Kalburgi Cement Pvt. Ltd., Extent 465.39Ha., located near Kherchikhed Village, Chincholi Taluk, Kalburgi District of Karnataka State.

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during inspection on 25.10.2018 by the undersigned and Shri Rohita Sethi, Asst. Mining Engineer in presence of Shri G. Sudhakar - Mines Manager, K. Nagaraja Rao –Geologist and other mining officials:

Rules	Nature of Violations observed
11(1)	<p>The Mining plan was approved vide letter no. 279/106/2011/BNG dated 08/02/2012. The deviation observed in mining operation vis-a-vis approved document are given below:</p> <ol style="list-style-type: none">The method of Mining of limestone in the area has been proposed in B, category Opencast Manual method of mining, with drilling by jack hammer holes, blasting by conventional explosives, manual loading in to tippers and transport by tippers with capacity 10T, but during site inspection it was observed that the mining operation have been carried out by mechanized method by using HEMM and deep hole drilling and loading and transportation is supported by Shovel and tippers.Location of OB dump has been proposed in between the coordinates E 815 N 550, E 820 N 600, E 905 N 570, E 890 N 620, but during site inspection it was observed that the location of the OB dump is E2026 N 852, E 2087 N 867, E2039 N 941, E 2061 N 945.

02. It is brought to your notice that violation of the above Rule constitutes an offence punishable under Rule 62 of MCDR, 2017.
03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
04. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (Forty Five) days** from the date of issue of this letter.

Yours faithfully,

Sd/-
(Arun Kumar)
Dy. Controller of Mines
Indian Bureau of Mines

Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

Sd/-
Dy. Controller of Mines
Indian Bureau of Mines