



भारत सरकार
GOVERNMENT OF INDIA
खान मंत्रालय
MINISTRY OF MINES
भारतीय खान ब्यूरो
INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय
OFFICE OF REGIONAL CONTROLLER OF MINE



फैक्स: (080) 23371027 / 23373287
दूरभाष: 080-23371027 / 23375366/67
Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,
गोरगुंटापाल्या येशवंतपुर,
बंगलुरु -560022

सं/No.: KNT/BLR/FE/433/BNG

Mine-code: 30KAR03154

दिनांक/Date: 02/08/2019

सेवा में/ To,

Shri Arun Kumar Chirania
Partner
M/s M. Hanumantha Rao
H. No. 37, W. No.17, Ground Floor
Main Road, Near Park
Patel Nagar, Bellary 583 101

विषय/Subject: **Violation of provisions of MCDR 2017 in respect of S.M. Block Iron ore Mine, ML No. 2505 of M/s M. Hanumantha Rao, Extent 40.47 Ha.(as per lease sketch), located near Narayanapur village, Sandur Taluk, Bellary District of Karnataka State.**

महोदय/Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during inspection on 18.07.2019 by undersigned in presence of S/Shri K. Venkata Sreedhar- Mines Manager, M.V. Mahesh-Mining Engineer and other mining officials:

Rules	Nature of Violations observed
11 (1)	As per the approved modified Mining Plan, approved by IBM vide letter no. 279/119/89/BNG dated 21/03/2018, for the period of 2017-18 to 2020-21: Step-wise temporary backfilling with maximum height of 10 m for each terrace was proposed within western pit between section nos. B-B' and C-C'; but during the course of inspection it was found that such backfilling was not suitably terraced and stabilized; at places height of backfilling was found at a range from 20 to 25m.
35 (2)	High resolution satellite images obtained from CARTOSAT-2 satellite LISS-IV sensor on the scale of cadastral map, as on 31 st March for that financial year, covering the mining lease and an area of 2 kilometres from the lease boundary was not submitted to the Regional Controller of Mines, IBM-Bangalore.
45(5)	<u>Part-V:</u> 1. Waste quantity disposed in external dump and in backfilling area are not shown separately in the Annual Return-2018-19. 2. Mineral reject quantity incorrectly mentioned as 317,150 tonnes.

	<p><u>Part-VI:</u> 1.The Ex-mine price for the grade 60% to 62% Lumps was reported as Rs. 2570/- in part VI(3), whereas the sale value for the same grade as reported in Part VI(5) amounts to Rs. 1963/-</p> <p>2. The Ex-mine price for grade 60% to 62% Fines was reported as Rs. 2245/- in Part VI(3), whereas the sale value for the same grade as reported in Part VI(5) amounts to Rs. 1881/-</p> <p>3. As per rule 45(8)(b) of MCDR 2017, Ex-mine price is the total sale value minus the deductions reported in Part-VI (4). In the Annual Return-2018-19, the deduction is reported as zero.</p>
--	--

02. It is brought to your notice that violation of the above Rule constitutes an offence punishable under Rule 62 of MCDR, 2017.
03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
04. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (Forty Five) days** from the date of issue of this letter.

भवदीय/Yours faithfully,
Sd/-

(Krishnendu Chatterjee)
Jr. Mining Geologist
Indian Bureau of Mines

Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

Sd/-
(Krishnendu Chatterjee)
Jr. Mining Geologist
Indian Bureau of Mines