

मेल/त्वरित डाक द्वारा



भारत सरकार /GOVERNMENT OF INDIA

खान मंत्रालय/ MINISTRY OF MINES

भारतीय खान ब्यूरो /INDIAN BUREAU OF MINES

क्षेत्रीय खान नियंत्रक कार्यालय/ OFFICE OF THE REGIONAL  
CONTROLLER OF MINES

फैक्स: (080) 23371027 / 23373287

दूरभाष: 080-23371027 / 23375366/67

Email ID: ro. bangalore@ibm.gov.in.

सं. KNT/GLB/Lst-17/BNG

29, इंडस्ट्रियल सबर्ब II स्टेज,, तुमकुर रोड,

गोरगुंटापाल्या येशवंतपुर,

बेंगलुरु -560022

दिनांक 21.01.2020

सेवा में

Shri Ravindra Lagwankar,  
GM/Agent Mines,  
M/s Vasavadatta Cement,  
Sedam-585222  
Kalaburgai-Dist

विषय/Sub : Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your Injepalli Limestone Mine, (ML No. 2417) over an area of 897.86 Ha located in Injepalli village, Sedam taluka, Kalaburgai district of Karnataka State.

महोदय/Sir,

The following provisions of the Mineral Conservation & Development Rules 2017 were found violated in your above mine during the inspection carried out by the undersigned in presence of, Shri .Shiojee Roy - Mines Manager/Mining Engineer & Sri. Vinayaka- Geologist on 16.12.2019

Rule	Nature of violations observed
11(1)	Modified RMP including PMCP was approved vide letter Vide letter no. 279/168/90/BNG/2342 dated 15/18.12.2017 for a period of 2017-18 to 2021-2022. The deviation observed in mining operation vis-a-vis approved document are given below:  (i)Retaining wall of 378 Mts were proposed in FY 2018-19 where as only 110 Mts. of retaining wall was constructed.  (ii)It was observed that only 51,075 Tons of Shale was handled against the proposal of 4, 98,276 Tons, thereby resulting in (-) 90% deviation.
35(2)	The Online self assessment template of Star Rating has been sent to the Regional Controller of Mines, IBM but high resolution Satellite image obtained from CARTOSAT-2,LISS IV sensor of the previous financial year (2018-19) covering the mining lease and an area of two kilometers from the lease boundary has not been submitted.

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.Further, the violation of Rule 11(1) may also attract

provisions of Rule 11(2) of MCDR, 2017 regarding suspension of mining operations till the compliance of violations.

03. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-

(अरुण कुमार)

उप खान नियंत्रक

भारतीय खान ब्यूरो

प्रतिलिपि सूचनार्थ/Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Department of Mining & Geology, No.49, Khanijabhavan, R.C. Road, Bangalore-560 001

Sd/-

(अरुण कुमार)

उप खान नियंत्रक

भारतीय खान ब्यूरो

11637