

मेल/त्वरित डाक द्वारा



भारत सरकार /GOVERNMENT OF INDIA
खान मंत्रालय/ MINISTRY OF MINES
भारतीय खान ब्यूरो /INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय/ OFFICE OF THE REGIONAL
CONTROLLER OF MINES

फैक्स: (080) 23371027 / 23373287

दूरभाष: 080-23371027 / 23375366/67

Email ID: ro. bangalore@ibm.gov.in.

सं. KNT/GLB/Lst-53/BNG

29, इंडस्ट्रियल सबर्ब II स्टेज,, तुमकुर रोड,

गोरगुंटापाल्या येशवंतपुर,

बेंगलुरु -560022

दिनांक 08.01.2020

सेवा में /To,

Shri Amit Mehta,

Vice president - Agent Mines

M/s Kalburgi Cement Private Limited

Chatrasala Village, Kherchikhed Post,

Chincholi taluq-585320

Kalaburgai-Dist

विषय/Sub : Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your Kalburgi Cement Kherchikhed Limestone Mine, (ML No. 2676) over an area of 465.39 Ha located in Kherchikhed village, Chincholi taluka, Kalaburgi district of Karnataka State.

महोदय/Sir,

The following provisions of the Mineral Conservation & Development Rules 2017 were found violated in your above mine during the inspection carried out by the undersigned in presence of, Shri J Pradeep Kumar - Mines Manager ,Shri. N.Prasanth- Mining Engineer & Sri. K Nagaraja Rao- Geologist on 17.12.2019

Rule	Nature of violations observed
11(1)	RMP including PMCP was approved vide letter Vide letter no. 279/1056/2011/BNG/1154, dtd: 28 th Nov 2018 for a period of 2019-20 to 2023-2024. The deviation observed in mining operation vis-a-vis approved document are given below: During the year 2019-20, only 28,649 Tons was produced against the proposal of 105,040 Tons till the month of Nov.2019, thereby resulting in (-) 73% deviation.
55	In case of category 'A' mines, a whole-time mining engineer shall be employed having minimum five years of professional experience of working in a supervisory capacity in the field of mining, where as the mining engineer employed does not possess the required experience
35(2)	The Online self assessment template of Star Rating has been sent to the

	Regional Controller of Mines, IBM but high resolution Satellite image obtained from CARTOSAT-2,LISS IV sensor of the previous financial year (2018-19) covering the mining lease and an area of two kilometers from the lease boundary has not been submitted.
--	--

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017. Further, the violation of Rule 11(1) may also attract provisions of Rule 11(2) of MCDR, 2017 regarding suspension of mining operations till the compliance of violations.

03. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-
(अरुण कुमार)
उप खान नियंत्रक
भारतीय खान ब्यूरो

प्रतिलिपि सूचनार्थ /Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Department of Mining & Geology, No.49, Khanijabhavan, R.C. Road, Bangalore-560 001

Sd/-
(अरुण कुमार)
उप खान नियंत्रक
भारतीय खान ब्यूरो