

मेल/त्वरित डाक द्वारा



भारत सरकार / GOVERNMENT OF INDIA

खान मंत्रालय/ MINISTRY OF MINES

भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES

क्षेत्रीय खान नियंत्रक कार्यालय/ OFFICE OF THE REGIONAL  
CONTROLLER OF MINES

फैक्स: (080) 23371027 / 23373287

दूरभाष: 080-23371027 / 23375366/67

Email ID: ro. bangalore@ibm.gov.in.

सं. KNT/BLR/Fe/416 /BNG

29, इंडस्ट्रियल सबर्ब II स्टेज,, तुमकुर रोड,

गोरगुंटापाल्या येशवंतपुर,

बेंगलुरु -560022

दिनांक:10.12.2019

सेवा में

Shri. H.G.Rangan goud,  
Mine Owner,  
Door No 15/142,  
Nehru Co-operative colony,  
Hosapete – 583201,  
Ballari Dist,  
Karnataka State.

विषय/Sub : Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your of Thimmappanagudi Iron Ore Mine (ML No. 2549) over an area of 46.20 Ha located in Muraripura village, Sandur taluka, Ballari district of Karnataka State.

महोदय/Sir,

The following provisions of the Mineral Conservation & Development Rules 2017 were found violated in your above mine during the inspection carried out by the undersigned in presence of, Shri .A.Sreekantha Reddy - Mines Manager cum Mining Engineer and Sri. Santhosh Reddy- Mine Geologist on 25.11.2019

Rule	Nature of violations observed
11(1)	Modified RMP including PMCP was approved vide letter no.279/736/2002/BNG/635 dated 17.05.2019 for a period of 2019-20 to 2021-2022. The deviation observed in mining operation vis-a-vis approved document are given below: During the inspection it was observed that about 4000 Tons of ROM was stacked in section DD'(E665120-665132, N1675290-1675313) which was not proposed in the approved document.
19	Heavy earth moving machinery log books duly authenticated by the manager or mining engineer showing date-wise account of hours worked, hours not worked, reasons for non-working, consumption of fuel or energy and lubricants and output of the machine during the corresponding working hours is not maintained regularly.
35(2)	The Online self assessment template of Star Rating has been sent to the

	Regional Controller of Mines, IBM but high resolution Satellite image obtained from CARTOSAT-2,LISS IV sensor of the previous financial year (2018-19) covering the mining lease and an area of two kilometers from the lease boundary has not been submitted.
--	--

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017. Further, the violation of Rule 11(1) may also attract provisions of Rule 11(2) of MCDR, 2017 regarding suspension of mining operations till the compliance of violations.

03. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-  
(अरुण कुमार)  
उप खान नियंत्रक  
भारतीय खान ब्यूरो

प्रतिलिपि सूचनार्थ/Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Department of Mining & Geology, No.49, Khanijabhavan, R.C. Road, Bangalore-560 001

Sd/-  
(अरुण कुमार)  
उप खान नियंत्रक  
भारतीय खान ब्यूरो