

REGISTERED A.D.



GOVERNMENT OF INDIA  
MINISTRY OF MINES  
INDIAN BUREAU OF MINES  
OFFICE OF REGIONAL CONTROLLER OF MINES



FAX : 080- 23371027 / 23373287  
Tel : 080-23371027 / 23375366 / 67  
Email ID: ro.bangalore@ibm.gov.in  
rcombng@rediffmail.com

29, Industrial Suburb, II Stage,  
Tumkur Road, Gorguntapalya,  
Yeshwantpur,  
Bangalore- 560 022.  
Date: 01.06.2015.

NO: KNT/HSN/Cr-3/BNG  
To: Sri V. VENUGOPAL,  
The Executive Director,  
M/s Mysore Minerals Limited,  
A Block, 5<sup>th</sup> Floor, TTMC Building,  
BMTc, Shantinagar,  
BANGALURU- 560 027

Sub: Violation of provisions of MCDR 1988 in respect of your Tagadur Chromite mine, ML 2477(614.99 Ha) in Tagadur village, Channarayapatna taluk, Hassan district, Karnataka state.

Sir,

The following provisions of the Mineral Conservation and Development Rules 1988 were found violated in your above mine during the inspection on 28.05.2015 by Sri K. Srinivas. Asstt. Mining Geologist, accompanied by Sri Chandrasekhar, Geologist.

Rule No.	Violations observed
13(1)	<p>Scheme of mining was approved vide letter no. 279/263/1991/BNG dated 02.04.2014 for the period 2012-13 to 2016-17. The deviations observed in mining operations vis-à-vis approved document are given below.</p> <p>Every holder of mining lease shall carry out mining operations in accordance with the approved mining plan/scheme of mining. The mining operations are not being carried out in accordance with the approved scheme of mining.</p> <p>(i) As per the approved document, drilling of ten exploratory boreholes has been proposed during the year 2014-15, the same has not been carried out.</p> <p>(ii) The annual production envisaged in the approved scheme of mining is 33060 tonnes whereas the actual production reported for the year 2014-15 is 2674 tonnes. The deviation is many folds on negative side.</p>

29	The copies of plans and sections have not been submitted to this office every year as required under this rule.
----	---

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 58 of MCDR 1988. Further, the violation of rule 13(1) may also attract provision of rule 13(2) of MCDR, 1988 regarding suspension of mining operations till the compliance of violations.

03. You are advised to rectify/explain the valid reasons for the above violations immediately and intimate the position to this office within 45 (forty five) days from the date of issue of this letter

Yours faithfully,

Sd/-

( Pukhraj Nenival )  
Dy.Controller of Mines

Copy for information to:

1. The Controller of Mines(SZ), IBM, Bangalore
2. The Director, Department of Mining & Geology, No. 49, Kanijabhavan, R.C .Road, Bangalore – 560 001.

Sd/-

( Pukhraj Nenival )  
Dy.Controller of Mines