



भारत सरकार
खान मंत्रालय
भारतीय खान ब्यूरो,

उल्लंघन पत्र
रजि. ए.डी./स्पीड पोस्ट/ई-मेल/फैक्स

क्षेत्रीय खान नियंत्रक कार्यालय

द्वितीय तल, जी० एस० आई० फील्ड प्रशिक्षण केन्द्र, महालेखाकार कार्यालय परिसर,
पोस्ट-विधानसभा, रायपुर-492005 (छत्तीसगढ़)
फोन एवं फैक्स-0771-2282530, 2285590 ई-मेल: ro.raipur@ibm.gov.in

क्र०- छ०ग० / सरगुजा / बॉक्साईड-2 / रायपुर
प्रति,

दिनांक:-14 / 01 / 2020

श्री अभिजीत पति, सी०ई०ओ०, निदेशक एवं नॉमिनेटेड ओनर,
सर्वश्री भारत एल्युमीनियम कंपनी लिमिटेड,
एल्युमीनियम सदन, कोर-6, तीसरा माला, स्कोप ऑफिस कॉम्प्लेक्स,
7, लोधी रोड, नई दिल्ली- 110003

विषय:- छत्तीसगढ़ राज्य के सरगुजा जिले में स्थित आपकी मैनपाट बॉक्साईड खदान 639.169 हे० में
खनिज संरक्षण एवं विकास नियमावली 2017 के नियमों के उल्लंघन के संबंध में।

महोदय,

आपकी उपरोक्त खान का निरीक्षण अधोहस्ताक्षरी द्वारा दिनांक 21 / 11 / 2019 को श्री अजय
तिवारी, खान प्रबंधक की उपस्थिति में किया गया तथा खान के निरीक्षण के दौरान यह पाया गया कि आपने
खनिज संरक्षण एवं विकास नियमावली 2017 के निम्नलिखित उपबंधों का उल्लंघन किया है :-

नियम	उल्लंघन के प्रकार का विस्तृत ब्यौरा
Rule 11(1)	The following deviations have been found in the mine from the approved Modified Mining Plan vide letter no. SRG/BXT/MPLN-1169/2018/RPR Raipur dated 22/11/2018 for the period of F.Y. 2018-19 to 2020-21: F.Y. 2018-19: Development: In the approved Modified Mining Plan, there was a proposal given for the production and development during the year 2018-19 from the Kudaridih (East) Block in-between Local coordinates N775 to N925 and E1275 to E1328. Whereas, production and development has been done in-between Local coordinates N650 to N1185 and E1265 to E1515. Sapnadar Block (A): In addition to the proposed area, development and production of mineral has been done along lease boundary pillar no. 03 to 05 at 7.5 m barrier zone without proposal and in most of places 7.5m barrier zone has been mined out
Rule 14 (1) & (2)	Laterite with 25% Al ₂ O ₃ reported as Mineral Reject under Part V of Annual returns for F.Y. 2018-19, should be stacked separately as it has been notified as Bauxite under Category of Aluminous Laterite vide Gazette Notification for Threshold value of Mineral through Notification No. C-284/3/CMG/2017, Nagpur dated 25/04/2018 of Ministry of Mines (Indian Bureau of Mines).
Rule 26 (1)	During inspection, it has been found that several quarries within lease area are kept abandoned where the mineral has been mined out earlier and later on, no Protective Measures have been taken around these quarries. Hence, suitable Protective Measures should be taken around all non-working quarries.
Rule 27 (1)	Financial Year 2018-19: It has been found that as per approved Modified Mining Plan, 159.74 Ha. lease area has been considered for calculation of Financial Assurance up to the end of the Plan Period whereas, 803.01 Ha. area has been utilized till the end of F.Y. 2018-19. Financial Assurance in the form of Bank Guarantee for the excess used area has to be submitted to the authorized officer.
Rule 45(7)	Monthly Returns; April 2019 to December 2019: Part II (Production, Dispatches And Stock): 2. Grade-wise production, Despatches, Stocks and Ex-mine prices of Processed ore (Bauxite): 50.927.00 Metric Tonnes of screened ore with 42.15% Al ₂ O ₃ and 8.82% SiO ₂ has not been reported and reflected in this table. Annual Return F.Y. 2018-19: Part V; General Geology & Mining (Sec 1/2 for Bauxite): 4.2 (c): Total quantity of Overburden/Waste removed during the year (tonnes) has not been mentioned. Part VI; (Production, Dispatches And Stock): 2. Grade-wise production, Despatches, Stocks and Ex-mine prices of Processed ore (Bauxite): 50,927.00 Metric Tonnes of screened ore with 42.15% Al ₂ O ₃ and 8.82% SiO ₂ has not been reported and reflected in this table. Part VII; Cost Of Production: Production cost of 19500.00 Metric Tonnes of produced ROM during F.Y. 2018-19 should be computed and reported under Cost of Production.

कृ०पृ०प०.2.

02. इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है एवं इस नियम का उल्लंघन की अनुपालन नहीं होने पर खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 11(2) एवं 45(7) के अंतर्गत:-
- (क) खान की समस्त खनन संक्रियाएं बंद की जा सकती है।
(ख) आपके विरुद्ध अभियोग याचिका दायर किया जा सकता है।
(ग) खनन पट्टे को निरस्त करने की सिफारिश राज्य सरकार से की जा सकती है।
03. अतः आपको सलाह दी जाती है कि आप उपरोक्त उल्लंघनों का अतिशीघ्र सुधार करें एवं इसके सुधार की सूचना इस पत्र के जारी होने से 45 दिन के भीतर इस कार्यालय को सूचित करें।

भवदीय

(शैवाल कार्तिकेय)
कनिष्ठ खनन भूविज्ञानी,
भारतीय खान ब्यूरो, रायपुर

प्रतिलिपि: सूचनार्थ हेतु :-

1. खान नियंत्रक (मध्य), भारतीय खान ब्यूरो, नागपुर (महाराष्ट्र) -440001
2. संचालक, भौमिकी एवं खनिकर्म, छत्तीसगढ़ इंद्रावती भवन, द्वितीय तल, डी ब्लॉक, केपिटल कॉम्प्लेक्स, नया रायपुर, छत्तीसगढ़।
3. उप महानिदेशक (सांख्यिकी), भारतीय खान ब्यूरो, नागपुर (महाराष्ट्र) -440001
4. श्री राजेश मिश्रा, एजेन्ट (माईन्स), सर्वश्री भारत एल्युमीनियम कंपनी लिमिटेड, माईन्स एवं जियोलॉजी ईंजीनिरिंग बिल्डिंग, बाल्को नगर, कोरबा, जिला-कोरबा (छत्तीसगढ़), पिन कोड- 495 684

(शैवाल कार्तिकेय)
कनिष्ठ खनन भूविज्ञानी
भारतीय खान ब्यूरो, रायपुर