

## भारत सरकार/ Government of India खान मंत्रालय / Ministry of Mines भारतीय खान ब्यूरो / Indian Bureau of Mines क्षेत्रीय खान नियंत्रक का कार्यालय / Office of the Regional Controller of Mines



रजिस्टर्ड ए०डी०/ उल्लंघनपत्र

File No.: MP/Satna/OCH-98 UUS3 \_ UUS6 सेवा मे,

Jabalpur, dated: 21/04/2021

M/s Kunjilal Ishwari Prasad Agrawal,

Street/Village: Koldiha No-2, P.O.-Jaitwara, Tahsil- New Ramnagar

District-Satna-485 221

विषय — म0प्र0 राज्य के Satna जिले में स्थित आपकी Barui Ochre, White Clay, Laterite & Bauxite Mine, (क्षेत्रफल= 8.094 हे0) में खनिज संरक्षण एव विकास नियमावली, 2017 के नियमों का उल्लंघन। (Mine Code-32MPR35043)

महोदय,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mentioned mine during the inspection by Shri Sanjay M. Girhe, Regional Mining Geologist on 19.02.2021 in presence of Shri. Ramchandra Agrawal, Lessee's representative as detailed under-:

नियम स.	पाए गए उल्लंघन की विस्तृत प्रकृति
Rule11 (1)	According to this rule-No holder of a mining lease shall commence or carry out mining operation in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Govt. pursuant to the provisions to caluse (b) of Sub Section (2) a Section 5 or approved by the competent authority of the Atomic Minerals Directorate for exploration and Researching respect of minerals specified in Part B of the First Schedule of the Act where the grade of such atomic minerals is equal to or above the threshold value lim declared under schedule-A of the Atomic Mineral Concession Rules 2016
	The Modification of Mining Plan of above mentioned mine was approved vide this office letter No-MP/Satna/Bauxite/MPLN/MOD-06/2020-21 dated 30.09.2020 incorporating the proposals of working from 2020-21 to 2024-25. During the inspection, it was found that following provision of rules have been violated
	i) In Part-A,Para-1(i),Under the future exploration programme, exploration was proposed in following manner
	Year Proposed exploration Exploration carried out
	2020-21 02 Core, 02 DTH Boreholes Nil
	From above table, it is clearly indicates that exploration by drilling core boreholes were no carried out as per approved proposals hence the deviation against the given proposals.
Rule 14(3)	The overburden and waste material obtained during mining operations shall not be allowed to be mixed with the materials as specified in sub-rule(1)
	But, during inspection it is observed that, waste material generated during sorting of yellow ochre & clay from quarry no-3 was being stacked over the top bench of working quarry-3 and this waste material was not stacked separately at earmarked location.
Rule 26(2)	The holder of mining lease shall submit a yearly report as per the format specified before 1 <sup>st</sup> July of every year setting forth the extent of protective and rehabilitative work carried out as envisaged in the approved mine closure plan, and if there is any deviation, reason thereof But, in your case the aforesaid Report in prescribe Form for the year 2019-20 was not submitted to the Regional Controller of Mine, Jabalpur till the date of inspection.
Rule 45(1)	The holder of the mining lease, or any person or company engaged in trading or storage or end use or export of minerals mined in the country, shall cause himself to be registered online with the Indian Bureau of Mines as per application specified in Form-K of the Schedule and the registration number so allotted by the Indian Bureau of Mines shall be used for all purpose of online reporting and correspondence connected therewith  But, it is observed that you have not done online MTS registration in prescribed Form so far till the date inspection & thus violated above provision of rule.

- O2 In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR-2017.
- 03. Non-compliance of the rule 11(1) & of MCDR-2017 may lead to suspension of Mining operations under the provisions of rule 11(2) of MCDR-2017.
- 04. You are therefore advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय.

(संदीप सिंह) उप.खान नियंत्रक भारतीय खान ब्यूरो,

## प्रतिलिपि सूचनार्थ हेतु प्रेषित :

- The Director of Geology & Mining, Govt .of Madhya Pradesh, Khanij Bhavan, 29-A, Arera Hills, Bhopal (M.P.).
- 02. The District Collector, Satna (M.P.).

## प्रतिलिपि प्रेषित:

The Controller of Mines (CZ), IBM, Nagpur for information.

उप.खान नियंत्रक भारतीय खान ब्यूरी

olc

पता : योजनाकमांक 11, कमलानेहरू नगर, जबलपुर482002(म0प्र0)/फोन नं00761-2416589 फैक्स0761-2416780. Address: Scheme No 11, Kamla Nehru Nagar, Jabaipur 482002 (M.P) Phone 0761-2416589 Fax: 0761-2416780 E-Mail:ro.jabalpur@ibm.gov.in