

मेल/त्वरितडाकद्वारा



भारतसरकार /GOVERNMENT OF INDIA
खानमंत्रालय/ MINISTRY OF MINES
भारतीयखानब्यूरो /INDIAN BUREAU OF MINES
क्षेत्रीयखाननियंत्रककार्यालय/ OFFICE OF THE REGIONAL
CONTROLLER OF MINES

फैक्स: (080) 23371027 / 23373287

दूरभाष: 080-23371027 / 23375366/67

Email ID: ro. bangalore@ibm.gov.in.

29, इंडस्ट्रियलसबर्बाIIस्टेज,,तुमकुरोड,

गोरगुंटापाल्यायेशवंतपुर,

बेंगलुरु -560022

सं.KNT/GLB/LST/42/BNG

दिनांक:23.06.2020

सेवामें/To,

Shri. S Sundaram,

Nominated Owner,

M/s Gulbarga Cement Limited,

H No.1-949/12/1,2,3

Sivashakti Layout, Kotanoor-D

Near Ganga Vihar Apartments, Sai Mandir Road,

Kalaburagi -585102

Karnataka

विषय/Sub: Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your Ferozabad Limestone Mine (ML No. 2558) over an area of 765.22 Ha located in Ferozabad,Kirani & Somnathahalli village, Kalaburagi Taluka, Kalaburagi district of Karnataka State

महोदय/Sir,

The following provisions of the Mineral Conservation & Development Rules 2017 were found violated in your above mine during the inspection carried out by the undersigned in presence of Sri V. Shiva Kumar - Manager Mining & Mining Engineer on 28.02.2020

Rule	Nature of violations observed
11(1)	RMP along with PMCP was approved vide letter no.279/738/2002/BNG dated 27.01.2017 for a period of 2017-18 to 2020-2021. The deviation observed in mining operation vis-a-vis approved document are given below: Retaining wall of 500 Mts was proposed all along the toe of the OB dump no. D3. It was observed that no retaining wall had been constructed.
26(1)	It was proposed to carry out afforestation in 0.45 Ha with 675 nos. of saplings in FY 2018-19 as per the approved progressive mine closure plan. No afforestation was carried out
45 (7)	Following deficiency was observed in the Annual Returns submitted for the year 2018-19 As per Part – V, sec 3, the reserves & resources at the end of the year is not furnished.

55(1)	<p>In case of fully mechanised category 'A' mines, every holder of a mining lease shall employ a whole time Geologist with minimum five years of professional experience of working in a supervisory capacity in the field of mining.</p> <p>Geologist is not appointed in the mine.</p>
-------	--

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017. Further, the violation of Rule 11(1) may also attract provisions of Rule 11(2) of MCDR, 2017 regarding suspension of mining operations till the compliance of violations.

03. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-
(अरुणकुमार)
उपखाननियंत्रक
भारतीयखानब्यूरो

प्रतिलिपिसूचनार्थ/Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Department of Mining & Geology, No.49, Khanijabhavan, R.C. Road, Bangalore-560 001

Sd/-
उपखाननियंत्रक
भारतीयखानब्यूरो