

मेल/त्वरितडाकद्वारा



भारतसरकार /GOVERNMENT OF INDIA
खानमंत्रालय/ MINISTRY OF MINES
भारतीयखानब्यूरो /INDIAN BUREAU OF MINES
क्षेत्रीयखाननियंत्रककार्यालय/ OFFICE OF THE REGIONAL
CONTROLLER OF MINES

फैक्स: (080) 23371027 / 23373287

दूरभाष: 080-23371027 / 23375366/67

Email ID: ro. bangalore@ibm.gov.in.

29, इंडस्ट्रियलसबर्बIIस्टेज,,तुमकुरोड,

गोरगुंटापाल्यायेशवंतपुर,

बेंगलुरु -560022

सं.KNT/GLB/LST/18/BNG

दिनांक:18.06.2020

सेवामें/To,

Shri. N Umashankar,

Executive Director,

M/s Sri. Balaji Cement & Power Limited,

(Formerly South India Cement Ltd.)

6-3-668/10/66,Durga Nagar Colony,

Panjagutta,Hyderabad,

Telangana-500082

विषय/Sub: Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your Malkhed Limestone Mine (ML No. 1684) over an area of 64.73 Ha located in Malkhed village, Sedam Taluka, Gulbarga district of Karnataka State

महोदय/Sir,

The following provisions of the Mineral Conservation & Development Rules 2017 were found violated in your above mine during the inspection carried out by the undersigned in presence of Sri K. Ramanjaneya Reddy - Manager Mining, Shri. Abdul Khadir - Mining Engineer & Shri. Ravikanth-Geologist on 27.02.2020

| Rule | Nature of violations observed |
|-------|--|
| 11(1) | <p>Scheme of Mining along with PMCP was approved vide letter no.279/345/92/BNG dated 28.09.2015 for a period of 2015-16 to 2019-2020. The deviation observed in mining operation vis-a-vis approved document are given below:</p> <p>i) Twelve nos. of exploratory boreholes were proposed in 2015-16 to convert G3 to G1 level of exploration, which has not been completed.</p> <p>ii) Against the proposal of 144430 Tons of mineral reject, nil Tons of mineral reject were generated.</p> <p>iii) OB generated was proposed to be dumped along the safety zone of seasonal stream towards the southern side whereas, two OB dumps were made in location N1895349-1895394 to E729930-730100 and, N1894990-1895038 to E729445-729620.</p> |

| | |
|--------|---|
| 26(2) | Yearly report on PMCP setting forth the extent of protective and rehabilitative works carried out as per the approved Progressive Mine Closure Plan has not been submitted. |
| 45 (7) | <p>Following deficiency was observed in the Annual Returns submitted for the year 2018-19</p> <p>(i) As per Part I, Sl No.12, in lease area (surface area) utilization at the end of the year, 8.00 Ha has been shown as covered under opencast working. Other details of the land use pattern have not been furnished.</p> <p>(ii) As per Part – V, sec 5, the details of the mining machineries used in the mine is not furnished</p> |

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017. Further, the violation of Rule 11(1) may also attract provisions of Rule 11(2) of MCDR, 2017 regarding suspension of mining operations till the compliance of violations.

03. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-
(अरुणकुमार)
उपखाननियंत्रक
भारतीयखानब्यूरो

प्रतिलिपिसूचनार्थ/ Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Department of Mining & Geology, No.49, Khanijabhavan, R.C. Road, Bangalore-560 001

Sd/-
उपखाननियंत्रक
भारतीयखानब्यूरो