



भारत सरकार

खान मंत्रालय

भारतीय खान ब्यूरो, क्षेत्रीय कार्यालय रायपुर

दुसरी मंजील, जीएसआई फील्ड प्रशिक्षण केन्द्र

महालेखाकार आफिस कोम्प्लेक्स, पोस्ट-विधान सभा- रायपुर- (छ.ग)-492005

फोन- 0771--2282530/2285590/95 [मेल- ro.raipur.ibm@gmail.com](mailto:ro.raipur.ibm@gmail.com)

No- CHG/RAP/LST-49/NGP

दिनांक -24/6/2019

प्रेषिति- श्री के.सी.झाँवर, नामित मालिक,  
सर्वश्री अल्ट्राटेक सीमेंट लिमिटेड,  
हिरमी सीमेंट वर्क्स,  
पोस्ट-हिरमी, तहसील-सिमगा,  
जिला-बलोदा बाजार(छ.ग.)-493195

विषय- छत्तीसगढ़ राज्य के बलोदा बाजार जिले में स्थित आपकी पारसवानी चूना पत्थर खदान 997.355 हे. में खनिज संरक्षण एवं विकास नियमावली 2017 के नियमों के उलंघन के संबंध में-

महोदय

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated during inspection of the above mine on 06.06.2019 by undersigned accompanied by Shri Anil Kawale, Manager(Mines) & Shri Vijesh Kushwaha, Mining Geologist.

Rule	Nature of Violation observed
11(1)	Mining operations should have been undertaken in accordance with the approved Mining Plan. The Modified Mining Plan was approved vide letter no. बलोदा बाजार / चूप /खयो-1160/2018-रायपुर dated 14.08.2018 and following deviation was observed during inspection 1. The mining operation is proposed in 2 pits North pit and south pit but the work is only done in North pit. 2. The bench height is proposed 8 meter but during mine visit it was observed that mine bench is 12-15 meter in northern boundary of ML. 3. The OB generation proposed from both the pit is 368483 cum but from North pit only OB generation quantity is 445877 cum, .and this shows excavation is extended outside proposed area. 4. Garland drain of 550 mtr along the dump has been proposed in 2018-19 but the same is not observed during mine visit. 5. The top soil and OB dumping is proposed in designated area but still OB and top soil are being dump in other places as well i.e near view point in working pit and North side of ML along lease boundary and Boundary pillars also not erected to demarcate the lease boundary
37(1)	The existing protective measures taken around waste dump are insufficient and it has been found that the waste material was escaping and washing away from the dumps and was contaminating the nearby area and extending outside lease boundary and no retaining wall constructed. A proper protective measure should be taken to prevent the escape of the material from the existing waste dumps.

- 2 इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है। एवम इस नियम का उल्लंघन की अनुपालना नहीं होने पर खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 11(2) के अंतर्गत  
(क) खान की सारी खनन संक्रियाएं बंद की जा सकती हैं।  
(ख) आपके विरुद्ध अभियोग दायर किया जा सकता है।  
(ग) खनन पट्टे को निरस्त करने की सिफारिस राज्य सरकार से की जा सकती है।
- 3 अतः आपको सलाह दी जाती है कि आप उपरोक्त उल्लंघनों का अतिशिघ्र सुधार करें एवम इसके सुधार की सूचना इस पत्र के जारी होने से 45 दिन के भीतर इस कार्यालय को सूचित करें।

भवदीय

(राजेश कुमार दास)

वरिष्ठ सहायक खान नियंत्रक

भारतीय खान ब्यूरो, रायपुर

प्रतिलिपि – for information please

- 1 खान नियंत्रक(मध्य), भारतीय खान ब्यूरो , नागपुर
- 2 संचालक, भौमिकी एवं खनिकर्म, छत्तीसगढ, इंद्रावती भवन, द्वितीय तल, डी ब्लॉक, केपिटल कॉम्प्लेक्स, नया रायपुर, छत्तीसगढ

वरिष्ठ सहायक खान नियंत्रक  
भारतीय खान ब्यूरो, रायपुर