SCRUTINY COMMENTS ON EXAMINATION OF DRAFT Modified MP IN RESPECT OF Dharmapur Iron Ore MINE (ML.NO.2239) SITUATED IN Sandur TALUK OFBellary-DISTTOVER AN OF 43.58 Ha OF M/s Zeenath Transport Company.

1. <u>Para 3.4</u>:---- The violation of rule 37(2) of MCDR 2017 pointed out on 1/5/2018 and their compliance has not been discussed.

Part-A

Geology & Exploration:--

- 2.**Para** 1(c):---As per recent notification of threshold value of minerals dated 25/04/2018, presence of "Hematitic Siliceous ore (+35 % Fe) if any in the mine should be discussed.
- 3. **Para 1(l)** (**Page no 31**):---- Non-mineable of resource (211 and 222) due to public road may be clearly mentioned.

Mining:--

- 4. <u>Para 2(a)</u>:-- The reasons for change in site of working should be properly justify with percentage of low grade and high grade ore production in the mine.
- 5. Para 2(b):--(i)The total of tentative excavation figure for year 2018-19 is not matching at table no 24. The same should be cheeked and corrected. (ii) Change in generation of waste as compared to last approved modified MP has not been discussed.
- 6.**Para 2** (f) (Page no- 43):-- Total of tentative excavation figure during remaining plan period is not matching at table no 31. The same should be cheeked and corrected w.r.t. mining chapter.
- 7. **Para 4** (b):-- The quantity of generation of waste figure during remaining plan period should be checked and corrected.
- 8. Para 7 (a):-- The existing mine office within the mine has not been discussed.
- 9. **Para 8:-**-The details of approval of FMCP submitted under rule 24 of MCDR 2017 have not been discussed with enclosed the copy of approval letter. The proposals of PMCP has been made as per approved FMCP may also be mentioned.

Annexures:

- 10. Enclosed boreholes logs should be signed by Geologist/QP
- 11. Feasibility study report should be signed by the QP.
- 12. Noise monitoring data has not been appended.

Plates:--

- 13. Plans should be enclosed in support of compliance of CCOM circular No- 2/2010.
- 14. Plate No 3(Surface Plan):---The plan should also be signed by the Surveyor.
- 15.A section showing Year-wise built-up of wastes has not been enclosed.
