



भारत सरकार/ GOVERNMENT OF INDIA
खान मंत्रालय/ MINISTRY OF MINES
भारतीय खान ब्यूरो/ INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय/
OFFICE OF REGIONAL CONTROLLER OF MINES



फैक्स: (080) 23371027 / 23373287
दूरभाष: 080-23371027 / 23375366/67
Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब IIस्टेज,, तुमकुर रोड,
गोरगुंटापाल्या येशवंतपुर,
बेंगलुरु -560022

सं/No.:KNT/BLR/Fe-201/BNG

दिनांक/Date: 21/04/2022

सेवामें/To,
Sri Md.Abdul Saleem,
Nominated Owner & DirectorMines,
The Sandur Manganese & Iron Ore Mine,
M/s. The Sandur Manganese & Iron Ores Limited.
'SATYALAYA' No.266,
Ward No.1, Palace Road,
Sandur-583 119, Ballari District.
eps@sandurgroup.com / shridharhegde@sandurgroup.com

विषय/Sub: Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your The Sandur Manganese & Iron Ore Mine(**ML No. 2678**) over an extent of **1860.10** Ha in Deogirivillage, Sandur Taluk, Ballari District, Karnataka state.(**MINE CODE:30KAR03180**)

महोदय/Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection carried out by Shri. H.M.Shivakumar-Assistant Mining Engineer accompanied by Dr. Sudhakara T.L in presence of Sri. Sunil Kumar G.S, Mining Engineer& Sri. Shridhar P. Hegde, Geologist on **04/03/2022**.

Rule	Nature of violations observed
11 (1)	<p>The Mining operations are required to be carried out in accordance with the approved Mining Plan document vide letter no. 279/281/91/BNG-Vol-II dated 02/09/2021, However, during the inspection deviations were observed in mining operation vis-à-vis approved document and are as follows:</p> <p>Workings in KMK East Pit between sections CC'-DD', it is observed that mine benches are not systematically developed andthe height and width of benchesare not maintained as per the proposal.</p>

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017read with MCD(Amendment) Rule, 2021.

-2-

सं/No.:KNT/BLR/Fe-201/BNG

03. The violation of Rule 11(1) may also attract provisions of Rule 11(2) of MCDR, 2017 regarding suspension of mining operations till the compliance of violations.

04. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty-Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-

Dr. Sudhakara T.L
Senior Mining Geologist
भारतीयखानब्यूरो/Indian Bureau of Mines

प्रतिलिपिसूचनार्थ/Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Department of Mining &Geology, No.49, Khanija bhavan, R.C. Road, Bangalore-560 001.

Sd/-

Dr. Sudhakara T.L
Senior Mining Geologist
भारतीयखानब्यूरो/Indian Bureau of Mines