

भारत सरकार/**Government of India**
खान मंत्रालय/**Ministry of Mines**
भारतीय खान ब्यूरो/**Indian Bureau of Mines**
हैदराबाद क्षेत्रीय कार्यालय/**Hyderabad Regional Office**

Phone No. : (040)-27539992/2753993
Fax No.(TF): (040)-27539991
E-Mail : ro.hyderabad@ibm.gov.in

603, 6th Floor,
CGOTowers, Kavadiguda,
Secunderabad – 500 080.

No. AP/NLG/LST-18/HYD

Date: 13.05.2020

To,

Shri K Gautam, Nominated owner and Executive Director
Gundlapally Limestone Mines
M/s NCL Industries Limited
Plot no.140, NCL Enclave
Petbasheerabad
Hyderabad- 500055

Sub: Violation of Provisions of Mineral Conservation and Development Rules,2017 (MCDR, 2017) in respect of your Gundlapalli Limestone Mines over an extent of 130.37 Ha situated in Gundlapalli Village, Mattampalli, Mandal, Suryapet District of Telangana State.

Sir,

The following provisions of Mineral Conservation and Development Rules 2017, were found violated in your above mine during the inspection of the mine on 07.03.2020 by the undersigned in presence of mine officials Shri G S Subba Rao, D.G.M (Mines) and Shri Sridhar M Bhat, Qualified person.

Rule no.	Nature of violation
11(1)	<p><i>No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government pursuant to the proviso to clause (b) of sub-section (2) of section 5</i></p> <p>Mining operations are not being carried out in accordance with the proposals given in approved Modified Mining Plan vide letter no. AP/NLG/MP//LST-11/Hyd dated 31.03.2017 to the extent indicated below:</p> <ol style="list-style-type: none">1. It was approved to carry out working below HFL of 53.34 meters with due permission of Directorate of Mines Safety (DMS) and “protective bund all along the HFL (High Flood Level) contour and water front”. Working has been extended within the HFL zone, which is not as per the approved plan and corrective action has not been taken which jeopardize the Systematic and scientific Mining.2. It was approved to protect the seasonal nala by bund on either side, but the same is not done so far.

	3. Only 12 bore holes were drilled so far against 32 no. of bore holes to be completed by the year 2017-18.
31(4)	<i>The plans and sections required under these rules shall be maintained up to date within three months in case of category 'A' mines as referred to in clause (a) of sub-rule (2) of rule 55.</i> Plans and sections are not being maintained and updated within 3 months and the same are not matching with actual field condition;

02. In this connection, it is brought to your notice that the above violation constitutes an offence punishable under rule 62 of MCDR, 2017, further the mining operations can be suspended under rule 11(2) of MCDR, 2017, if compliance of rules 11(1) is not found satisfactory.

03. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

Yours faithfully,

(IBRAHIM SHARIEF)

Sr. Assistant Controller of Mines

For information and necessary action:

1. The Directorate General of Mines Safety, Zonal office, 7th floor, CGO towers, Kavadiguda, Hyderabad, **for information with regard to HFL (Highest flood level)**
2. The Director of Mines & Geology, Government of Telengana, Hyderabad, for information and necessary action
3. The Assistant Director of Mines & Geology, Government of Telangana, Suryapeta, for information and necessary action.

(IBRAHIM SHARIEF)

Sr. Assistant Controller of Mines
For Regional Controller of Mines

मूल प्रति पर नहीं

1^प खान नियंत्रक(द), भारतीय खान ब्यूरो, बंगलूर को प्रतिलिपि सूचनार्थ अग्रेषित ।

(इब्राहिम शरीफ)
वरिष्ठ सहायक खान नियंत्रक
कृते क्षेत्रीय खान नियंत्रक

VIOLATION LETTER
BY MAIL/ POST

भारत सरकार/**Government of India**

खान मंत्रालय/Ministry of Mines
भारतीय खान ब्यूरो/Indian Bureau of Mines
हैदराबाद क्षेत्रीय कार्यालय/Hyderabad Regional Office

Phone No. : (040)-27539992/2753993
Fax No.(TF): (040)-27539991
E-Mail : ro.hyderabad@ibm.gov.in

603, 6th Floor,
CGOTowers, Kavadiguda,
Secunderabad – 500 080.

No. AP/NLG/LST-18/HYD

Date: 13.05.2020

To,

Shri K Gautam, Nominated owner and Executive Director
Gundlapally Limestone Mines
M/s NCL Industries Limited
Plot no.140, NCL Enclave
Petbasheerabad
Hyderabad- 500055

Sub: Violation of Provisions of Mineral Conservation and Development Rules,2017 (MCDR, 2017) in respect of your Gundlapalli Limestone Mines over an extent of 130.37 Ha situated in Gundlapalli Village, Mattampalli, Mandal, Suryapet District of Telangana State.

Sir,

The following provisions of Mineral Conservation and Development Rules 2017, were found violated in your above mine during the inspection of the mine on 07.03.2020 by the undersigned in presence of mine officials Shri G S Subba Rao, D.G.M (Mines) and Shri Sridhar M Bhat, Qualified person.

Rule no.	Nature of violation
11(1)	<p><i>No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government pursuant to the proviso to clause (b) of sub-section (2) of section 5</i></p> <p>Mining operations are not being carried out in accordance with the proposals given in approved Modified Mining Plan vide letter no. AP/NLG/MP//LST-11/Hyd dated 31.03.2017 to the extent indicated below:</p> <p>4. It was approved to carry out working below HFL of 53.34 meters with due permission of Directorate of Mines Safety (DMS) and “protective bund all along the HFL (Highest Flood Level) contour and water front”.</p> <p>During the inspection it was observed that mining operations are being carried out up to 42.12 meters in Pit-1 and 40.175 meters in Pit-2 without obtaining permission from DMS and without constructing “protective bund all along HFL contour”, which is not in the interest of systematic and safe mining.</p> <p>5. It was approved to protect the seasonal nala by bund on either side, but the same is not done so far.</p>

	6. Only 12 bore holes were drilled so far against 32 no. of bore holes to be completed by the year 2017-18.
31(4)	<i>The plans and sections required under these rules shall be maintained up to date within three months in case of category 'A' mines as referred to in clause (a) of sub-rule (2) of rule 55.</i> Plans and sections are not being maintained and updated within 3 months and the same are not matching with actual field condition;

04. In this connection, it is brought to your notice that the above violation constitutes an offence punishable under rule 62 of MCDR, 2017, further the mining operations can be suspended under rule 11(2) of MCDR, 2017, if compliance of rules 11(1) is not found satisfactory.

05. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

Yours faithfully,

(IBRAHIM SHARIEF)

Sr. Assistant Controller of Mines

For information and necessary action:

4. The Directorate General of Mines Safety, Zonal office, 7th floor, CGO towers, Kavadiguda, Hyderabad, **for information with regard to HFL (Highest flood level)**
5. The Director of Mines & Geology, Government of Telangana, Hyderabad, for information and necessary action
6. The Assistant Director of Mines & Geology, Government of Telangana, Suryapeta, for information and necessary action.

(IBRAHIM SHARIEF)

Sr. Assistant Controller of Mines
For Regional Controller of Mines

मूल प्रति पर नहीं

2^ण खान नियंत्रक(द), भारतीय खान ब्यूरो, बंगलूर को प्रतिलिपि सूचनार्थ अग्रेषित ।

(इब्राहिम शरीफ)
वरिष्ठ सहायक खान नियंत्रक
कृते क्षेत्रीय खान नियंत्रक

Rule no.	Nature of violation
11(1)	<i>No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in</i>

	<p>accordance with the system established by the State Government pursuant to the proviso to clause (b) of sub-section (2) of section 5</p> <p>Mining operations are not being carried out in accordance with the proposals given in approved Modified Mining Plan vide letter no. AP/NLG/MP//LST-11/Hyd dated 31.03.2017 to the extent indicated below:</p> <ol style="list-style-type: none"> 1. Due to the Pulichintla project on Krishna River, HFL (High Flood Level) in the region is 53.34 meters above MSL which bay in to lease area below HFL on North-western and Southern side, covering an area of about 42.318 Ha. In this regard commitment was made to obtain permission from Directorate of Mines Safety (DMS) and to construct “protective bund all along the HFL (Highest Flood Level) contour and water front” to carry out mining operations. <p>Working has been extended within the HFL zone, which is not as per the approved plan and corrective action has not been taken which jeopardize the Systematic and scientific Mining. Also bund on either side of nala has not been constructed.</p> <ol style="list-style-type: none"> 2. It was approved to construct ‘Bund’ on either side of the seasonal nala to protect it, but the same is not done. 3. Only 12 bore holes were drilled so far against 32 no. of bore holes to be completed by the year 2017-18.
31(4)	<p><i>The plans and sections required under these rules shall be maintained up to date within three months in case of category ‘A’ mines as referred to in clause (a) of sub-rule (2) of rule 55.</i></p> <p>Plans and sections are not being maintained and updated within 3 months and the same are not matching with actual field condition;</p>