



भारत सरकार
खान मंत्रालय
भारतीय खान ब्यूरो,
क्षेत्रीय खान नियंत्रक कार्यालय
द्वितीय तल, जी० एस० आई० फील्ड प्रशिक्षण केन्द्र, महालेखाकार कार्यालय परिसर,
पोस्ट-विधानसभा, रायपुर-492005 (छत्तीसगढ़)
फोन एवं फैक्स-0771-2282530, 2285590 ई-मेल: ro.raipur.ibm@gmail.com



क्र०- छग०/दुर्ग/चूप.-23/रायपुर

खान कोड: 38 छ.ग. 01016

दिनांक :-12.07.2017

प्रति,

मेसर्स विमल स्टोन एसोसिएट्स, पट्टेदार
वास्ते श्री विमल कुमार लूनिया,
सेमी अर्बन इन्डस्ट्रियल एरिया फ्रेजरपुर,
पोस्ट- जगदलपुर,
जिला- बस्तर (छ.ग.)-494001

विषय:- छत्तीसगढ़ राज्य के बस्तर जिले में स्थित आपकी मोंगरापाल चूनापत्थर खदान 15.94 हे० में खनिज संरक्षण एवं विकास नियमावली 2017 के नियमों के उल्लंघन के संबंध में।

महोदय,

आपकी उपरोक्त खान का निरीक्षण दिनांक 29.06.2017 को अधोहस्ताक्षरी द्वारा श्री मोहित लूनिया, खान मालिक प्रतिनिधि की उपस्थिति में किया गया तथा खान के निरीक्षण में पाया कि आपने खनिज संरक्षण एवं विकास नियमावली 2017 के निम्नलिखित उपबंधों का उल्लंघन किया है।

नियम	उल्लंघन के प्रकार का विस्तृत ब्यौरा
Rule 11 (1)	The following deviations have been found in the mine from approved Scheme of Mining Plan vide letter no. BST/LST/MPLN-941/NGP/2-Raipur Dated 17/08/2016 for the period of 2016-17 to 2020-21: Boundary Pillars: It has been found that all the pillars does not have their serial/identification numbers. Boundary Pillars are not been constructed and maintained as per specification mentioned in MCR, 2016. Borehole: For the year 2016-17, it has been proposed to carry out 05 nos. of borehole up to a cumulative depth of 150m; none of the boreholes have been drilled. Development: (i) There was a proposal given for development from the central part of the existing quarry up to western side of the quarry along with the construction of 2 nos. of benches, whereas development has been observed irregularly all over the quarry without construction of any benches. (ii) There was no such proposal given for making big cubicle size blocks of the limestone from the quarry using wire cutting machine, whereas same is in practice in the mine. Waste Dump: (i) There was a proposal given for waste dumping at south-eastern part of the lease area whereas dumping has been observed in the north-western side of the lease area. (ii) There was a proposal given for construction of garland drain for the protection of dump, whereas no garland drain has been constructed around the dump. Afforestation: There was a proposal given for plantation of 500 nos. of plants during 2016-17, whereas none of the plants have been planted.
Rule 19 (1), (2) & (3)	Log book of heavy earth moving machinery used in the mines is not been maintained and made available during inspection.
Rule 26 (2)	A yearly report as per the format specified by the Indian Bureau of Mines, before 1st day of July every year setting forth the extent of protective and rehabilitative works carried out has not been submitted for the year 2015-16 and 2016-17.
Rule 27 (2)	An amount equal to the difference between the financial assurance due has not been submitted within ninety days from the date of notification.
Rule 33	Updated print copy of the surface geological plan and sections has not been submitted before 30th day of June for the year 2015-16 and 2016-17.
Rule 35	Online self assessment report of mining and allied activities as per the notified template of star rating in the format prescribed by the Indian Bureau of Mines before 1st day of July for the year 2016-17 has not been submitted.

Continue...2..

Rule 45	Annual Returns of 2016-17 has been scrutinized and it has been found that several information has not been furnished and incorporated in the return, such as Part-I; 2.0 Location of Mine, Part V; 4.0 Mining operations during the year (e.g. Total quantity of overburden/waste removed during the year) etc. Since the lease is Non-Captive hence the Captive consumption of 7.625 metric tonnes of ore is needed to be justified as industrial use. Grade of Mineral reject 50% CaO may be incorrect.
Rule 54	Labour attendance register, production register, contribution of DMF & NEMT have not been maintained.
Rule 55	Whole-time Mining Engineer and a Geologist are not been appointed.

02. इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है एवं इस नियम का उल्लंघन की अनुपालन नहीं होने पर खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 11(2) एवं 45(7)(क) के अंतर्गत
- (क) खान की समस्त खनन संक्रियाएं बंद की जा सकती है।
(ख) आपके विरुद्ध अभियोग याचिका दायर किया जा सकता है।
(ग) खनन पट्टे को निरस्त करने की सिफारिश राज्य सरकार से की जा सकती है।
03. अतः आपको सलाह दी जाती है कि आप उपरोक्त उल्लंघनों का अतिशीघ्र सुधार करें एवं इसके सुधार की सूचना इस पर के पारी होने से 45 दिन के भीतर इस कार्यालय को सूचित करें।

भवदीय

(शैवाल कार्तिकेय)
कनिष्ठ खनन भूविज्ञानी,
भारतीय खान ब्यूरो, रायपुर

प्रतिलिपि: सूचनार्थ हेतु :-

1. खान नियंत्रक (मध्य), भारतीय खान ब्यूरो, नागपुर-440001
2. संचालक, भौमिकी एवं खनिकर्म, छत्तीसगढ़ इंद्रावती भवन, द्वितीय तल, डी ब्लॉक, केपिटल कॉम्प्लेक्स, नया रायपुर, छत्तीसगढ़।

(शैवाल कार्तिकेय)
कनिष्ठ खनन भूविज्ञानी,
भारतीय खान ब्यूरो, रायपुर