



भारत सरकार
खान मंत्रालय
भारतीय खान ब्यूरो,
क्षेत्रीय खान नियंत्रक कार्यालय
द्वितीय तल, जी० एस० आई० फील्ड प्रशिक्षण केन्द्र, महालेखाकार कार्यालय परिसर,
पोस्ट-विधानसभा, रायपुर-492005 (छत्तीसगढ़)
फोन एवं फैक्स-0771-2282530, 2285590 ई-मेल: ro.raipur@ibm.gov.in



क्र०- छग०/बलराम०/बॉक्साइड/रायपुर/०7एमपीआर42005

दिनांक :- 21.08.2017

प्रति,

श्री के० एन० भंडारी,
नॉमिनेटेड ऑनर,
आदित्य बिड़ला सेंटर, के० अहीरा मार्ग,
वर्ली, मुम्बई (महाराष्ट्र)- 400030
फोन: 022 66525000

विषय:- छत्तीसगढ़ राज्य के बलरामपुर-रामानुजगंज जिले में स्थित आपकी सामरी बॉक्साइड खदान क्षेत्रफल 2146.746 हे० में खनिज संरक्षण एवं विकास नियमावली 2017 के नियमों के उल्लंघन के संबंध में।

महोदय,

आपकी आपकी उपरोक्त खान का निरीक्षण दिनांक 02.08.2017 को अधोहस्ताक्षरी द्वारा श्री अमित तिवारी, खान प्रबंधक की उपस्थिति में किया गया तथा खान के निरीक्षण के दौरान यह पाया गया कि आपने खनिज संरक्षण एवं विकास नियमावली 2017 के निम्नलिखित उपबंधों का उल्लंघन किया है:-

नियम	उल्लंघन के प्रकार का विस्तृत ब्यौरा
Rule 11(1)	<p>The following deviations have been found in the mine from the approved Scheme of Mining vide SRG/BX/MPLN-385/NGP dated 18/08/2015 for the period of 2014-15 to 2018-19:</p> <p>Boundary Pillars: Boundary Pillars are not been constructed and maintained as per specification mentioned in MCR, 2016.</p> <p>Development: (i) In the approved Scheme of Mining, there was a proposal given for production of Mineral in the year 2016-17 from Quarry No. R3-1 & R3-2 in between N48500-49000 & E48000-48500, D-3 in between N51500-52500 & E 47500-48000, DH3 in between N53000-54000 & E46000-47000, A3 in between N49000-49500 & E48500-49000, G3 in between N46500-47500 & E46500-47000, whereas the production and development have been carried out from different locations ranging between N53000-54000 & E46000-46500 (Plot no. 499, 507 & 516), N52500-N53000 & E47000-47500 (Plot no. 1441), N51500-52000 & E47500-48000 (existing quarry extended towards southern direction; Plot no. 1464), N48500-49500 & E47000-48000 (Plot no. 376 & 372) and N48000-48500 & E46500-47000 (Plot no. 311/3).</p> <p>(ii) In the approved Modified Mining Plan, there was a proposal given for production of Mineral in the year 2017-18 from Quarry No. R4-1 in between N47000-48000 & E48500-49000, R4-2 in between N46500-47500 & E48500-49000, D4 in between N50000-51000 & E48000-48500, DH4 in between N53000-53500 & E46500-47000, A4 in between N49000-49500 & E48500-49000 and G4 in between N46500-47000 & E46500-47000 of the lease area whereas, presently production and development is being carried out from different locations ranging between N47000-47500 & E48000-48500, N53500-54000 & E46000-46500 and in between N52500-53500 & E46500-47500.</p>
Rule 23	As the mining activities has not been carried out as per proposal, therefore the year wise proposal given on protective measures for reclamation and rehabilitation works does not match with the actual achievement.
Rule 27	As the mining activities have not been carried out as per proposal therefore the details of land use pattern given in the proposal does not match with the actual achievement and development.
Rule 33	Updated print copy of the surface geological plan and sections has not been submitted before 30th day of June for the year 2016-17.
Rule 35	Soft copy of the high resolution satellite image obtained from CARTOSAT-2 satellite LISS-IV sensor on the scale of cadastral map, as on the 31st day of March for the Financial year 2016-17, covering the mining lease and an area of two kilometres have not been submitted.

नियम	उल्लंघन के प्रकार का विस्तृत ब्यौरा
Rule 44	The local plant species in the region are Teak (<i>Tectona grandis</i>), Sal (<i>Shorea robusta</i>), Bija (<i>Pterocarpus marsupium</i>), Saja (<i>Terminalia tomentosa</i>), Dhawarda (<i>Anogeissus latifolia</i>), Bamboo (<i>Dendrocalamus strictus</i>), Tendu (<i>Diospyrus melanoxylon</i>), Mahua (<i>Madhuka indica</i>) and Ambla (<i>Embilica officinalis</i>) etc. whereas, it has been observed that most of plants that have been planted in the backfilled area is acacia (80-90%). The over plantation of acacia plants may change the bio-diversity & may effect the local climate of the region.
Rule 47	Notice of shaft sinking and boreholes within fifteen days after the commencement has not been sent to the Regional Controller of Mines, Raipur.
Rule 48	Core samples of 166 nos. of boreholes, drilled during the year 2016-17 have not been preserved. Further it has been observed that out of 166 nos. of bore holes, 38 nos. of bore holes have been drilled during 2015-16 and same achievement has been considered in 2016-17.

02. इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है एवं इस नियम का उल्लंघन की अनुपालन नहीं होने पर खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 11(2) के अंतर्गत
(क) खान की समस्त खनन संक्रियाएं बंद की जा सकती है।
(ख) आपके विरुद्ध अभियोग याचिका दायर किया जा सकता है।
(ग) खनन पट्टे को निरस्त करने की सिफारिश राज्य सरकार से की जा सकती है।
03. अतः आपको सलाह दी जाती है कि आप उपरोक्त उल्लंघनों का अतिशीघ्र सुधार करें एवं इसके सुधार की सूचना इस पत्र के जारी होने से 45 दिन के भीतर इस कार्यालय को सूचित करें।

भवदीय

(शैवाल कार्तिकेय)
कनिष्ठ खनन भूविज्ञानी,
भारतीय खान ब्यूरो, रायपुर

प्रतिलिपि: सूचनार्थ एवं आवश्यक कार्यवाही हेतु :-

1. खान नियंत्रक (मध्य), भारतीय खान ब्यूरो, नागपुर-440001
2. संचालक, भौमिकी एवं खनिकर्म, छत्तीसगढ़ इंद्रावती भवन, द्वितीय तल, डी ब्लॉक, केपिटल कॉम्प्लेक्स, नया रायपुर, छत्तीसगढ़।
3. श्री एम0 के0 नायक, खान ऐजेंट, हिन्डाल्को इण्डस्ट्रीज लि0, कुसमी तहसील -कुसमी, जिला बलरामपुर - रामानुजगंज (छ.ग.). 497224

(शैवाल कार्तिकेय)
कनिष्ठ खनन भूविज्ञानी,
भारतीय खान ब्यूरो, रायपुर