



भारत सरकार GOVERNMENT OF INDIA

खान मंत्रालय MINISTRY OF MINES

भारतीय खान ब्यूरो INDIAN BUREAU OF MINES

क्षेत्रीय खान नियंत्रक के कार्यालय OFFICE OF THE REGIONAL CONTROLLER OF MINES, GOA

Fatorda, Margao, Goa – 403 602

**VIOLATION LETTER**  
**REGD WITH A/D/SPEED POST**

File No.- KNT/BJP/LST-64/GOA

Mine Code: 38KAR26047

Date: 07.06.2019

To,  
Shri C.G. Raikar, Lessee  
Lokapur Limestone Mine (ML No. 2390),  
C/o Vijay Laxmi jewelers,  
Vallabhai Chowk, Bagalkot,  
Bagalkot Dist., Karnataka-587 101

**Sub: Violation of provisions of Mineral Conservation and Development Rules, 2017 (MCDR,2017) in respect of your Lokapur Limestone Mine (ML No. 2390), over an area of 4.86 Ha. in Tq- Mudhol, Bagalkot Dist. of Karnataka state.**

Sir,

The following provisions of Mineral Conservation and Development Rules'2017 were found violated in your above said mine during inspection on 24.05.2019 by the undersigned in the presence of Mr. B. Prabhakar Reddy, Mines Manager and other officials of your mine.

Rule No.	Nature of Violation observed
11 (1)	<p>The Mining operations required to be carried out in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines. However, Mining operations have not been carried out in accordance with the Modification of Mining Plan (MMP) approved dated:- 31.01.2018 to the extent indicated below:-</p> <p>(i) As per approved MMP, in year 2018-19 &amp; 2019-20 the waste dump proposed to be made at earmarked place in north western side of the lease near to ML boundary pillar BP-4. However, it was observed during inspection that waste dump has not been made at the earmarked place; instead it was made near to ML boundary pillar BP-3.</p> <p>(ii) As per approved MMP, in year 2018-19 a bund of 115 m length, 7.5 m width &amp; 2 m height proposed to be made at earmarked place in north western side of the lease near to ML boundary pillar BP-4 along the 7.5 m safety barrier in two sides of proposed waste dump. However, the same has not been made at the earmarked place.</p>
35 (2)	<p>High resolution satellite image as on 31<sup>st</sup> March for that financial year covering the mining lease and area of two km from the lease boundary, ought to be submitted before the 1st day of July each year for the preceding financial year to the Regional controller, has not been submitted so far for the year 2017-18. Violation in this respect was also issued previously by this office, however the same has not been complied so far.</p>

- 
02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR, 2017.
03. *The mining operations can be suspended under Rule 11 (2), if compliance of Rule 11 (1) is not found satisfactory.*
04. You are advised to rectify the above violations **immediately** and intimate the position to this office **within 45 (forty-five) days** from the date of issue of this letter.

Yours faithfully,

(P. PRAKASH)  
Dy. Controller of Mines

Not on Original

Copy to: -

- (1) The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
- (2) The Director, Directorate of Mines & Geology, Government of Karnataka, 49, Khanij Bhawan, Race Course Road, Bengaluru.

(P. PRAKASH)  
Dy. Controller of Mines  
For Regional Controller of Mines